


ECO INSPECTION REPORT Basic

Order ID : 18052

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered by : _____ | Inspection Date : 16/01/2018


5/10



Overall Score

- ✔ Evaluated across 6 segments
- ✔ 2 owners , 2 Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ **Verified Technician**










167+ vehicle inspected
2+ years experience

Ajay Srinivas Raghavan













Bajaj Discover 100cc, 2016



VEHICLE INFORMATION			
MAKE	BAJAJ	REGISTRATION NO	HR26AE4522
MODEL	DISCOVER	VIN/CHASIS NUMBER	13443
YEAR	2016	KMS RUN	2580
TRIM	100CC	INSURANCE EXPIRY	2018-1-18
COLOR	RED	LOCATION	GURGAON
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	2,580	 RC COPY AVAILABLE	NO	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO

ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

ECO SCORE	ECO COMMENTS
 Tire 8 / 10	 Tire <u>Good</u>
 Control 4 / 10	 Control <u>Service Required</u>
 Light 6 / 10	 Light <u>New Headlight</u>
 Oil 7 / 10	 Oil <u>Fine</u>
 Chassis 2 / 10	 Chassis <u>Damaged</u>
 Stand 6 / 10	 Stand <u>New Stand</u>

 **DESCRIPTION**

Sample Report

Ordered by: | Inspected date: 16/01/2018


Order Id: 18052

Overall Score



5/10

 IMAGES



SAMPLE

Ordered by: | Inspected date: 16/01/2018

Order Id: 18052

Overall Score  **5/10**

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE