

# ECO INSPECTION REPORT Basic

Order ID : 18059

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered by : \_\_\_\_\_ | Inspection Date : 16/01/2018

**7/10**


**Overall Score**

- ✓ Evaluated across 5 segments
- ✓ 4 owners , 3 Years Vehicle Age
- ✓ No Accidental History

Inspected By

 **Verified Technician**

167+ vehicle inspected  
2+ years experience



Ajay Srinivas Raghavan
















## Ashok Leyland Stile LE 8 SEATER, 2015



VEHICLE INFORMATION			
MAKE	ASHOK LEYLAND	TRANSMISSION TYPE	AUTOMATIC
MODEL	STILE	REGISTRATION NO	HGR5678
YEAR	2015	VIN/CHASIS NUMBER	6788
TRIM	LE 8 SEATER	KMS RUN	30000
COLOR	SILVER	INSURANCE EXPIRY	2018-1-18
BODY TYPE	COMPACT SUV	LOCATION	GURGAON
FUEL TYPE	HYBRID	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	56	 RC COPY AVAILABLE	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	NO
		 BANK NOC	NO

### ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

ECO SCORE		ECO COMMENTS	
 Interior	 5 / 10	 Interior	Average
 Wheel	 8 / 10	 Wheel	Fine
 Test	 8 / 10	 Test	Perfect Condition
 Exterior	 8 / 10	 Exterior	Good
 Hood	 6 / 10	 Hood	Painted

### DESCRIPTION

sample report

Ordered by: | Inspected date: 16/01/2018

Order Id: 18059

Overall Score



7/10

 IMAGES



Ordered by: | Inspected date: 16/01/2018

Order Id: 18059

Overall Score  **7/10**

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE