

ECO INSPECTION REPORT

Premium

Order ID : 10317

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered by : POONAM RANI | Inspection Date : 25/04/2017

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 104 does not need attention
- ✓ 2 owners , 6 Years Vehicle Age
- ✓ 1 Accidental History Reported

Inspected By




✓ **Verified Technician**

76+ vehicle inspected
1+ years experience

Abhishek Jain










Maruti Suzuki Eeco 5 STR WITH AC PLUSHTR, 2011




VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	EECO	REGISTRATION NO	DL3CBU2790
YEAR	2011	VIN/CHASIS NUMBER	MA3ERLF1S00219799
TRIM	5 STR WITH AC PLUSHTR	KMS RUN	66837
COLOR	SILVER	INSURANCE EXPIRY	2017-2-11
BODY TYPE	MUV	LOCATION	SHAHDARA
FUEL TYPE	CNG	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS


 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	YES	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	25,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Value for this vehicle comes to be:






1,65,598




Good Condition

ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT


ECO SCORE

 Interior	<div style="width: 75%; background-color: yellow; height: 10px;"></div>	6 / 10
 Wheel	<div style="width: 75%; background-color: yellow; height: 10px;"></div>	6 / 10
 Test	<div style="width: 75%; background-color: yellow; height: 10px;"></div>	6 / 10
 Exterior	<div style="width: 75%; background-color: yellow; height: 10px;"></div>	6 / 10
 Hood	<div style="width: 75%; background-color: yellow; height: 10px;"></div>	6 / 10

TOTAL ESTIMATE SPEND 22,000



www.droom.in/eco
support@eco.com
Contact No. 1800 407 0707 (Toll Free)

-a service by  droom.in

Page no. 1 of 7

Ordered by: POONAM RANI | Inspected date: 25/04/2017

Order Id: 10317

Overall Score **6/10**



1,65,598

DOES NOT NEED ATTENTION

NEED ATTENTION

INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
DOOR PANEL	6		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	6		0
SPEAKERS	6		0
HANDBRAKE	6		0
PEDAL	6		0
SPEEDOMETER/ODOMETER	6		0
HAZARD LIGHTS	6		0
STEERING MOUNTED CONTROLS	0	NOT AVAILABLE	0
CENTRAL LOCK	0		0
A/C VENTS AND HEATER	5	AC BLOWER NOISY, NEED CLEANING & SERVICING	5000
CUP HOLDER	0		0
NAVIGATION	0		0
POWER WINDOWS (NO)	0		0

WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
TYRES	6		0
SPARE TYRE	6		0
WHEEL ASSEMBLY (STEEL RIM)	6		0

Ordered by: POONAM RANI | Inspected date: 25/04/2017

Order Id: 10317

Overall Score **6/10**



1,65,598

DOES NOT NEED ATTENTION

NEED ATTENTION



TEST DRIVE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	6		0
ENGINE NOISE	6		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CLUTCH PERFORMANCE	4	CLUTCH HARD,NEED O/H	5000
CRUISE CONTROL	0		0
REAR PARKING SENSORS	0		0
REAR VIEW CAMERA	0		0



HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	6		0
COOLANT LEVEL	6		0

Ordered by: POONAM RANI | Inspected date: 25/04/2017

Order Id: 10317

Overall Score  **6/10**



1,65,598

DOES NOT NEED ATTENTION

NEED ATTENTION

HOOD (CONTINUED)

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0
ENGINE SOUND	0		0

EXTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LICENSE PLATE	6		0
FRONT BUMPER	6		0
HEAD LIGHTS	6		0
GRILLE	6		0
TURN SIGNAL	6		0
HOOD	6		0
FRONT WINDSHIELD	6		0
SIDE VIEW MIRRORS	6		0
LH FENDER	6		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH RUNNING BOARD	6		0
LH QUARTER PANEL	6		0
REAR WINDSHIELD	6		0

Ordered by: POONAM RANI | Inspected date: 25/04/2017

Order Id: 10317

Overall Score



6/10



1,65,598

DOES NOT NEED ATTENTION

NEED ATTENTION



EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
REAR BUMPER	6		0
TRUNK LID/TAIL GATE	6		0
RH RUNNING BOARD	6		0
RH REAR DOOR	6		0
RH FRONT DOOR	6	DENTED	2500
RH FENDER	6		0
BODY RUST	6		0
ROOF (REGULAR)	6		0
PAINT CONDITION	6		0
FOG LAMPS	0		0
PILLAR	3	RHS A-PILLAR HAS BEEN REPAIRED.	2500
FUEL LID	4	BROKEN	1000
TAIL LIGHT	5	RHS TAIL LIGHT MINOR CRACK	1000
LUGGAGE COMPARTMENT LIGHT	0		0
RH QUARTER PANEL	4	DENTED	5000



DESCRIPTION

Average condition car, CNG endrosed at RC

Overall Score



6/10



1,65,598

DOES NOT NEED ATTENTION

NEED ATTENTION

IMAGES



DAMAGE IMAGES



Ordered by: POONAM RANI | Inspected date: 25/04/2017

Order Id: 10317

Overall Score



6/10



1,65,598

DOES NOT NEED ATTENTION

NEED ATTENTION



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE