

# ECO INSPECTION REPORT

Premium

Order ID : 18436

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered by : \_\_\_\_\_ | Inspection Date : 15/12/2017

## 8/10

**Overall Score**

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 120 does not need attention
- ✓ 2 owners , 2 Years Vehicle Age
- ✓ No Accidental History

Inspected By



✓ **Verified Technician**

58+ vehicle inspected  
2+ years experience










Ajay Srinivas Raghavan

## Ford Ecosport Trend 1.5l Tdci, 2016



VEHICLE INFORMATION			
MAKE	FORD	TRANSMISSION TYPE	MANUAL
MODEL	ECOSPORT	REGISTRATION NO	DGJJJ
YEAR	2016	VIN/CHASIS NUMBER	FHJG
TRIM	TREND 1.5L TDCI	KMS RUN	8666
COLOR	RED	INSURANCE EXPIRY	2018-2-2
BODY TYPE	SEDAN	LOCATION	GJJC
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	1,200	 RC COPY AVAILABLE	NO	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.

With this evaluation, the Fair Market Value for this vehicle comes to be:






## 7,90,495



Very Good Condition


### ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

#### ECO SCORE


 Interior	<div style="width: 80%; height: 10px; background-color: green; border: 1px solid gray;"></div>	8 / 10
 Wheel	<div style="width: 80%; height: 10px; background-color: green; border: 1px solid gray;"></div>	8 / 10
 Test	<div style="width: 70%; height: 10px; background-color: green; border: 1px solid gray;"></div>	7 / 10
 Exterior	<div style="width: 80%; height: 10px; background-color: green; border: 1px solid gray;"></div>	8 / 10
 Hood	<div style="width: 80%; height: 10px; background-color: green; border: 1px solid gray;"></div>	8 / 10

#### TOTAL ESTIMATE SPEND 0


0

 interior


0

 wheel


0

 test

0

 exterior

0

 hood

Ordered by: | Inspected date: 15/12/2017

Order Id: 18436

Overall Score



8/10



7,90,495

DOES NOT NEED ATTENTION

NEED ATTENTION



## INTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
DOOR PANEL	8		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
STEERING-MOUNTED CONTROLS	8		0
CENTRAL LOCK	8		0
PEDALS	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION	8		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0



## WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
TYRES	8		0
SPARE TYRE	7		0
WHEEL ASSEMBLY (STEEL RIM)	7		0
CENTRAL LOCK	8		0

Ordered by: | Inspected date: 15/12/2017

Order Id: 18436

Overall Score



8/10



7,90,495

DOES NOT NEED ATTENTION

NEED ATTENTION



## TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	8		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL	7		0
REAR PARKING SENSORS	7		0
REAR VIEW CAMERA	7		0



## HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0

Ordered by: | Inspected date: 15/12/2017

Order Id: 18436

Overall Score  **8/10**



**7,90,495**

DOES NOT NEED ATTENTION

NEED ATTENTION

## HOOD (CONTINUED)

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0
CENTRAL LOCK	8		0
ENGINE SOUND	0		0

## EXTERIOR

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
HEAD LIGHTS	8		0
GRILLE	7		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0

Ordered by: | Inspected date: 15/12/2017

Order Id: 18436

Overall Score



8/10



7,90,495

DOES NOT NEED ATTENTION

NEED ATTENTION

IMAGES



Ordered by: | Inspected date: 15/12/2017

Order Id: 18436

Overall Score



8/10



7,90,495

DOES NOT NEED ATTENTION

NEED ATTENTION

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE