

# ECO INSPECTION REPORT Premium

Order ID : 10829

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered by : Sanjay Khanna


Inspection Date : 10/05/2017

Inspected By

## 7/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 111 does not need attention
- ✓ 1 owner , 5 Years Vehicle Age
- ✓ No Accidental History



✓ **Verified Technician**




175+ vehicle inspected  
1+ years experience

Davinder Pal Singh

## Suzuki Access 125cc, 2012



VEHICLE INFORMATION			
MAKE	SUZUKI	LOCATION	S N
MODEL	ACCESS	REGISTRATION NO	DL4SBZ2076
YEAR	2012	VIN/CHASIS NUMBER	79320
TRIM	125CC	KMS RUN	13351
COLOR	WHITE	INSURANCE EXPIRY	2017-5-1
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY OBSERVATIONS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Value for this vehicle comes to be:







Orange Book Value Not Available



orangebookvalue.com


## ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

### ECO SCORE


 Tyre	<div style="width: 60%; height: 10px; background: linear-gradient(to right, yellow, grey);"></div>	6 / 10
 Control	<div style="width: 70%; height: 10px; background: linear-gradient(to right, green, grey);"></div>	7 / 10
 Light	<div style="width: 70%; height: 10px; background: linear-gradient(to right, green, grey);"></div>	7 / 10
 Oil	<div style="width: 60%; height: 10px; background: linear-gradient(to right, yellow, grey);"></div>	6 / 10
 Chassis	<div style="width: 70%; height: 10px; background: linear-gradient(to right, green, grey);"></div>	7 / 10
 Stand	<div style="width: 70%; height: 10px; background: linear-gradient(to right, green, grey);"></div>	7 / 10

### TOTAL ESTIMATE SPEND 0


0




0




0




0



0



0



Ordered by: Sanjay Khanna | Inspected date: 10/05/2017

Order Id: 10829

Overall Score  **7/10**



Orange Book Value Not Available

DOES NOT NEED ATTENTION

NEED ATTENTION

## TYRE

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
TYRES CONDITION & AIR PRESSURE FRONT	7		0
TYRES CONDITION & AIR PRESSURE REAR	7		0
WHEELS BEARINGS REAR	6	OK	0
WHEELS SEALS FRONT	6		0
WHEELS SEALS REAR	6		0
BRAKES FUNCTION FRONT	6		0
BRAKES FUNCTION REAR	6		0
BRAKES CONDITION FRONT	6		0
BRAKES CONDITION REAR	6		0
WHEELS SPOKES FRONT	0	NA	0
WHEELS SPOKES REAR	0	NA	0
WHEELS RIMS FRONT	4	BEND	0
WHEELS RIMS REAR	3	BEND	0
WHEELS BEARINGS FRONT	5	OK	0

## STAND

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
CENTRE STAND CONDITION	7		0
CENTRE STAND RETENTION	7		0
SIDE STAND CONDITION	7		0
SIDE STAND RETENTION	7		0

Ordered by: Sanjay Khanna | Inspected date: 10/05/2017

Order Id: 10829

Overall Score  **7/10**



Orange Book Value Not Available

DOES NOT NEED ATTENTION

NEED ATTENTION



## CONTROL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
HANDLEBARS CONDITION	7		0
LEVERS & PEDAL CONDITION	7		0
PIVOTS	7		0
CABLES CONDITION	7		0
CABLES ROUTING	7		0
HOSES CONDITION	7		0
HOSES ROUTING	7		0
THROTTLE OPERATION	7		0



## OIL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LEVELS – ENGINE OIL	6		0
LEVELS – GEAR OIL, SHAFT DRIVE	6		0
LEVELS – FUEL	6		0
LEAKS – ENGINE OIL	6		0
LEAKS – GEAR OIL, SHAFT DRIVE	6		0
LEAKS – FUEL	6		0
ENGINE SOUND	0		0
LEVELS – HYDRAULIC FLUID	0	NA	0
LEVELS – COOLANT	0	NA	0
LEAKS – HYDRAULIC FLUID	0	NA	0
LEAKS – COOLANT	0	NA	0

Ordered by: Sanjay Khanna | Inspected date: 10/05/2017

Order Id: 10829

Overall Score  **7/10**



Orange Book Value Not Available

DOES NOT NEED ATTENTION

NEED ATTENTION

## LIGHT

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BATTERY CONDITION	7		0
BATTERY VENT TUBE	7		0
HEADLAMP CONDITION	7		0
HEADLAMP AIM	7		0
TAILLAMP/BRAKELAMP CONDITION	7		0
TAILLAMP/BRAKELAMP OPERATION	7		0
TURN SIGNALS OPERATION FRONT LEFT	7		0
TURN SIGNALS OPERATION FRONT RIGHT	7		0
TURN SIGNALS OPERATION REAR LEFT	7		0
TURN SIGNALS OPERATION REAR RIGHT	7		0
SWITCHES OPERATION	7		0
MIRRORS CONDITION	7		0
MIRRORS AIM	7		0
LENSES & REFLECTORS CONDITION	7		0
WIRING CONDITION	7		0
WIRING ROUTING	7		0

Ordered by: Sanjay Khanna | Inspected date: 10/05/2017

Order Id: 10829

Overall Score  **7/10**



Orange Book Value Not Available

DOES NOT NEED ATTENTION

NEED ATTENTION



## CHASSIS



**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
FRAME CONDITION	7		0
FRAME STEERING-HEAD BEARINGS	7		0
FRAME SWINGARM BUSHINGS	7		0
SUSPENSION FRONT FORKS LEFT	7		0
SUSPENSION FRONT FORKS RIGHT	7		0
SUSPENSION REAR SHOCK(S) LEFT	7		0
SUSPENSION REAR SHOCK(S) RIGHT	7		0
CHAIN OR BELT TENSION	7		0
CHAIN OR BELT LUBRICATION	7		0
CHAIN OR BELT SPROCKETS	7		0
FASTENERS THREADED	7		0
FASTENERS CLIPS & COTTER PINS	7		0
ENGINE	7		0
TRANSMISSION	7		0



## DESCRIPTION

ok

Ordered by: Sanjay Khanna | Inspected date: 10/05/2017

Order Id: 10829

Overall Score



7/10



Orange Book Value Not Available

DOES NOT NEED ATTENTION

NEED ATTENTION

IMAGES



Ordered by: Sanjay Khanna | Inspected date: 10/05/2017

Order Id: 10829

Overall Score



7/10



Orange Book Value Not Available

DOES NOT NEED ATTENTION

NEED ATTENTION

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.