

# ECO INSPECTION REPORT

Premium

Order ID : 13479

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered by : Biren Patel

Inspection Date : 15/07/2017

8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 120 does not need attention
- ✓ 1 owner , 3 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Abhijit Rathod

✓ Verified Technician

266+ vehicle inspected

1+ years experience









## Honda City Sv Mt Diesel, 2014



### VEHICLE INFORMATION

MAKE	HONDA	TRANSMISSION TYPE	MANUAL
MODEL	CITY	REGISTRATION NO	GJ01 RG0422
YEAR	2014	VIN/CHASIS NUMBER	MAKGM85CGENO10078
TRIM	SV MT DIESEL	KMS RUN	53055
COLOR	OTHER	INSURANCE EXPIRY	2016-7-17
BODY TYPE	SEDAN	LOCATION	AEC BRIDGE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	15,000	 RC COPY AVAILABLE	NO	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.

With this evaluation, the Fair Market Value for this vehicle comes to be:

**9,21,210**




Very Good Condition

### ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

#### ECO SCORE

 Interior	<div style="width: 80%;"></div>	8 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 80%;"></div>	8 / 10
 Hood	<div style="width: 80%;"></div>	8 / 10

#### TOTAL ESTIMATE SPEND 0



Ordered by: Biren Patel | Inspected date: 15/07/2017

Order Id: 13479

Overall Score



8/10



9,21,210

DOES NOT NEED ATTENTION

NEED ATTENTION



## INTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
DOOR PANEL	9		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS	8		0
HANDBRAKE	8		0
STEERING MOUNTED CONTROLS	8		0
PEDAL	8		0
CENTRAL LOCK	8		0
A/C VENTS AND HEATER	8		0
CUP HOLDER	8		0
NAVIGATION	8		0
SPEEDOMETER/ODOMETER	8		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHTS	8		0



## WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
TYRES	8		0
SPARE TYRE	8		0
WHEEL ASSEMBLY (STEEL RIM)	8		0



Ordered by: Biren Patel | Inspected date: 15/07/2017

Order Id: 13479

Overall Score  **8/10**



**9,21,210**

DOES NOT NEED ATTENTION

NEED ATTENTION



## TEST DRIVE



**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL	8		0
REAR PARKING SENSORS	8		0
REAR VIEW CAMERA	8		0



## HOOD



**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	9		0
COOLANT LEVEL	8		0



Ordered by: Biren Patel | Inspected date: 15/07/2017

Order Id: 13479

Overall Score  **8/10**



**9,21,210**

DOES NOT NEED ATTENTION

NEED ATTENTION

## HOOD (CONTINUED)

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	8		0
ENGINE SOUND	0		0

## EXTERIOR

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LICENSE PLATE	8		0
FRONT BUMPER	8		0
HEAD LIGHTS	9		0
GRILLE	9		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	9		0
LH RUNNING BOARD	8		0



Ordered by: Biren Patel | Inspected date: 15/07/2017

Order Id: 13479

Overall Score  **8/10**



**9,21,210**

DOES NOT NEED ATTENTION

NEED ATTENTION

## EXTERIOR (CONTINUED)

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	8		0
TAIL LIGHT	9		0
TRUNK LID/TAIL GATE	9		0
LUGGAGE COMPARTMENT LIGHT	9		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	8		0
RH REAR DOOR	8		0
RH FRONT DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	8		0
PAINT CONDITION	8		0

## DESCRIPTION

Good vehicle



Ordered by: Biren Patel | Inspected date: 15/07/2017

Order Id: 13479

Overall Score



8/10















9,21,210

DOES NOT NEED ATTENTION

NEED ATTENTION

IMAGES



Ordered by: Biren Patel | Inspected date: 15/07/2017

Order Id: 13479

Overall Score



8/10



9,21,210

DOES NOT NEED ATTENTION

NEED ATTENTION

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

