

ECO INSPECTION REPORT Premium

Order ID : 14847

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered by : Anubhav Talwar | Inspection Date : 23/08/2017

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 109 does not need attention
- ✓ 1 owner , 3 Years Vehicle Age
- ✓ No Accidental History

Inspected By




✓ **Verified Technician**

560+ vehicle inspected
1+ years experience

Jeevan Tanwal

Audi A4 2.0 Tdi 174bhp Premium, 2014



VEHICLE INFORMATION

MAKE	AUDI	TRANSMISSION TYPE	AUTOMATIC
MODEL	A4	REGISTRATION NO	HR51
YEAR	2014	VIN/CHASIS NUMBER	000000
TRIM	2.0 TDI 174BHP PREMIUM	KMS RUN	19979
COLOR	BLACK	INSURANCE EXPIRY	2017-7-4
BODY TYPE	SEDAN	LOCATION	DELHI
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	15,000	 RC COPY AVAILABLE	NO	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Value for this vehicle comes to be:






23,89,807



Good Condition


ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT


ECO SCORE


 Interior	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
 Wheel	<div style="width: 60%; background-color: yellow; height: 10px;"></div>	6 / 10
 Test	<div style="width: 50%; background-color: orange; height: 10px;"></div>	5 / 10
 Exterior	<div style="width: 60%; background-color: yellow; height: 10px;"></div>	6 / 10
 Hood	<div style="width: 60%; background-color: yellow; height: 10px;"></div>	6 / 10


TOTAL ESTIMATE SPEND 11,500


11,500




 interior

 wheel

 test

 exterior

 hood

Ordered by: Anubhav Talwar | Inspected date: 23/08/2017

Order Id: 14847

Overall Score



6/10



23,89,807

DOES NOT NEED ATTENTION

NEED ATTENTION



INTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS	7		0
HANDBRAKE	7		0
STEERING MOUNTED CONTROLS	7		0
PEDAL	7		0
CENTRAL LOCK	7		0
A/C VENTS AND HEATER	6		0
CUP HOLDER	7		0
SPEEDOMETER/ODOMETER	6		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHTS	7		0
NAVIGATION	0		0



WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
TYRES	6		0
SPARE TYRE	6		0
WHEEL ASSEMBLY (ALLOY RIM)	6		0

Ordered by: Anubhav Talwar | Inspected date: 23/08/2017

Order Id: 14847

Overall Score **6/10**



23,89,807

DOES NOT NEED ATTENTION

NEED ATTENTION

TEST DRIVE

5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
ENGINE NOISE	6		0
IGNITION SYSTEM	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL	6		0
REAR PARKING SENSORS	6		0
STEERING PERFORMANCE	5	TEST DRIVE NOT TAKEN.	0
BRAKE PERFORMANCE	5	TEST DRIVE NOT TAKEN.	0
CLUTCH PERFORMANCE	5	TEST DRIVE NOT TAKEN.	0
SUSPENSION PERFORMANCE	5	TEST DRIVE NOT TAKEN.	0
SUSPENSION FRONT SHOCKS	5	TEST DRIVE NOT TAKEN.	0
SUSPENSION REAR SHOCKS	5	TEST DRIVE NOT TAKEN.	0
REAR VIEW CAMERA	0		0

HOOD

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	6		0
COOLANT LEVEL	6		0

Ordered by: Anubhav Talwar | Inspected date: 23/08/2017

Order Id: 14847

Overall Score  **6/10**



23,89,807

DOES NOT NEED ATTENTION

NEED ATTENTION

HOOD (CONTINUED)

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0
ENGINE SOUND	0		0

EXTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LICENSE PLATE	6		0
HEAD LIGHTS	6		0
GRILLE	6		0
TURN SIGNAL	6		0
FOG LAMPS	6		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	6		0
SIDE VIEW MIRRORS	6		0
LH FENDER	6		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH RUNNING BOARD	6		0
LH QUARTER PANEL	6		0

Ordered by: Anubhav Talwar | Inspected date: 23/08/2017

Order Id: 14847

Overall Score  **6/10**



23,89,807

DOES NOT NEED ATTENTION

NEED ATTENTION

EXTERIOR (CONTINUED)

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
FUEL LID	6		0
REAR WINDSHIELD	6		0
REAR BUMPER	6		0
TAIL LIGHT	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	6		0
RH RUNNING BOARD	6		0
RH FRONT DOOR	6		0
RH FENDER	6		0
BODY RUST	6		0
ROOF (SUN ROOF)	6		0
PAINT CONDITION	6		0
FRONT BUMPER	5	FOG LAMP COVER MISSING.	1500
TRUNK LID/TAIL GATE	5	SCRATCHES.	5000
RH REAR DOOR	5	MINOR SCRATCHES.	5000

DESCRIPTION

Car is average condition.

Ordered by: Anubhav Talwar | Inspected date: 23/08/2017

Order Id: 14847

Overall Score



6/10



23,89,807

DOES NOT NEED ATTENTION

NEED ATTENTION

IMAGES



Ordered by: Anubhav Talwar | Inspected date: 23/08/2017

Order Id: 14847

Overall Score



6/10



23,89,807

DOES NOT NEED ATTENTION

NEED ATTENTION



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.