

ECO INSPECTION REPORT

Premium

Order ID : 14933

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered by : Gaurav Kalra | Inspection Date : 26/08/2017

6/10

Overall Score

- ✔ Evaluated across 5 segments
- ✔ Covered 121+ checkpoints
- ✔ 108 does not need attention
- ✔ 1 owner , 6 Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ **Verified Technician**

599+ vehicle inspected

1+ years experience

Jeevan Tanwal

Maruti Suzuki Sx4 Zxi At Bs-iv, 2011



VEHICLE INFORMATION			
MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	AUTOMATIC
MODEL	SX4	REGISTRATION NO	HR26
YEAR	2011	VIN/CHASIS NUMBER	00000
TRIM	ZXI AT BS-IV	KMS RUN	50040
COLOR	SILVER	INSURANCE EXPIRY	2017-7-12
BODY TYPE	SEDAN	LOCATION	DELHI
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	20,000	 RC COPY AVAILABLE	NO	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Value for this vehicle comes to be:






3,31,033




Good Condition

ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test	<div style="width: 50%;"></div>	5 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 3,000



Bar chart showing spend estimates for interior, wheel, test, exterior, and hood. The 'test' category has the highest spend estimate of 3,000.

Ordered by: Gaurav Kalra | Inspected date: 26/08/2017

Order Id: 14933

Overall Score



6/10



3,31,033

DOES NOT NEED ATTENTION

NEED ATTENTION



INTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	6		0
SPEAKERS	6		0
HANDBRAKE	6		0
STEERING MOUNTED CONTROLS	6		0
PEDAL	6		0
CENTRAL LOCK	6		0
A/C VENTS AND HEATER	6		0
CUP HOLDER	6		0
SPEEDOMETER/ODOMETER	6		0
POWER WINDOWS (YES)	6		0
HAZARD LIGHTS	6		0
DOOR PANEL	6		0
NAVIGATION	0		0



WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
TYRES	6		0
SPARE TYRE	6		0
WHEEL ASSEMBLY (ALLOY RIM)	6		0

Ordered by: Gaurav Kalra | Inspected date: 26/08/2017

Order Id: 14933

Overall Score  **6/10**



3,31,033

DOES NOT NEED ATTENTION

NEED ATTENTION

TEST DRIVE

 **5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
ENGINE NOISE	6		0
IGNITION SYSTEM	6		0
TRANSMISSION ENGAGE	6		0
REAR PARKING SENSORS	6		0
STEERING PERFORMANCE	5	TEST DRIVE NOT TAKEN.	0
BRAKE PERFORMANCE	5	TEST DRIVE NOT TAKEN.	0
CLUTCH PERFORMANCE	5	TEST DRIVE NOT TAKEN.	0
SUSPENSION PERFORMANCE	5	TEST DRIVE NOT TAKEN.	0
SUSPENSION FRONT SHOCKS	5	TEST DRIVE NOT TAKEN.	0
SUSPENSION REAR SHOCKS	5	TEST DRIVE NOT TAKEN.	0
CRUISE CONTROL	0		0
REAR VIEW CAMERA	0		0

HOOD

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
ENGINE SOUND	6		0
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	6		0

Ordered by: Gaurav Kalra | Inspected date: 26/08/2017

Order Id: 14933

Overall Score **6/10**



3,31,033

DOES NOT NEED ATTENTION

NEED ATTENTION

HOOD (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0

EXTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LICENSE PLATE	6		0
HEAD LIGHTS	6		0
GRILLE	6		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	6		0
SIDE VIEW MIRRORS	6		0
LH FENDER	6		0
LH FRONT DOOR	6		0
LH RUNNING BOARD	6		0
FUEL LID	6		0
REAR WINDSHIELD	6		0

Ordered by: Gaurav Kalra | Inspected date: 26/08/2017

Order Id: 14933

Overall Score  **6/10**



3,31,033

DOES NOT NEED ATTENTION

NEED ATTENTION

EXTERIOR (CONTINUED)

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
TAIL LIGHT	6		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	6		0
RH RUNNING BOARD	6		0
RH REAR DOOR	6		0
RH FRONT DOOR	6		0
RH FENDER	6		0
BODY RUST	6		0
ROOF (REGULAR)	6		0
PAINT CONDITION	6		0
FRONT BUMPER	5	SCRATCHES.	1500
LH REAR DOOR	5	REPAINTED.	0
LH QUARTER PANEL	5	REPAINTED.	0
REAR BUMPER	5	SCRATCHES	1500

DESCRIPTION

Car is average condition

Ordered by: Gaurav Kalra | Inspected date: 26/08/2017

Order Id: 14933

Overall Score



6/10




3,31,033

DOES NOT NEED ATTENTION

NEED ATTENTION

IMAGES



Ordered by: Gaurav Kalra | Inspected date: 26/08/2017

Order Id: 14933

Overall Score



6/10



3,31,033

DOES NOT NEED ATTENTION

NEED ATTENTION



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.