

ECO INSPECTION REPORT

Premium

Order ID : 16468

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered by : Mr. Jagmohan Singh | Inspection Date : 29/09/2017

7/10

Overall Score

- ✔ Evaluated across 5 segments
- ✔ Covered 121+ checkpoints
- ✔ 115 does not need attention
- ✔ 1 owner , 6 Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ **Verified Technician**

42+ vehicle inspected









1+ years experience

Rajeev Narula

Maruti Suzuki Wagon R 1.0 Lxi Cng, 2011



VEHICLE INFORMATION			
MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	WAGON R 1.0	REGISTRATION NO	DL2CAN7484
YEAR	2011	VIN/CHASIS NUMBER	MA3EWDE1S00327060
TRIM	LXI CNG	KMS RUN	51071
COLOR	SILVER	INSURANCE EXPIRY	2017-10-9
BODY TYPE	OTHER	LOCATION	DELHI
FUEL TYPE	CNG	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	8,000	 RC COPY AVAILABLE	YES (ORIGINAL)
 DENT	NO	 INSURANCE COPY AVAILABLE	NO
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	NO
		 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Value for this vehicle comes to be:

2,43,035




ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

ECO SCORE


-  Interior 6 / 10
-  Wheel 8 / 10
-  Test 6 / 10
-  Exterior 7 / 10
-  Hood 7 / 10

TOTAL ESTIMATE SPEND 0


0

 interior


0

 wheel


0

 test

0

 exterior

0

 hood

Ordered by: Mr. Jagmohan singh | Inspected date: 29/09/2017

Order Id: 16468

Overall Score  **7/10**



2,43,035

DOES NOT NEED ATTENTION

NEED ATTENTION

INTERIOR

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
DOOR PANEL	6		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	6		0
CENTRAL LOCK	7		0
PEDALS	7		0
A/C VENTS & HEATER	6		0
CUP HOLDERS	7		0
POWER WINDOWS (YES)	6		0
HAZARD LIGHT	6		0
STEERING-MOUNTED CONTROLS	0	UNAVAILABLE	0
NAVIGATION	0	UNAVAILABLE	0

WHEEL

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
TYRES	8		0
SPARE TYRE	7		0
WHEEL ASSEMBLY (STEEL RIM)	8		0
CENTRAL LOCK	7		0

Ordered by: Mr. Jagmohan singh | Inspected date: 29/09/2017

Order Id: 16468

Overall Score  **7/10**



2,43,035

DOES NOT NEED ATTENTION

NEED ATTENTION



TEST DRIVE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	6		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL	0	UNAVAILABLE	0
REAR PARKING SENSORS	0	UNAVAILABLE	0
REAR VIEW CAMERA	0	UNAVAILABLE	0



HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LH APRON	6		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0

Ordered by: Mr. Jagmohan singh | Inspected date: 29/09/2017

Order Id: 16468

Overall Score  **7/10**



2,43,035

DOES NOT NEED ATTENTION

NEED ATTENTION

HOOD (CONTINUED)

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	7		0
CENTRAL LOCK	7		0
ENGINE SOUND	0		0

EXTERIOR

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LICENSE PLATE	6		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	7		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	6		0
LH FENDER	7		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH RUNNING BOARD	6		0

Ordered by: Mr. Jagmohan singh | Inspected date: 29/09/2017

Order Id: 16468

Overall Score  **7/10**



2,43,035

DOES NOT NEED ATTENTION

NEED ATTENTION

EXTERIOR (CONTINUED)

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LH QUARTER PANEL	6		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	6		0
RH RUNNING BOARD	6		0
RH REAR DOOR	6		0
RH FRONT DOOR	6		0
RH FENDER	6		0
BODY RUST	6		0
ROOF (REGULAR)	6		0
PAINT CONDITION	7		0

DESCRIPTION

vehicle is in good condition

Ordered by: Mr. Jagmohan singh | Inspected date: 29/09/2017

Order Id: 16468

Overall Score



7/10




2,43,035

DOES NOT NEED ATTENTION

NEED ATTENTION

IMAGES



Ordered by: Mr. Jagmohan singh | Inspected date: 29/09/2017

Order Id: 16468

Overall Score



7/10



2,43,035

DOES NOT NEED ATTENTION

NEED ATTENTION

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.