

ECO INSPECTION REPORT

Premium

Order ID : 17537

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered by : _____ | Inspection Date : 26/10/2017

8/10

Overall Score

- ✔ Evaluated across **6** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** owner , **5** Years Vehicle Age
- ✔ No Accidental History

Inspected By

✔ **Verified Technician**

492+ vehicle inspected

1+ years experience

Abhijit Rathod

Piaggio Vespa 125cc, 2012



VEHICLE INFORMATION			
MAKE	PIAGGIO	LOCATION	AHMEDABAD
MODEL	VESPA	REGISTRATION NO	GJ01PK7214
YEAR	2012	VIN/CHASIS NUMBER	ABCD
TRIM	125CC	KMS RUN	30802
COLOR	WHITE	INSURANCE EXPIRY	2016-10-27
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY OBSERVATIONS					
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	NO	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO

orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.

With this evaluation, the Fair Market Value for this vehicle comes to be:

30,130

Very Good Condition

ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

ECO SCORE

- Tyre 8 / 10
- Control 8 / 10
- Light 8 / 10
- Oil 8 / 10
- Chassis 8 / 10
- Stand 8 / 10

TOTAL ESTIMATE SPEND 0

0

0

0

0

0

0

Tyre
 Control
 Light
 Oil
 Chassis
 Stand

Ordered by: | Inspected date: 26/10/2017

Order Id: 17537

Overall Score **8/10**



30,130

DOES NOT NEED ATTENTION

NEED ATTENTION

TYRE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
FRONT TYRE CONDITION & AIR PRESSURE	8		0
REAR TYRE CONDITION & AIR PRESSURE	7		0
WHEELS SPOKES FRONT	7		0
WHEELS SPOKES REAR	8		0
WHEELS RIMS FRONT	8		0
WHEELS RIMS REAR	8		0
WHEELS BEARINGS FRONT	8		0
WHEELS BEARINGS REAR	8		0
WHEELS SEALS FRONT	8		0
WHEELS SEALS REAR	8		0
BRAKE FUNCTION FRONT	8		0
BRAKE FUNCTION REAR	8		0
BRAKES CONDITION FRONT	8		0
BRAKES CONDITION REAR	8		0

STAND

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
CENTRE STAND CONDITION	8		0
CENTRE STAND RETENTION	8		0
SIDE STAND CONDITION	8		0
SIDE STAND RETENTION	8		0

Ordered by: | Inspected date: 26/10/2017

Order Id: 17537

Overall Score



8/10



30,130

DOES NOT NEED ATTENTION

NEED ATTENTION



CONTROL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
HANDLEBARS CONDITION	8		0
LEVERS & PEDAL CONDITION	8		0
PIVOTS	8		0
CABLES CONDITION	8		0
CABLES ROUTING	8		0
HOSES CONDITION	8		0
HOSES ROUTING	8		0
THROTTLE OPERATION	8		0



OIL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LEVELS - ENGINE OIL	8		0
LEVELS - GEAR OIL/SHAFT DRIVE	8		0
LEVELS - HYDRAULIC FLUID	8		0
LEVELS - COOLANT	8		0
LEVELS - FUEL	8		0
LEAKS - ENGINE OIL	8		0
LEAKS - GEAR OIL	8		0
LEAKS - HYDRAULIC FLUID	8		0
LEAKS - COOLANT	8		0
LEAKS - FUEL	8		0
ENGINE SOUND	0		0

Ordered by: | Inspected date: 26/10/2017

Order Id: 17537

Overall Score



8/10



30,130

DOES NOT NEED ATTENTION

NEED ATTENTION

 LIGHT



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BATTERY CONDITION	8		0
BATTERY VENT TUBE	8		0
HEADLAMP CONDITION	8		0
TAILLAMP/BRAKELAMP CONDITION	8		0
TAILLAMP/BRAKELAMP OPERATION	8		0
TURN SIGNALS OPERATION FRONT LEFT	8		0
TURN SIGNALS OPERATION FRONT RIGHT	8		0
TURN SIGNALS OPERATION REAR LEFT	8		0
TURN SIGNALS OPERATION REAR RIGHT	8		0
SWITCHES OPERATION	8		0
MIRRORS CONDITION	8		0
MIRRORS AIM	8		0
LENSES & REFLECTORS CONDITION	8		0
WIRING CONDITION	8		0
WIRING ROUTING	7		0

Ordered by: | Inspected date: 26/10/2017

Order Id: 17537

Overall Score **8/10**



30,130

DOES NOT NEED ATTENTION

NEED ATTENTION

CHASSIS

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
FRAME CONDITION	8		0
FRAME STEERING-HEAD BEARINGS	8		0
FRAME SWINGARM BUSHINGS	8		0
SUSPENSION FRONT FORKS LEFT	8		0
SUSPENSION FRONT FORKS RIGHT	8		0
SUSPENSION REAR SHOCKS LEFT	8		0
SUSPENSION REAR SHOCKS RIGHT	8		0
CHAIN/BELT TENSION	8		0
CHAIN/BELT LUBRICATION	8		0
CHAIN/BELT SPROCKETS	8		0
FASTENERS THREADED	8		0
FASTENERS CLIPS & COTTER PINS	8		0
ENGINE	8		0
TRANSMISSION	8		0

DESCRIPTION

good

Ordered by: | Inspected date: 26/10/2017

Order Id: 17537

Overall Score



8/10



30,130

DOES NOT NEED ATTENTION

NEED ATTENTION

Ordered by: | Inspected date: 26/10/2017

Order Id: 17537

Overall Score



8/10



30,130

DOES NOT NEED ATTENTION

NEED ATTENTION



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

