

ECO INSPECTION REPORT Premium

Order ID : 21794

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Ravi Kumar	Inspection Date : 2018-08-18	Valid Till : 2018-11-18
----------------------------	---------------------------------	----------------------------

8/10

Overall Score

- ✔ Evaluated across 6 segments
- ✔ Covered 121+ checkpoints
- ✔ 121 does not need attention
- ✔ 1 Owner , 5 Years Vehicle Age
- ✔ No Accidental History

Inspected By




✔ **Verified Technician**

7+ vehicle inspected








1+ years experience

Ajay Singh

Harley Davidson Super Glide Custom 1585cc, 2013



VEHICLE INFORMATION			
MAKE	HARLEY DAVIDSON	LOCATION	BANGALORE
MODEL	SUPER GLIDE CUSTOM	REGISTRATION NO.	KA 03 HR 350
YEAR	2013	VIN/CHASIS NUMBER	MEGIGV4N50N310227
TRIM	1585CC	KMS RUN	16390
COLOR	BLACK	INSURANCE EXPIRY	2019-4-27
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY OBSERVATIONS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	40,000	 RC COPY AVAILABLE	YES (DUPLICATE)
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	NO
		 BANK NOC	NO



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.

With this evaluation, the Fair Market Price for this vehicle comes to be:







7,13,148



Very Good Condition


ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE


 Tyre	<div style="width: 80%; height: 10px; background-color: green;"></div>	8 / 10
 Control	<div style="width: 80%; height: 10px; background-color: green;"></div>	8 / 10
 Light	<div style="width: 80%; height: 10px; background-color: green;"></div>	8 / 10
 Oil	<div style="width: 90%; height: 10px; background-color: green;"></div>	9 / 10
 Chassis	<div style="width: 80%; height: 10px; background-color: green;"></div>	8 / 10
 Stand	<div style="width: 70%; height: 10px; background-color: green;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0


0

 Tyre


0

 Control


0

 Light


0

 Oil

0

 Chassis

0

 Stand

Ordered by: Ravi Kumar | Inspected date: 2018-08-18

Order Id: 21794

Overall Score



8/10



7,13,148

TYRE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7		0
REAR TYRE CONDITION & AIR PRESSURE	8		0
WHEEL SPOKES FRONT	8		0
WHEEL SPOKES REAR	8		0
WHEEL RIM FRONT	7		0
WHEEL RIM REAR	8		0
WHEEL BEARINGS FRONT	8		0
WHEEL BEARINGS REAR	8		0
WHEEL SEALS FRONT	8		0
WHEEL SEALS REAR	10		0
BRAKE FUNCTION FRONT	8		0
BRAKE FUNCTION REAR	9		0
BRAKES CONDITION FRONT	8		0
BRAKES CONDITION REAR	8		0

IMAGES



Ordered by: Ravi Kumar | Inspected date: 2018-08-18

Order Id: 21794

Overall Score




8/10



7,13,148



NEED ATTENTION



STAND




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	7	CENTRE STAND WILL NOT COME	0
CENTRE STAND RETENTION	7	CENTRE STAND WILL NOT COME	0
SIDE STAND CONDITION	7		0
SIDE STAND RETENTION	7		0



IMAGES



NEED ATTENTION





CONTROL



8/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	7		0
LEVERS & PEDAL CONDITION	8		0
PIVOTS	8		0
CABLES CONDITION	8		0
CABLES ROUTING	7		0
HOSES CONDITION	7		0
HOSES ROUTING	7		0
THROTTLE OPERATION	8		0



IMAGES



NEED ATTENTION



OIL





9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7		0

LEVELS - GEAR OIL/SHAFT DRIVE	8		0
LEVELS - HYDRAULIC FLUID	7		0
LEVELS - COOLANT	7		0
LEVELS - FUEL	9		0
LEAKS - ENGINE OIL	10		0
LEAKS - GEAR OIL	10		0
LEAKS - HYDRAULIC FLUID	10		0
LEAKS - COOLANT	10		0
LEAKS - FUEL	10		0

 IMAGES



Ordered by: Ravi Kumar | Inspected date: 2018-08-18

Order Id: 21794

Overall Score **8/10**




7,13,148

LIGHT

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	10		0
BATTERY VENT TUBE	10		0
HEADLAMP CONDITION	7		0
TAILLAMP/BRAKELAMP CONDITION	8		0
TAILLAMP/BRAKELAMP OPERATION	8		0
TURN SIGNALS OPERATION FRONT LEFT	8		0
TURN SIGNALS OPERATION FRONT RIGHT	8		0
TURN SIGNALS OPERATION REAR LEFT	7		0
TURN SIGNALS OPERATION REAR RIGHT	7		0
SWITCHES OPERATION	8		0
MIRRORS CONDITION	8		0
MIRRORS AIM	8		0
LENSES & REFLECTORS CONDITION	8		0
WIRING CONDITION	8		0
WIRING ROUTING	8		0

IMAGES



Ordered by: Ravi Kumar | Inspected date: 2018-08-18

Order Id: 21794

Overall Score



8/10



7,13,148

 NEED ATTENTION 



 CHASSIS



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	8		0
FRAME STEERING-HEAD BEARINGS	9		0
FRAME SWINGARM BUSHINGS	8		0
SUSPENSION FRONT FORKS LEFT	8		0
SUSPENSION FRONT FORKS RIGHT	8		0
SUSPENSION REAR SHOCKS LEFT	8		0
SUSPENSION REAR SHOCKS RIGHT	8		0
CHAIN/BELT TENSION	8		0
CHAIN/BELT LUBRICATION	8		0
CHAIN/BELT SPROCKETS	8		0
FASTENERS THREADED	8		0
FASTENERS CLIPS & COTTER PINS	8		0
ENGINE	8		0
TRANSMISSION	8		0

Ordered by: Ravi Kumar | Inspected date: 2018-08-18

Order Id: 21794

Overall Score




8/10



7,13,148


 IMAGES



 NEED ATTENTION 



 DOCUMENTS



 DESCRIPTION

Good

Overall Score




8/10



7,13,148

IMAGES



Ordered by: Ravi Kumar | Inspected date: 2018-08-18

Order Id: 21794

Overall Score



8/10



7,13,148

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.