

ECO INSPECTION REPORT

Premium

Order ID : 20893

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Shyam Therakanambi	Inspection Date : 2018-07-26	Valid Till : 2018-10-26
------------------------------------	---------------------------------	----------------------------

8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 0 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Verified Technician










152+ vehicle inspected
1+ years experience

Sathish Prasanna

Mahindra Kuv100 Nxt K8 6 Str, 2018



VEHICLE INFORMATION			
MAKE	MAHINDRA	TRANSMISSION TYPE	MANUAL
MODEL	KUV100 NXT	REGISTRATION NO.	KA02MN3228
YEAR	2018	VIN/CHASIS NUMBER	88797
TRIM	K8 6 STR	KMS RUN	3837
COLOR	SILVER	INSURANCE EXPIRY	2019-3-2
BODY TYPE	SEDAN	LOCATION	BANGALORE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	YES (ORIGINAL)
 DENT	NO	 INSURANCE COPY AVAILABLE (BUMPER TO BUMPER)	YES
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	NO
		 BANK NOC	NO

 Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

7,19,848

 Very Good Condition

orangebookvalue.com

ECO SCORE & REPAIR COST ESTIMATE

Category	Score
Interior	8/10
Wheel	8/10
Test Drive	8/10
Exterior	8/10
Hood	8/10

TOTAL ESTIMATE SPEND 0

Interior: 0, Wheel: 0, Test Drive: 0, Exterior: 0, Hood: 0

Ordered by: Shyam Therakanambi | Inspected date: 2018-07-26

Order Id: 20893

Overall Score



8/10



7,19,848



INTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	9		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	8		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION	8		0
ODOMETER	8		0
POWER WINDOWS (YES)	9		0
HAZARD LIGHT	8		0



IMAGES



Ordered by: Shyam Therakanambi | Inspected date: 2018-07-26

Order Id: 20893

Overall Score



8/10



7,19,848



TEST DRIVE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	8		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL	8		0
REAR PARKING SENSORS	8		0
REAR VIEW CAMERA	8		0

IMAGES



WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE	8		0
WHEEL ASSEMBLY (STEEL RIM)	8		0

 IMAGES



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	8		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: Shyam Therakanambi | Inspected date: 2018-07-26

Order Id: 20893

Overall Score



8/10



7,19,848



EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8		0
FRONT BUMPER	8		0
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	9		0
SIDE VIEW MIRRORS	9		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	9		0
REAR BUMPER	8		0
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	8		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	8		0
RH REAR DOOR	8		0

Ordered by: Shyam Therakanambi | Inspected date: 2018-07-26

Order Id: 20893

Overall Score



8/10



7,19,848



EXTERIOR (CONTINUED)



8/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	8		0
PAINT CONDITION	9		0



IMAGES



DOCUMENTS



DESCRIPTION

good condition vehicle

Ordered by: Shyam Therakanambi | Inspected date: 2018-07-26

Order Id: 20893

Overall Score




8/10



7,19,848

IMAGES



Ordered by: Shyam Therakanambi | Inspected date: 2018-07-26

Order Id: 20893

Overall Score



8/10



7,19,848

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.