

ECO INSPECTION REPORT

Premium

Order ID : 20380

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Rinku Sharma	Inspection Date : 2018-07-07	Valid Till : 2018-10-07
------------------------------	---------------------------------	----------------------------

7/10

Overall Score

- ✔ Evaluated across 5 segments
- ✔ Covered 121+ checkpoints
- ✔ 121 does not need attention
- ✔ 1 Owner , 1 Year Vehicle Age
- ✔ No Accidental History

Inspected By



✔ **Verified Technician**

1+ vehicle inspected


1+ years experience

Ankit Tomar

Maruti Suzuki Alto 800 Lxi, 2017



VEHICLE INFORMATION			
MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	ALTO 800	REGISTRATION NO.	HR26DH4343
YEAR	2017	VIN/CHASIS NUMBER	95771
TRIM	LXI	KMS RUN	5495
COLOR	RED	INSURANCE EXPIRY	2018-7-7
BODY TYPE	HATCHBACK	LOCATION	GURGAON
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	5,495	 RC COPY AVAILABLE	YES (ORIGINAL)
 DENT	NO	 INSURANCE COPY AVAILABLE	NO
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	NO
		 BANK NOC	NO



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:






2,69,181



Very Good Condition


ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE


 Interior	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
 Wheel	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
 Test Drive	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
 Exterior	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
 Hood	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0


0

 Interior


0

 Wheel


0

 Test Drive

0

 Exterior

0

 Hood

Ordered by: Rinku Sharma | Inspected date: 2018-07-07

Order Id: 20380

Overall Score **7/10**



2,69,181



INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION	7		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0



IMAGES



Ordered by: Rinku Sharma | Inspected date: 2018-07-07

Order Id: 20380

Overall Score **7/10**




2,69,181

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL	7		0
REAR PARKING SENSORS	7		0
REAR VIEW CAMERA	7		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE	7		0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: Rinku Sharma | Inspected date: 2018-07-07

Order Id: 20380

Overall Score  **7/10**



2,69,181

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0

Ordered by: Rinku Sharma | Inspected date: 2018-07-07

Order Id: 20380

Overall Score **7/10**



2,69,181

EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7		0
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0

IMAGES



DOCUMENTS



DESCRIPTION

Engine noise OK

Ordered by: Rinku Sharma | Inspected date: 2018-07-07

Order Id: 20380

Overall Score




7/10



2,69,181

IMAGES



Ordered by: Rinku Sharma | Inspected date: 2018-07-07

Order Id: 20380

Overall Score



7/10



2,69,181

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.