

# ECO INSPECTION REPORT Premium

Order ID : 21919

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Vivek Chaturvedi	Inspection Date : 2018-08-23	Valid Till : 2018-11-23	Inspected By  <b>Verified Technician</b> 63+ vehicle inspected 1+ years experience  <b>Lokesh Kumar</b>
----------------------------------	---------------------------------	----------------------------	---

## 6/10

**Overall Score**

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 121 does not need attention
- 1 Owner , 1 Year Vehicle Age
- No Accidental History

## Audi A4 35 Tdi Technology, 2017



VEHICLE INFORMATION			
MAKE	AUDI	TRANSMISSION TYPE	AUTOMATIC
MODEL	A4	REGISTRATION NO.	HR26DH4514
YEAR	2017	VIN/CHASIS NUMBER	702005
TRIM	35 TDI TECHNOLOGY	KMS RUN	9457
COLOR	BLACK	INSURANCE EXPIRY	2018-9-20
BODY TYPE	SEDAN	LOCATION	GURGOW
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	31,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

## 40,75,007

orangebookvalue.com

## ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND 0	
Interior	<div style="width: 60%;"><div style="width: 60%;"></div></div> 6 / 10	0	Interior            Wheel            Test Drive            Exterior            Hood
Wheel	<div style="width: 60%;"><div style="width: 60%;"></div></div> 6 / 10	0	
Test Drive	<div style="width: 70%;"><div style="width: 70%;"></div></div> 7 / 10	0	
Exterior	<div style="width: 60%;"><div style="width: 60%;"></div></div> 6 / 10	0	
Hood	<div style="width: 60%;"><div style="width: 60%;"></div></div> 6 / 10	0	

Ordered by: Vivek Chaturvedi | Inspected date: 2018-08-23

Order Id: 21919

Overall Score **6/10**



**40,75,007**

## INTERIOR

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	FAIR	0
CARPET & FLOOR MAT	6	FAIR	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	6	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (YES)	6		0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6		0
HAZARD LIGHT	6		0

## IMAGES



Ordered by: Vivek Chaturvedi | Inspected date: 2018-08-23

Order Id: 21919

Overall Score



6/10



40,75,007



## TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
ENGINE NOISE	6	NO	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION PERFORMANCE	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD.P	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7		0
REAR VIEW CAMERA (NO)	10		0



## IMAGES




## WHEEL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	AVERAGE	0
SPARE TYRE (YES)	6		0
WHEEL ASSEMBLY	6		0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	FAIR	0
RH APRON	6	FAIR	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	TOP	0
ENGINE OIL	6	AVERAGE	0
COOLANT LEVEL	6	TOP	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	FAIR	0
EXHAUST SYSTEM	6	FAIR	0

 IMAGES



Ordered by: Vivek Chaturvedi | Inspected date: 2018-08-23

Order Id: 21919

Overall Score



6/10



40,75,007

## EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
FRONT BUMPER	6	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	6	FAIR	0
TURN SIGNAL	6	GOOD	0
FOG LAMPS	6	NA	0
HOOD	6	GOOD	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
SIDE VIEW MIRRORS	6	GOOD	0
LH FENDER	6	MINOR SCRATCH	0
LH FRONT DOOR	6	FAIR	0
LH REAR DOOR	6	FAIR	0
LH RUNNING BOARD	6	MINOR SCRATCH	0
LH QUARTER PANEL	6	FAIR	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
REAR BUMPER	6	MINOR SCARACH	0
TAIL LIGHT	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH QUARTER PANEL	6	GOOD	0
RH RUNNING BOARD	6	MINOR SCRATCH	0
RH REAR DOOR	6	GOOD	0

Ordered by: Vivek Chaturvedi | Inspected date: 2018-08-23

Order Id: 21919

Overall Score



6/10



40,75,007



## EXTERIOR (CONTINUED)







6/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	GOOD	0
RH FENDER	7	MINOR SCRATCH	0
BODY RUST	6	MINOR	0
ROOF (SUN ROOF)	6		0
PAINT CONDITION	6	GOOD	0



## IMAGES



## DOCUMENTS



## DESCRIPTION

1 car new 2 tyre good condition 3 minor scratch



Ordered by: Vivek Chaturvedi | Inspected date: 2018-08-23

Order Id: 21919

Overall Score




6/10



40,75,007

IMAGES



Ordered by: Vivek Chaturvedi | Inspected date: 2018-08-23

Order Id: 21919

Overall Score



6/10



40,75,007

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.