

ECO INSPECTION REPORT

Premium

Order ID : 20873

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Bhaskarrao Gurindapalli	Inspection Date : 2018-07-25	Valid Till : 2018-10-25
---	---------------------------------	----------------------------

10/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 1 Year Vehicle Age
- ✓ No Accidental History

Inspected By










 **Sanjay Kumar**

- ✓ Verified Technician
- 7+ vehicle inspected
- 1+ years experience

Mahindra Xuv500 W4, 2017



VEHICLE INFORMATION			
MAKE	MAHINDRA	TRANSMISSION TYPE	MANUAL
MODEL	XUV500	REGISTRATION NO.	MH14GH5007
YEAR	2017	VIN/CHASIS NUMBER	G15018
TRIM	W4	KMS RUN	14412
COLOR	OTHER	INSURANCE EXPIRY	2018-7-20
BODY TYPE	SEDAN	LOCATION	BILLEKAHALLI
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	50,000	 RC COPY AVAILABLE	YES (ORIGINAL)
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	NO
		 BANK NOC	NO













Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

11,61,282



Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND
 Interior	<div style="width: 100%; height: 10px; background-color: green;"></div> 10/10	<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> <div style="text-align: center;">0</div> </div> <div style="display: flex; justify-content: space-around; margin-top: 10px;">  Interior  Wheel  Test Drive  Exterior  Hood </div>
 Wheel	<div style="width: 100%; height: 10px; background-color: green;"></div> 10/10	
 Test Drive	<div style="width: 100%; height: 10px; background-color: green;"></div> 10/10	
 Exterior	<div style="width: 100%; height: 10px; background-color: green;"></div> 10/10	
 Hood	<div style="width: 100%; height: 10px; background-color: green;"></div> 10/10	

Ordered by: Bhaskarrao Gurindapalli | Inspected date: 2018-07-25

Order Id: 20873

Overall Score **10/10**



11,61,282

INTERIOR

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	10		0
DOOR HINGES	10		0
CARPET & FLOOR MAT	10		0
SEAT & SEAT BELT	10		0
DASHBOARD & INSTRUMENT PANEL	10		0
HORN	10		0
SPEAKERS & MUSIC SYSTEM	10		0
HANDBRAKE	10		0
STEERING-MOUNTED CONTROLS	10		0
PEDALS	10		0
CENTRAL LOCK	10		0
A/C VENTS & HEATER	10		0
CUP HOLDERS	10		0
NAVIGATION	10		0
ODOMETER	10		0
POWER WINDOWS (YES)	10		0
HAZARD LIGHT	10		0

IMAGES

NEED ATTENTION



TEST DRIVE

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	10		0
BRAKE PERFORMANCE	10		0
CLUTCH PERFORMANCE	10		0
ENGINE NOISE	10		0
IGNITION SYSTEM	10		0
SUSPENSION PERFORMANCE	10		0
SUSPENSION FRONT SHOCKS	10		0
SUSPENSION REAR SHOCKS	10		0
TRANSMISSION ENGAGE	10		0
CRUISE CONTROL	10		0
REAR PARKING SENSORS	10		0
REAR VIEW CAMERA	10		0



IMAGES



ECO INSPECTION REPORT

Premium

Ordered by: Bhaskarrao Gurindapalli | Inspected date: 2018-07-25

Order Id: 20873

Overall Score



10/10



11,61,282



WHEEL

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	10		0
SPARE TYRE	10		0
WHEEL ASSEMBLY (STEEL RIM)	10		0

IMAGES

NEED ATTENTION



HOOD

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	10		0
RH APRON	10		0
RADIATOR	10		0
WIRING	10		0
BATTERY	10		0
BRAKE FLUID LEVEL	10		0
ENGINE OIL	10		0
COOLANT LEVEL	10		0
BRAKE & COOLANT HOSE PIPES	10		0
UNDERCARRIAGE	10		0
EXHAUST SYSTEM	10		0

IMAGES

NEED ATTENTION



Ordered by: Bhaskarrao Gurindapalli | Inspected date: 2018-07-25

Order Id: 20873

Overall Score **10/10**



11,61,282

EXTERIOR

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	10		0
FRONT BUMPER	10		0
HEAD LIGHTS	10		0
GRILLE	10		0
TURN SIGNAL	10		0
FOG LAMPS	10		0
HOOD	10		0
PILLAR	10		0
FRONT WINDSHIELD	10		0
SIDE VIEW MIRRORS	10		0
LH FENDER	10		0
LH FRONT DOOR	10		0
LH REAR DOOR	10		0
LH RUNNING BOARD	10		0
LH QUARTER PANEL	10		0
FUEL LID	10		0
REAR WINDSHIELD	10		0
REAR BUMPER	10		0
TAIL LIGHT	10		0
TRUNK LID/TAIL GATE	10		0
LUGGAGE COMPARTMENT LIGHT	10		0
RH QUARTER PANEL	10		0
RH RUNNING BOARD	10		0
RH REAR DOOR	10		0

Ordered by: Bhaskarrao Gurindapalli | Inspected date: 2018-07-25

Order Id: 20873

Overall Score 10/10



11,61,282

EXTERIOR (CONTINUED)


10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	10		0
RH FENDER	10		0
BODY RUST	10		0
ROOF (REGULAR)	10		0
PAINT CONDITION	10		0

IMAGES

NEED ATTENTION





DESCRIPTION

all good condition

Ordered by: Bhaskarrao Gurindapalli | Inspected date: 2018-07-25

Order Id: 20873

Overall Score




10/10



11,61,282

IMAGES



Ordered by: Bhaskarrao Gurindapalli | Inspected date: 2018-07-25

Order Id: 20873

Overall Score  10/10



11,61,282

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.