

ECO INSPECTION REPORT

Premium

Order ID : 24782

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Anurag | Inspection Date : 2018-09-30 | Valid Till : 2018-12-30

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 96 does not need attention
- ✓ 2 Owners , 8 Years Vehicle Age
- ✓ No Accidental History

Inspected By

Verified Technician

406+ vehicle inspected
1+ years experience

Santosh Kumar

Fiat Linea Emotion 1.3, 2010



| VEHICLE INFORMATION | | | |
|---------------------|-------------|-------------------|-----------|
| MAKE | FIAT | TRANSMISSION TYPE | MANUAL |
| MODEL | LINEA | REGISTRATION NO. | DL12C3116 |
| YEAR | 2010 | VIN/CHASIS NUMBER | 9016479 |
| TRIM | EMOTION 1.3 | KMS RUN | 98877 |
| COLOR | RED | INSURANCE EXPIRY | 2018-5-17 |
| BODY TYPE | SEDAN | LOCATION | GHAZIABAD |
| FUEL TYPE | DIESEL | ENGINE SOUND LINK | NIL |

| KEY HIGHLIGHTS | | | | | |
|--------------------------|--------|--------------------------|----------------|------------------------|-----------------|
| FLOOD DAMAGE | NO | MAJOR ACCIDENT(S) | NO | SERVICE LOGS AVAILABLE | YES (ONE MONTH) |
| TYRE LIFE REMAINING (KM) | 32,000 | RC COPY AVAILABLE | YES (ORIGINAL) | BANK HYPOTHECATION | NO |
| DENT | YES | INSURANCE COPY AVAILABLE | NO | BANK NOC | NO |

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,55,594

Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

| | | |
|------------|--|--------|
| Interior | | 6 / 10 |
| Wheel | | 6 / 10 |
| Test Drive | | 7 / 10 |
| Exterior | | 5 / 10 |
| Hood | | 5 / 10 |

TOTAL ESTIMATE SPEND 17,300

| | |
|------------|--------|
| Interior | 1,500 |
| Wheel | 0 |
| Test Drive | 0 |
| Exterior | 3,300 |
| Hood | 12,500 |

Ordered by: Anurag | Inspected date: 2018-09-30

Order Id: 24782

Overall Score  **6/10**



2,55,594

INTERIOR

 **6/10**

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|------------------------------|-------------|------------------------|--------------------------|
| DOOR PANEL | 6 | GOOD | 0 |
| DOOR HINGES | 6 | GOOD | 0 |
| CARPET & FLOOR MAT | 6 | GOOD | 0 |
| DASHBOARD & INSTRUMENT PANEL | 6 | GOOD | 0 |
| HORN | 6 | GOOD | 0 |
| SPEAKERS & MUSIC SYSTEM | 6 | GOOD | 0 |
| HANDBRAKE | 6 | GOOD | 0 |
| STEERING-MOUNTED CONTROLS | 6 | GOOD | 0 |
| PEDALS | 6 | GOOD | 0 |
| CENTRAL LOCK | 6 | GOOD | 0 |
| A/C VENTS & HEATER | 6 | GOOD | 0 |
| CUP HOLDERS | 6 | GOOD | 0 |
| ODOMETER | 6 | GOOD | 0 |
| POWER WINDOWS (YES) | 6 | GOOD | 0 |
| HAZARD LIGHT | 6 | GOOD | 0 |
| SEAT & SEAT BELT | 5 | NEED TO BE DRYCLEANING | 1500 |
| NAVIGATION (NO) | 0 | NO | 0 |

IMAGES



Ordered by: Anurag | Inspected date: 2018-09-30

Order Id: 24782

Overall Score **6/10**



2,55,594

TEST DRIVE

7/10

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|---------------------------|-------------|-------------------|--------------------------|
| STEERING PERFORMANCE | 6 | GOOD | 0 |
| BRAKE PERFORMANCE | 6 | GOOD | 0 |
| CLUTCH PERFORMANCE | 6 | GOOD | 0 |
| IGNITION SYSTEM | 6 | GOOD | 0 |
| SUSPENSION PERFORMANCE | 6 | GOOD | 0 |
| SUSPENSION FRONT SHOCKS | 6 | GOOD | 0 |
| SUSPENSION REAR SHOCKS | 6 | GOOD | 0 |
| TRANSMISSION ENGAGE | 6 | GOOD | 0 |
| CRUISE CONTROL (NO) | 10 | | 0 |
| REAR PARKING SENSORS (NO) | 10 | | 0 |
| REAR VIEW CAMERA (NO) | 10 | | 0 |
| ENGINE NOISE | 5 | AVERAGE CANDITION | 0 |

IMAGES




WHEEL

6/10

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|------------------------|-------------|------------------|--------------------------|
| TYRES | 7 | GOOD | 0 |
| SPARE TYRE (YES) | 6 | GOOD | 0 |
| WHEEL ASSEMBLY | 6 | GOOD | 0 |

 IMAGES



 HOOD



5/10

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|----------------------------|-------------|------------------|--------------------------|
| LH APRON | 6 | GOOD | 0 |
| RH APRON | 6 | GOOD | 0 |
| RADIATOR | 6 | GOOD | 0 |
| WIRING | 6 | GOOD | 0 |
| BATTERY | 6 | GOOD | 0 |
| BRAKE FLUID LEVEL | 6 | GOOD | 0 |
| BRAKE & COOLANT HOSE PIPES | 6 | GOOD | 0 |
| UNDERCARRIAGE | 6 | GOOD | 0 |
| ENGINE OIL | 3 | BAD | 2000 |
| COOLANT LEVEL | 4 | BAD | 500 |
| EXHAUST SYSTEM | 5 | BLACK SMOKE | 10000 |

 IMAGES



Ordered by: Anurag | Inspected date: 2018-09-30

Order Id: 24782

Overall Score



6/10



2,55,594

 EXTERIOR



5/10

| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|---------------------------|-------------|---------------------------|--------------------------|
| LICENSE PLATE | 6 | GOOD | 0 |
| HEAD LIGHTS | 6 | GOOD | 0 |
| GRILLE | 6 | GOOD | 0 |
| TURN SIGNAL | 6 | GOOD | 0 |
| FOG LAMPS | 6 | GOOD | 0 |
| PILLAR | 6 | GOOD | 0 |
| REAR WINDSHIELD | 6 | GOOD | 0 |
| LUGGAGE COMPARTMENT LIGHT | 6 | GOOD | 0 |
| BODY RUST | 6 | GOOD | 0 |
| ROOF (REGULAR) | 6 | GOOD | 0 |
| FRONT BUMPER | 5 | PAINTED AND MINOR SCRATCH | 1000 |
| HOOD | 5 | PAINTED | 0 |
| FRONT WINDSHIELD | 4 | ALL READY CHANGE | 0 |
| SIDE VIEW MIRRORS | 5 | PAINTED AND SCRATCH | 500 |
| LH FENDER | 5 | PAINTED | 0 |
| LH FRONT DOOR | 5 | PAINTED | 0 |
| LH REAR DOOR | 5 | PAINTED | 0 |
| LH RUNNING BOARD | 5 | PAINTED | 0 |
| LH QUARTER PANEL | 5 | PAINTED | 0 |
| FUEL LID | 5 | PAINTED | 0 |
| REAR BUMPER | 5 | PAINTED | 0 |
| TAIL LIGHT | 4 | BAD CANDITION | 1800 |
| TRUNK LID/TAIL GATE | 4 | PAINTED AND DENT | 0 |
| RH QUARTER PANEL | 5 | PAINTED | 0 |

Ordered by: Anurag | Inspected date: 2018-09-30

Order Id: 24782

Overall Score



6/10



2,55,594



EXTERIOR (CONTINUED)



5/10






| INSPECTION CHECKPOINTS | SCORE(X/10) | REMARKS/COMMENTS | OPTIONAL SPEND EST. (RS) |
|------------------------|-------------|--------------------|--------------------------|
| RH RUNNING BOARD | 5 | PAINTED | 0 |
| RH REAR DOOR | 5 | PAINTED | 0 |
| RH FRONT DOOR | 5 | PAINTED | 0 |
| RH FENDER | 5 | PAINTED | 0 |
| PAINT CONDITION | 5 | ALL CAR IS PAINTED | 0 |



IMAGES




NEED ATTENTION





 **DOCUMENTS**



 **DESCRIPTION**

all car is painted without roof rear camera is available frant windshield is all ready change smal

Ordered by: Anurag | Inspected date: 2018-09-30

Order Id: 24782

Overall Score






6/10



2,55,594

IMAGES





Ordered by: Anurag | Inspected date: 2018-09-30

Order Id: 24782

Overall Score



6/10



2,55,594

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.