



ECO INSPECTION CERTIFICATE

Premium

Order ID : 28385

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Hitesh	Inspection Date : 2018-10-23	Valid Till : 2019-01-23	 Inspected By  Gagan Gurawaliya
<h2>8/10</h2> <p>Overall Score</p>		<ul style="list-style-type: none"> ✓ Evaluated across 5 segments ✓ Covered 121+ checkpoints ✓ 116 does not need attention ✓ 1 Owner , 6 Years Vehicle Age ✓ No Accidental History 	
		<ul style="list-style-type: none"> ✓ Verified Technician 127+ vehicle inspected 1+ years experience 	









Land Rover Freelander 2 SD4 HSE, 2012



VEHICLE INFORMATION

MAKE	LAND ROVER	TRANSMISSION TYPE	MANUAL
MODEL	FREELANDER 2	REGISTRATION NO.	HR26BV8199
YEAR	2012	VIN/CHASIS NUMBER	910009
TRIM	SD4 HSE	KMS RUN	76419
COLOR	SILVER	INSURANCE EXPIRY	2018-11-21
BODY TYPE	SUV	LOCATION	ICON DLF5
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (ONE MONTH)
 TYRE LIFE REMAINING (KM)	40,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

18,37,658




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%;"></div>	8 / 10
 Wheel	<div style="width: 80%;"></div>	8 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 88,000



Ordered by: Hitesh | Inspected date: 2018-10-23

Order Id: 28385

Overall Score



8/10



18,37,658



INTERIOR





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD	0
DOOR HINGES	8	GOOD	0
CARPET & FLOOR MAT	8	GOOD	0
SEAT & SEAT BELT	8	GOOD	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD	0
HORN	8	GOOD	0
SPEAKERS & MUSIC SYSTEM	8	GOOD	0
HANDBRAKE	8	GOOD	0
STEERING-MOUNTED CONTROLS	8	GOOD	0
PEDALS	8	GOOD	0
CENTRAL LOCK	8	GOOD	0
A/C VENTS & HEATER	8	GOOD	0
CUP HOLDERS	8	GOOD	0
ODOMETER	8	GOOD	0
HAZARD LIGHT	8	GOOD	0



IMAGES



Ordered by: Hitesh | Inspected date: 2018-10-23

Order Id: 28385

Overall Score **8/10**



18,37,658

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD	0
BRAKE PERFORMANCE	8	GOOD	0
CLUTCH PERFORMANCE	8	GOOD	0
ENGINE NOISE	8	GOOD	0
IGNITION SYSTEM	8	GOOD	0
SUSPENSION PERFORMANCE	8	GOOD	0
SUSPENSION FRONT SHOCKS	8	GOOD	0
SUSPENSION REAR SHOCKS	8	GOOD	0
TRANSMISSION ENGAGE	8	GOOD	0

IMAGES



WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0

 IMAGES



 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD	0
RH APRON	8	GOOD	0
RADIATOR	8	GOOD	0
WIRING	8	GOOD	0
BATTERY	8	GOOD	0
BRAKE FLUID LEVEL	8	GOOD	0
ENGINE OIL	8	GOOD	0
COOLANT LEVEL	8	GOOD	0
BRAKE & COOLANT HOSE PIPES	8	GOOD	0
UNDERCARRIAGE	8	GOOD	0
EXHAUST SYSTEM	8	GOOD	0

 IMAGES



Ordered by: Hitesh | Inspected date: 2018-10-23

Order Id: 28385

Overall Score  **8/10**



18,37,658

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD	0
HEAD LIGHTS	7	IF NEED TO REPLACE	18000
GRILLE	8	GOOD	0
TURN SIGNAL	8	GOOD	0
FOG LAMPS	8	GOOD	0
HOOD	8	GOOD	0
PILLAR	8	GOOD	0
FRONT WINDSHIELD	8	GOOD	0
LH FENDER	8	GOOD	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	8	GOOD	0
LH RUNNING BOARD	8	GOOD	0
LH QUARTER PANEL	8	GOOD	0
FUEL LID	8	GOOD	0
REAR WINDSHIELD	8	GOOD	0
TAIL LIGHT	8	GOOD	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD	0
RH QUARTER PANEL	8	GOOD	0
RH RUNNING BOARD	8	GOOD	0
RH REAR DOOR	7	GOOD	0
RH FRONT DOOR	7	GOOD	0
BODY RUST	8	GOOD	0
PAINT CONDITION	8	GOOD	0
FRONT BUMPER	5	NEED TO REPAIR OTHERWISE REPLACE	20000

Ordered by: Hitesh | Inspected date: 2018-10-23

Order Id: 28385

Overall Score



8/10



18,37,658



EXTERIOR (CONTINUED)





7/10





INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SIDE VIEW MIRRORS	5	NEED TO REPAIR	5000
REAR BUMPER	5	NEED TO REPAIR	15000
TRUNK LID/TAIL GATE	5	NEED TO REPAIR	18000
RH FENDER	5	NEED TO REPAIR	12000



IMAGES



NEED ATTENTION



Ordered by: Hitesh | Inspected date: 2018-10-23

Order Id: 28385

Overall Score




8/10



18,37,658



DOCUMENTS



DESCRIPTION

minor scratches all tyres are already changed dent on the fender and backdoor

Ordered by: Hitesh | Inspected date: 2018-10-23

Order Id: 28385

Overall Score




8/10



18,37,658

IMAGES



Ordered by: Hitesh | Inspected date: 2018-10-23

Order Id: 28385

Overall Score



8/10



18,37,658

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.