

ECO INSPECTION CERTIFICATE

Premium

Order ID : 29730

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Anshuman

Inspection Date :
2018-11-05

Valid Till :
2019-02-05

8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Manoj Kumar

- ✓ Verified Technician
- 140+ vehicle inspected
- 1+ years experience

Fiat Linea Active T-Jet, 2016



VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	LINEA	REGISTRATION NO.	HR26DC1108
YEAR	2016	VIN/CHASIS NUMBER	040356
TRIM	ACTIVE T-JET	KMS RUN	17282
COLOR	GREY	INSURANCE EXPIRY	2019-3-15
BODY TYPE	OTHER	LOCATION	GGN
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (FULL)
TYRE LIFE REMAINING (KM)	45,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

4,97,634




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 30,000



Ordered by: Anshuman | Inspected date: 2018-11-05

Order Id: 29730

Overall Score



8/10



4,97,634



INTERIOR





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD	0
DOOR HINGES	8	GOOD	0
CARPET & FLOOR MAT	8	GOOD	0
SEAT & SEAT BELT	8	GOOD	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD	0
HORN	8	GOOD	0
SPEAKERS & MUSIC SYSTEM	8	GOOD	0
HANDBRAKE	8	GOOD	0
STEERING-MOUNTED CONTROLS	8	GOOD	0
PEDALS	8	GOOD	0
CENTRAL LOCK	8	GOOD	0
A/C VENTS & HEATER	9	GOOD	0
CUP HOLDERS	8	GOOD	0
ODOMETER	8	GOOD	0
HAZARD LIGHT	8	GOOD	0



IMAGES



Ordered by: Anshuman | Inspected date: 2018-11-05

Order Id: 29730

Overall Score **8/10**



4,97,634

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD	0
BRAKE PERFORMANCE	8	GOOD	0
CLUTCH PERFORMANCE	8	GOOD	0
ENGINE NOISE	8	GOOD	0
IGNITION SYSTEM	8	GOOD	0
SUSPENSION PERFORMANCE	8	GOOD	0
SUSPENSION FRONT SHOCKS	8	GOOD	0
SUSPENSION REAR SHOCKS	8	GOOD	0
TRANSMISSION ENGAGE	8	GOOD	0

IMAGES




WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD	0
RH APRON	8	GOOD	0
RADIATOR	8	GOOD	0
WIRING	8	GOOD	0
BATTERY	8	GOOD	0
BRAKE FLUID LEVEL	8	GOOD	0
ENGINE OIL	8	GOOD	0
COOLANT LEVEL	8	GOOD	0
BRAKE & COOLANT HOSE PIPES	8	GOOD	0
UNDERCARRIAGE	8	GOOD	0
EXHAUST SYSTEM	8	GOOD	0

 IMAGES



Ordered by: Anshuman | Inspected date: 2018-11-05

Order Id: 29730

Overall Score **8/10**



4,97,634

 **EXTERIOR**

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD	0
HEAD LIGHTS	8	GOOD	0
GRILLE	8	GOOD	0
TURN SIGNAL	8	GOOD	0
FOG LAMPS	8	GOOD	0
PILLAR	8	GOOD	0
FRONT WINDSHIELD	8	GOOD	0
SIDE VIEW MIRRORS	8	GOOD	0
LH FENDER	8	GOOD	0
LH FRONT DOOR	8	GOOD	0
LH RUNNING BOARD	8	GOOD	0
LH QUARTER PANEL	8	GOOD	0
FUEL LID	8	GOOD	0
REAR WINDSHIELD	8	GOOD	0
REAR BUMPER	8	GOOD	0
TAIL LIGHT	8	GOOD	0
TRUNK LID/TAIL GATE	8	GOOD	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD	0
RH QUARTER PANEL	8	GOOD	0
RH RUNNING BOARD	8	GOOD	0
RH REAR DOOR	8	GOOD	0
RH FRONT DOOR	8	GOOD	0
RH FENDER	8	GOOD	0
BODY RUST	8	GOOD	0

Ordered by: Anshuman | Inspected date: 2018-11-05

Order Id: 29730

Overall Score



8/10



4,97,634



EXTERIOR (CONTINUED)




7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
PAINT CONDITION	8	GOOD	0
FRONT BUMPER	2	NEED TO REPAIR	10000
HOOD	1	NEED TO REPAIR	10000
LH REAR DOOR	5	NEED TO REPAIR	10000



IMAGES



DOCUMENTS



DESCRIPTION

minor scratches minor dent

Ordered by: Anshuman | Inspected date: 2018-11-05

Order Id: 29730

Overall Score




8/10



4,97,634

IMAGES



Ordered by: Anshuman | Inspected date: 2018-11-05

Order Id: 29730

Overall Score



8/10



4,97,634

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.