

ECO INSPECTION CERTIFICATE

Premium

Order ID : 30293

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
NEERAJ

Inspection Date :
2018-11-11

Valid Till :
2019-02-11

6/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 107 does not need attention
- ✓ 1 Owner , 14 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Tej Pratap
Yadav

- ✓ Verified Technician
- 34+ vehicle inspected
- 1+ years experience

Bajaj Ct 100 100CC, 2004



VEHICLE INFORMATION

MAKE	BAJAJ	LOCATION	DELHI
MODEL	CT 100	REGISTRATION NO.	DL7SAJ2373
YEAR	2004	VIN/CHASIS NUMBER	01508
TRIM	100CC	KMS RUN	3000
COLOR	OTHER	INSURANCE EXPIRY	2017-7-12
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (PARTIAL)
TYRE LIFE REMAINING (KM)	5,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

12,618




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	<div style="width: 60%;"></div>	6 / 10
Control	<div style="width: 50%;"></div>	5 / 10
Light	<div style="width: 50%;"></div>	5 / 10
Oil	<div style="width: 60%;"></div>	6 / 10
Chassis	<div style="width: 60%;"></div>	6 / 10
Stand	<div style="width: 50%;"></div>	5 / 10

TOTAL ESTIMATE SPEND 10,800



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: NEERAJ | Inspected date: 2018-11-11

Order Id: 30293

Overall Score



6/10



12,618



TYRE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	6	GOOD	0
REAR TYRE CONDITION & AIR PRESSURE	6	GOOD	0
WHEEL SPOKES FRONT	6	GOOD	0
WHEEL SPOKES REAR	6	GOOD	0
WHEEL RIM REAR	6	GOOD	0
WHEEL BEARINGS FRONT	6	GOOD	0
WHEEL BEARINGS REAR	6	GOOD	0
WHEEL SEALS FRONT	6	GOOD	0
WHEEL SEALS REAR	6	GOOD	0
BRAKE FUNCTION FRONT	6	GOOD	0
BRAKE FUNCTION REAR	6	GOOD	0
BRAKES CONDITION FRONT	6	GOOD	0
BRAKES CONDITION REAR	6	GOOD	0
WHEEL RIM FRONT	4	RUSTED NEED TO BE CHANGE	5000

IMAGES





www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: NEERAJ | Inspected date: 2018-11-11

Order Id: 30293

Overall Score  **6/10**




12,618

STAND

 **5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND RETENTION	6	GOOD	0
SIDE STAND RETENTION	6	GOOD	0
CENTRE STAND CONDITION	3	RUSTED NEED TO BE CHANGE	500
SIDE STAND CONDITION	4	RUSTED NEED TO BE CHANGE	500

IMAGES




CONTROL

 **5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	6	GOOD	0
CABLES CONDITION	6	GOOD	0
CABLES ROUTING	6	GOOD	0
HOSES CONDITION	6	GOOD	0
HOSES ROUTING	6	GOOD	0
THROTTLE OPERATION	6	GOOD	0
LEVERS & PEDAL CONDITION	4	RUSTED NEED TO BE REPAIR	200
PIVOTS	3	EUSTED AND LUSE	200

IMAGES



OIL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6	GOOD	0
LEVELS - GEAR OIL/SHAFT DRIVE	6	GOOD	0
LEVELS - FUEL	6	GOOD	0
LEAKS - ENGINE OIL	6	GOOD	0
LEAKS - GEAR OIL	6	GOOD	0
LEAKS - FUEL	6	GOOD	0
LEAKS - HYDRAULIC FLUID	0	NA	0
LEAKS - COOLANT	0	NA	0

IMAGES



Ordered by: NEERAJ | Inspected date: 2018-11-11

Order Id: 30293

Overall Score



6/10



12,618

LIGHT



5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY VENT TUBE	6	GOOD	0
HEADLAMP CONDITION	6	GOOD	0
TAILLAMP/BRAKELAMP CONDITION	6	GOOD	0
SWITCHES OPERATION	6	GOOD	0
MIRRORS CONDITION	6	NA VEHICLE	500
MIRRORS AIM	6	GOOD	0
LENSES & REFLECTORS CONDITION	6	GOOD	0
WIRING ROUTING	6	GOOD	0
BATTERY CONDITION	2	DISCHARGE	1000
TAILLAMP/BRAKELAMP OPERATION	3	NOT WORKING NEED TO BE REPAIR	500
TURN SIGNALS OPERATION FRONT LEFT	3	NA VEHICLE	100
TURN SIGNALS OPERATION FRONT RIGHT	3	NOT WORKING	100
TURN SIGNALS OPERATION REAR LEFT	3	NOT WORKING	100
TURN SIGNALS OPERATION REAR RIGHT	3	NOT WORKING	100
WIRING CONDITION	3	ALL WIRING OPEN NEED TO BE REPAIE	2000

IMAGES



Ordered by: NEERAJ | Inspected date: 2018-11-11

Order Id: 30293

Overall Score  **6/10**




12,618

CHASSIS

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6	GOOD	0
FRAME STEERING-HEAD BEARINGS	6	GOOD	0
FRAME SWINGARM BUSHINGS	6	GOOD	0
SUSPENSION FRONT FORKS LEFT	6	GOOD	0
SUSPENSION FRONT FORKS RIGHT	6	GOOD	0
SUSPENSION REAR SHOCKS LEFT	6	GOOD	0
SUSPENSION REAR SHOCKS RIGHT	6	GOOD	0
CHAIN/BELT TENSION	6	GOOD	0
CHAIN/BELT LUBRICATION	6	GOOD	0
CHAIN/BELT SPROCKETS	6	GOOD	0
FASTENERS THREADED	6	GOOD	0
FASTENERS CLIPS & COTTER PINS	6	GOOD	0
ENGINE	6	GOOD	0
TRANSMISSION	6	GOOD	0

IMAGES



Ordered by: NEERAJ | Inspected date: 2018-11-11

Order Id: 30293

Overall Score



6/10



12,618



DOCUMENTS



DESCRIPTION

front Rim registered all wire open all indicator not working rear break light not working fuel t

Ordered by: NEERAJ | Inspected date: 2018-11-11

Order Id: 30293

Overall Score




6/10



12,618

IMAGES



Ordered by: NEERAJ | Inspected date: 2018-11-11

Order Id: 30293

Overall Score



6/10



12,618

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.