



ECO INSPECTION CERTIFICATE

Premium

Order ID : 30595

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ganesh	Inspection Date : 2018-11-15	Valid Till : 2019-02-15	 Inspected By  Tata Uday Kumar ✓ Verified Technician 11+ vehicle inspected 1+ years experience
------------------------	---------------------------------	----------------------------	--

9/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 4 Years Vehicle Age
- ✓ No Accidental History




Fiat Linea 1.4 T-JET EMOTION, 2014



VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	LINEA	REGISTRATION NO.	MH14EH9284
YEAR	2014	VIN/CHASIS NUMBER	MCA110HD20903460Z
TRIM	1.4 T-JET EMOTION	KMS RUN	35917
COLOR	RED	INSURANCE EXPIRY	2019-9-12
BODY TYPE	SEDAN	LOCATION	HYDERABAD
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	5,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

4,95,316




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 100%; background-color: green;"></div>	10 / 10
 Wheel	<div style="width: 70%; background-color: green;"></div>	7 / 10
 Test Drive	<div style="width: 100%; background-color: green;"></div>	10 / 10
 Exterior	<div style="width: 100%; background-color: green;"></div>	10 / 10
 Hood	<div style="width: 100%; background-color: green;"></div>	10 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Ganesh | Inspected date: 2018-11-15

Order Id: 30595

Overall Score



9/10



4,95,316



INTERIOR







10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	10		0
DOOR HINGES	10	GOOD	0
CARPET & FLOOR MAT	9	GOOD	0
SEAT & SEAT BELT	9	GOOD	0
DASHBOARD & INSTRUMENT PANEL	9		0
HORN	10	GOOD	0
SPEAKERS & MUSIC SYSTEM	9	GOOD	0
HANDBRAKE	10	GOOD	0
STEERING-MOUNTED CONTROLS	10	GOOD	0
PEDALS	9	GOOD	0
CENTRAL LOCK	9	GOOD	0
A/C VENTS & HEATER	10	GOOD	0
CUP HOLDERS	10	GOOD	0
ODOMETER	10		0
HAZARD LIGHT	10		0



IMAGES



Ordered by: Ganesh | Inspected date: 2018-11-15

Order Id: 30595

Overall Score **9/10**




4,95,316

TEST DRIVE

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	10	GOOD	0
BRAKE PERFORMANCE	9	GOOD	0
CLUTCH PERFORMANCE	10	GOOD	0
ENGINE NOISE	10	GOOD	0
IGNITION SYSTEM	10	GOOD	0
SUSPENSION PERFORMANCE	10		0
SUSPENSION FRONT SHOCKS	10		0
SUSPENSION REAR SHOCKS	10		0
TRANSMISSION ENGAGE	10		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0

 IMAGES




 HOOD

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	9		0
RH APRON	10		0
RADIATOR	10	GOOD	0
WIRING	10	GOOD	0
BATTERY	10		0
BRAKE FLUID LEVEL	10	GOOD	0
ENGINE OIL	10	GOOD	0
COOLANT LEVEL	10	GOOD	0
BRAKE & COOLANT HOSE PIPES	10	GOOD	0
UNDERCARRIAGE	9	GOOD	0
EXHAUST SYSTEM	10	GOOD	0

 IMAGES



Ordered by: Ganesh | Inspected date: 2018-11-15

Order Id: 30595

Overall Score



9/10



4,95,316

 EXTERIOR



10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	9		0
FRONT BUMPER	9		0
HEAD LIGHTS	9		0
GRILLE	9		0
TURN SIGNAL	9		0
FOG LAMPS	10		0
HOOD	10		0
PILLAR	9		0
FRONT WINDSHIELD	9		0
SIDE VIEW MIRRORS	9		0
LH FENDER	10		0
LH FRONT DOOR	10		0
LH REAR DOOR	10		0
LH RUNNING BOARD	10		0
LH QUARTER PANEL	10		0
FUEL LID	9		0
REAR WINDSHIELD	10		0
REAR BUMPER	9		0
TAIL LIGHT	10		0
TRUNK LID/TAIL GATE	10		0
LUGGAGE COMPARTMENT LIGHT	10		0
RH QUARTER PANEL	10		0
RH RUNNING BOARD	10		0
RH REAR DOOR	9		0

Ordered by: Ganesh | Inspected date: 2018-11-15

Order Id: 30595

Overall Score **9/10**




4,95,316












EXTERIOR (CONTINUED)

10/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	10		0
RH FENDER	10		0
BODY RUST	10		0
PAINT CONDITION	9		0

IMAGES





 DOCUMENTS



 DESCRIPTION

good

Ordered by: Ganesh | Inspected date: 2018-11-15

Order Id: 30595

Overall Score





















9/10



4,95,316

IMAGES





Ordered by: Ganesh | Inspected date: 2018-11-15

Order Id: 30595

Overall Score



9/10



4,95,316

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.