

ECO INSPECTION CERTIFICATE

Premium

Order ID : 30825

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Prabh	Inspection Date : 2018-11-19	Valid Till : 2019-02-20
-----------------------	---------------------------------	----------------------------

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **118** does not need attention
- ✔ **1** Owner , **10** Years Vehicle Age
- ✔ No Accidental History

Inspected By

Verified Technician
65+ vehicle inspected
1+ years experience

Pawan Kumar
Gupta

Volkswagen Passat HIGHLINE DSG S, 2008



VEHICLE INFORMATION

MAKE	VOLKSWAGEN	TRANSMISSION TYPE	MANUAL
MODEL	PASSAT	REGISTRATION NO.	CH04F6602
YEAR	2008	VIN/CHASIS NUMBER	00614
TRIM	HIGHLINE DSG S	KMS RUN	88433
COLOR	BLACK	INSURANCE EXPIRY	2018-9-1
BODY TYPE	OTHER	LOCATION	CHANDIGARH
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	2,000	RC COPY AVAILABLE	NO	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

6,73,644




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Wheel	<div style="width: 70%; background-color: green;"></div>	7 / 10
Test Drive	<div style="width: 80%; background-color: green;"></div>	8 / 10
Exterior	<div style="width: 60%; background-color: yellow;"></div>	6 / 10
Hood	<div style="width: 70%; background-color: green;"></div>	7 / 10

TOTAL ESTIMATE SPEND **12,000**



Ordered by: prabh | Inspected date: 2018-11-19

Order Id: 30825

Overall Score  **7/10**



6,73,644

INTERIOR

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	6		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	6		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	6		0

IMAGES



Ordered by: prabh | Inspected date: 2018-11-19

Order Id: 30825

Overall Score **7/10**



6,73,644

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6		0
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY	6		0

 IMAGES



 HOOD




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	6		0
WIRING	7		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	7		0
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	6		0

 IMAGES





Ordered by: prabh | Inspected date: 2018-11-19

Order Id: 30825

Overall Score  **7/10**



6,73,644

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	6		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	6		0
LH FENDER	7		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	6		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	6		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	6		0
RH FRONT DOOR	6	MINOR SCRATHES	0
RH FENDER	6		0
BODY RUST	7		0

Ordered by: prabh | Inspected date: 2018-11-19

Order Id: 30825

Overall Score **7/10**




6,73,644

EXTERIOR (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	6		0
PAINT CONDITION	6		0
FOG LAMPS	0	NOT FITTED	5000
RH RUNNING BOARD	5	SCRATHES AND DENTS	5000
RH REAR DOOR	5	SCRATHES	2000

IMAGES





 DESCRIPTION

good

Ordered by: prabh | Inspected date: 2018-11-19

Order Id: 30825

Overall Score





7/10



6,73,644

IMAGES





Ordered by: prabh | Inspected date: 2018-11-19

Order Id: 30825

Overall Score



7/10



6,73,644

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.