

ECO INSPECTION REPORT Premium

Order ID : 19060

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered by : Manish Sharma | Inspection Date : 2018-02-05

9/10

Overall Score

- ✓ Evaluated across **6** segments
- ✓ Covered **121+** checkpoints
- ✓ **118** does not need attention
- ✓ **1** owner , **2** Years Vehicle Age
- ✓ No Accidental History

Inspected By




✓ **Verified Technician**

352+ vehicle inspected

1+ years experience

Jetendra Singh


Harley Davidson Street 750 750cc, 2016



VEHICLE INFORMATION

MAKE	HARLEY DAVIDSON	LOCATION	GURGAON
MODEL	STREET 750	REGISTRATION NO	DL 8SBC9538
YEAR	2016	VIN/CHASIS NUMBER	504378
TRIM	750CC	KMS RUN	2707
COLOR	BLACK	INSURANCE EXPIRY	2018-1-18
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY OBSERVATIONS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	15,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.







With this evaluation, the Fair Market Value for this vehicle comes to be:

4,74,139





Very Good Condition


ECO SCORE


 Tyre	<div style="width: 90%; background-color: green;"></div>	9 / 10
 Control	<div style="width: 90%; background-color: green;"></div>	9 / 10
 Light	<div style="width: 90%; background-color: green;"></div>	9 / 10
 Oil	<div style="width: 90%; background-color: green;"></div>	9 / 10
 Chassis	<div style="width: 90%; background-color: green;"></div>	9 / 10
 Stand	<div style="width: 90%; background-color: green;"></div>	9 / 10


TOTAL ESTIMATE SPEND 0


0


0


0


0


0


0


Ordered by: Manish Sharma | Inspected date: 2018-02-05

Order Id: 19060

Overall Score **9/10**



4,74,139

DOES NOT NEED ATTENTION

NEED ATTENTION

TYRE

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
FRONT TYRE CONDITION & AIR PRESSURE	9		0
REAR TYRE CONDITION & AIR PRESSURE	9		0
WHEELS SPOKES FRONT	9		0
WHEELS SPOKES REAR	9		0
WHEELS RIMS FRONT	9		0
WHEELS RIMS REAR	9		0
WHEELS BEARINGS FRONT	9		0
WHEELS BEARINGS REAR	9		0
WHEELS SEALS FRONT	9		0
WHEELS SEALS REAR	9		0
BRAKE FUNCTION FRONT	9		0
BRAKE FUNCTION REAR	9		0
BRAKES CONDITION FRONT	9		0
BRAKES CONDITION REAR	9		0

STAND

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
SIDE STAND CONDITION	9		0
SIDE STAND RETENTION	9		0
CENTRE STAND CONDITION	0	N/A	0
CENTRE STAND RETENTION	0	N/A	0

Ordered by: Manish Sharma | Inspected date: 2018-02-05

Order Id: 19060

Overall Score **9/10**



4,74,139

DOES NOT NEED ATTENTION

NEED ATTENTION



CONTROL



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
HANDLEBARS CONDITION	9		0
LEVERS & PEDAL CONDITION	9		0
PIVOTS	8		0
CABLES CONDITION	9		0
CABLES ROUTING	9		0
HOSES CONDITION	8		0
HOSES ROUTING	9		0
THROTTLE OPERATION	9		0



OIL



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LEVELS - ENGINE OIL	9		0
LEVELS - GEAR OIL/SHAFT DRIVE	9		0
LEVELS - HYDRAULIC FLUID	9		0
LEVELS - COOLANT	8		0
LEVELS - FUEL	9		0
LEAKS - ENGINE OIL	9		0
LEAKS - GEAR OIL	9		0
LEAKS - HYDRAULIC FLUID	9		0
LEAKS - COOLANT	9		0
LEAKS - FUEL	9		0
ENGINE SOUND	0		0

Ordered by: Manish Sharma | Inspected date: 2018-02-05

Order Id: 19060

Overall Score **9/10**



4,74,139

DOES NOT NEED ATTENTION

NEED ATTENTION

 LIGHT

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BATTERY CONDITION	9		0
BATTERY VENT TUBE	9		0
HEADLAMP CONDITION	9		0
TAILLAMP/BRAKELAMP CONDITION	9		0
TAILLAMP/BRAKELAMP OPERATION	9		0
TURN SIGNALS OPERATION FRONT LEFT	9		0
TURN SIGNALS OPERATION FRONT RIGHT	9		0
TURN SIGNALS OPERATION REAR LEFT	9		0
TURN SIGNALS OPERATION REAR RIGHT	9		0
SWITCHES OPERATION	9		0
MIRRORS CONDITION	9		0
MIRRORS AIM	9		0
LENSES & REFLECTORS CONDITION	9		0
WIRING CONDITION	9		0
WIRING ROUTING	9		0

Ordered by: Manish Sharma | Inspected date: 2018-02-05

Order Id: 19060

Overall Score **9/10**



4,74,139

DOES NOT NEED ATTENTION

NEED ATTENTION



CHASSIS



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
FRAME CONDITION	9		0
FRAME STEERING-HEAD BEARINGS	9		0
FRAME SWINGARM BUSHINGS	9		0
SUSPENSION FRONT FORKS LEFT	9		0
SUSPENSION FRONT FORKS RIGHT	9		0
SUSPENSION REAR SHOCKS LEFT	9		0
SUSPENSION REAR SHOCKS RIGHT	9		0
CHAIN/BELT TENSION	9		0
CHAIN/BELT LUBRICATION	8		0
CHAIN/BELT SPROCKETS	9		0
FASTENERS THREADED	9		0
FASTENERS CLIPS & COTTER PINS	9		0
ENGINE	9		0
TRANSMISSION	9		0



DESCRIPTION

Good

Ordered by: Manish Sharma | Inspected date: 2018-02-05

Order Id: 19060

Overall Score



9/10









4,74,139

DOES NOT NEED ATTENTION

NEED ATTENTION

IMAGES



Ordered by: Manish Sharma | Inspected date: 2018-02-05

Order Id: 19060

Overall Score



9/10



4,74,139

DOES NOT NEED ATTENTION

NEED ATTENTION



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.