

ECO INSPECTION CERTIFICATE

Premium

Order ID : 36444

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Akshay	Inspection Date : 2018-12-27	Valid Till : 2019-03-27	Inspected By Hemant Kumar
------------------------	---------------------------------	----------------------------	----------------------------------

7/10
Overall Score

- Evaluated across 5 segments
- Covered 121+ checkpoints
- 121 does not need attention
- 2 Owners , 1 Year Vehicle Age
- No Accidental History

Verified Technician
131+ vehicle inspected
1+ years experience

Ford Endeavour TITANIUM 3.2 4X4 AT, 2017



VEHICLE INFORMATION

MAKE	FORD	TRANSMISSION TYPE	AUTOMATIC
MODEL	ENDEAVOUR	REGISTRATION NO.	HR26DB5159
YEAR	2017	VIN/CHASIS NUMBER	55300
TRIM	TITANIUM 3.2 4X4 AT	KMS RUN	20478
COLOR	RED	INSURANCE EXPIRY	2018-12-6
BODY TYPE	SUV	LOCATION	DELHI
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (PARTIAL)
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

28,29,697




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Akshay | Inspected date: 2018-12-27

Order Id: 36444

Overall Score



7/10



28,29,697



INTERIOR





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	8	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	8	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	8	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	8	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (YES)	8	GOOD	0
ODOMETER	8	GOOD	0
POWER WINDOWS (YES)	8	GOOD	0
HAZARD LIGHT	8	GOOD	0



IMAGES



Ordered by: Akshay | Inspected date: 2018-12-27

Order Id: 36444

Overall Score **7/10**



28,29,697

NEED ATTENTION ⚠️



TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	8	GOOD	0
SUSPENSION PERFORMANCE	8	GOOD	0
SUSPENSION FRONT SHOCKS	8	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	8	GOOD	0
CRUISE CONTROL (YES)	7	GOOD	0
REAR PARKING SENSORS (YES)	8	GOOF	0
REAR VIEW CAMERA (YES)	8	GOOD	0

IMAGES



Ordered by: Akshay | Inspected date: 2018-12-27

Order Id: 36444

Overall Score **7/10**



28,29,697

WHEEL


7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	FAIR CONDITION	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD	0

IMAGES



NEED ATTENTION ⚠️




HOOD

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD	0
RH APRON	8	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	6	FAIR CONDITION	0
BRAKE FLUID LEVEL	7	GOOD	0

ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

IMAGES



NEED ATTENTION



Ordered by: Akshay | Inspected date: 2018-12-27

Order Id: 36444

Overall Score



7/10



28,29,697

 EXTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	7	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	7	GOOD	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
REAR BUMPER	7	GOOD	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	8	GOOD	0
RH REAR DOOR	8	GOOD	0

Ordered by: Akshay | Inspected date: 2018-12-27

Order Id: 36444

Overall Score **7/10**




28,29,697

EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	GOOD	0
RH FENDER	7	GOOD	0
BODY RUST	8	GOOD	0
ROOF (SUN ROOF)	7	GOOD	0
PAINT CONDITION	8	GOOD	0

IMAGES



NEED ATTENTION ⚠





 DOCUMENTS



 DESCRIPTION

minor scratches in body rear tyre weak overall good condition

Ordered by: Akshay | Inspected date: 2018-12-27

Order Id: 36444

Overall Score









7/10



28,29,697

 IMAGES





Ordered by: Akshay | Inspected date: 2018-12-27

Order Id: 36444

Overall Score



7/10



28,29,697

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.