

ECO INSPECTION CERTIFICATE

Premium

Order ID : 36786

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Adit	Inspection Date : 2018-12-31	Valid Till : 2019-04-02
----------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **104** does not need attention
- ✔ **1** Owner , **10** Years Vehicle Age
- ✔ No Accidental History

Inspected By



Tej Pratap Yadav

- ✔ **Verified Technician**
- 142+ vehicle inspected
- 1+ years experience



Fiat Punto EMOTION 1.4, 2009



VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	PUNTO	REGISTRATION NO.	DL7CK4063
YEAR	2009	VIN/CHASIS NUMBER	006335
TRIM	EMOTION 1.4	KMS RUN	122859
COLOR	GREY	INSURANCE EXPIRY	2019-11-17
BODY TYPE	SEDAN	LOCATION	DELHI
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (PARTIAL)
 TYRE LIFE REMAINING (KM)	25,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,60,573




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 50%;"></div>	5 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND **83,000**



Ordered by: Adit | Inspected date: 2018-12-31

Order Id: 36786

Overall Score  **6/10**



1,60,573

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	FAIR	0
DOOR HINGES	6	FAIR	0
CARPET & FLOOR MAT	6	FAIR	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
PEDALS	6	FAIR	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	6	FAIR	0
CUP HOLDERS	6	FAIR	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	6	FAIR	0
STEERING-MOUNTED CONTROLS	0	NA	0

IMAGES



Ordered by: Adit | Inspected date: 2018-12-31

Order Id: 36786


Overall Score



6/10



1,60,573



🚗 TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	6	FAIR	0
IGNITION SYSTEM	6	FAIR	0
SUSPENSION PERFORMANCE	6	FAIR	0
SUSPENSION FRONT SHOCKS	6	FAIR	0
SUSPENSION REAR SHOCKS	6	FAIR	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
STEERING PERFORMANCE	4	STEERING TURNING TIME NOISE NEED TO BE REPAIR	15000
ENGINE NOISE	4	ENGINE STARTING TIME NOISE NEED TO BE CHECK AND REPAIR	25000

🚗 IMAGES



Ordered by: Adit | Inspected date: 2018-12-31

Order Id: 36786

Overall Score



6/10



1,60,573

WHEEL




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	FAIR	0
SPARE TYRE (YES)	6	FAIR	0
WHEEL ASSEMBLY (STEEL RIM)	6	FAIR	0

IMAGES



NEED ATTENTION ⚠



HOOD




7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	6	FAIR	0
WIRING	6	FAIR	0
BATTERY	6	AVRAGE	0
BRAKE FLUID LEVEL	7	GOOD	0

ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	6	FAIR	0

 IMAGES



 NEED ATTENTION 



Ordered by: Adit | Inspected date: 2018-12-31

Order Id: 36786

Overall Score  **6/10**



1,60,573

 **EXTERIOR**

 **5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
GRILLE	6	FAIR	0
TURN SIGNAL	6	FAIR	0
HOOD	6	FAIR	0
PILLAR	6	FAIR	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	6	FAIR	0
LH RUNNING BOARD	6	FAIR	0
FUEL LID	6	FAIR	0
REAR WINDSHIELD	7	GOOD	0
TRUNK LID/TAIL GATE	6	FAIR	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
BODY RUST	6	FAIR	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	6	FAIR	0
FRONT BUMPER	5	DENT AND SCRATCH NEED TO BE REPAIR	1500
HEAD LIGHTS	3	RUSTED NEED TO BE CHANGE	5500
FOG LAMPS	0	NA	0
LH FENDER	4	DENT AND SCRATCH NEED TO BE REPAIR	1500
LH FRONT DOOR	4	DENT AND SCRATCH NEED TO BE REPAIR	1500
LH REAR DOOR	3	DENT AND SCRATCH NEED TO BE REPAIR	2500
LH QUARTER PANEL	4	DENT AND SCRATCH NEED TO BE REPAIR	1500

REAR BUMPER	1	DAMAGE NEED TO NE CHANGE	8000
TAIL LIGHT	2	L.H.S DAMAGE NEED TO BE CHANGE	5000

Ordered by: Adit | Inspected date: 2018-12-31

Order Id: 36786

Overall Score



6/10



1,60,573



EXTERIOR (CONTINUED)



5/10







INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH QUARTER PANEL	1	DAMAGE NEED TO BE REPAIR	4500
RH RUNNING BOARD	2	DAMAGE NEED TO BE REPAIR	5000
RH REAR DOOR	3	DENT NEED TO BE REPAIR	2500
RH FRONT DOOR	4	DENT AND SCRATCH NEED TO BE REPAIR	1500
RH FENDER	4	DENTED NEED TO BE REPAIR	2500






IMAGES



NEED ATTENTION





DESCRIPTION

all body dent and scratch rear bumper damage need to change engine starting time noise steering tu

Ordered by: Adit | Inspected date: 2018-12-31

Order Id: 36786

Overall Score





6/10



1,60,573

IMAGES







Ordered by: Adit | Inspected date: 2018-12-31

Order Id: 36786

Overall Score



6/10



1,60,573

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.