



ECO INSPECTION CERTIFICATE

Premium

Order ID : 37528

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Lakho	Inspection Date : 2019-01-04	Valid Till : 2019-04-04	 Inspected By  Aabid Ali
<p>7/10</p> <p>Overall Score</p>			
<ul style="list-style-type: none"> ✓ Evaluated across 5 segments ✓ Covered 121+ checkpoints ✓ 118 does not need attention ✓ 2 Owners , 6 Years Vehicle Age ✓ No Accidental History 			<ul style="list-style-type: none"> ✓ Verified Technician 158+ vehicle inspected 1+ years experience



Hyundai Accent Executive, 2013



VEHICLE INFORMATION

MAKE	HYUNDAI	TRANSMISSION TYPE	MANUAL
MODEL	ACCENT	REGISTRATION NO.	DL8CAA8722
YEAR	2013	VIN/CHASIS NUMBER	369124
TRIM	EXECUTIVE	KMS RUN	121658
COLOR	WHITE	INSURANCE EXPIRY	2019-5-17
BODY TYPE	SEDAN	LOCATION	DELHI
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (PARTIAL)
 TYRE LIFE REMAINING (KM)	20,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	YES
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,02,619




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 4,500



Ordered by: lakho | Inspected date: 2019-01-04

Order Id: 37528

Overall Score



7/10



2,02,619



INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	8	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0



IMAGES



Ordered by: lakho | Inspected date: 2019-01-04


Order Id: 37528

Overall Score **7/10**



2,02,619

NEED ATTENTION ⚠️



TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



Ordered by: lakho | Inspected date: 2019-01-04

Order Id: 37528

Overall Score



7/10



2,02,619

WHEEL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD	0

IMAGES



NEED ATTENTION ⚠



HOOD




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0

ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	6	FAIR	0
EXHAUST SYSTEM	6	FAIR	0

IMAGES



NEED ATTENTION



Ordered by: lakho | Inspected date: 2019-01-04

Order Id: 37528

Overall Score  **7/10**



2,02,619

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	8	GOOD	0
LH REAR DOOR	6	GOOD	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
REAR BUMPER	7	GOOD	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	7	GOOD	0
RH FRONT DOOR	7	GOOD	0
RH FENDER	7	GOOD	0
BODY RUST	7	GOOD	0

Ordered by: lakho | Inspected date: 2019-01-04

Order Id: 37528

Overall Score **7/10**



2,02,619

EXTERIOR (CONTINUED)


7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0
FOG LAMPS	0	NA	0
HOOD	4	UPPER SIDE DENT	2500
LH FRONT DOOR	5	MINOR DENT	2000

IMAGES




NEED ATTENTION ⚠️





DOCUMENTS



DESCRIPTION

Dent and minor scratches need to repair Engine head leak need to repair

Ordered by: lakho | Inspected date: 2019-01-04

Order Id: 37528

Overall Score












7/10



2,02,619

IMAGES





Ordered by: lakho | Inspected date: 2019-01-04

Order Id: 37528

Overall Score



7/10



2,02,619

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.