


ECO INSPECTION CERTIFICATE

Premium

Order ID : 37298

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Gandharav	Inspection Date : 2019-01-05	Valid Till : 2019-04-05	Inspected By  Manoj Kumar
---------------------------	---------------------------------	----------------------------	--

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 110 does not need attention
- ✓ 1 Owner , 8 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**
323+ vehicle inspected
1+ years experience

Fiat Punto EMOTION 1.3, 2011



VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	PUNTO	REGISTRATION NO.	HR03M8339
YEAR	2011	VIN/CHASIS NUMBER	027406
TRIM	EMOTION 1.3	KMS RUN	119796
COLOR	WHITE	INSURANCE EXPIRY	2019-10-31
BODY TYPE	HATCHBACK	LOCATION	SEC 23A
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (FULL)
TYRE LIFE REMAINING (KM)	35,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,16,447




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 52,000



Ordered by: Gandharav | Inspected date: 2019-01-05

Order Id: 37298

Overall Score **7/10**




2,16,447

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD	0
DOOR HINGES	8	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0
STEERING-MOUNTED CONTROLS	0	NA	0

IMAGES



Ordered by: Gandharav | Inspected date: 2019-01-05

Order Id: 37298

Overall Score **7/10**



2,16,447

NEED ATTENTION



TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



Ordered by: Gandharav | Inspected date: 2019-01-05

Order Id: 37298

Overall Score **7/10**



2,16,447

WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	8	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	8	GOOD	0

IMAGES



HOOD

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

IMAGES



Ordered by: Gandharav | Inspected date: 2019-01-05

Order Id: 37298

Overall Score



7/10



2,16,447



EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	6	MINOR SCRATCHES	0
LH RUNNING BOARD	7	GOOD	0
FUEL LID	8	GOOD	0
REAR WINDSHIELD	8	GOOD	0
REAR BUMPER	6	MINOR SCRATCHES	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	6	MINOR DENT	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	7	GOOD	0
BODY RUST	7	GOOD	0
ROOF (REGULAR)	8	GOOD	0
PAINT CONDITION	7	GOOD	0
FRONT BUMPER	3	NEED TO REPAIR	6000
HEAD LIGHTS	1	RH SIDE HEAD LIGHT DAMAGE NEED TO REPLACE	6000
HOOD	3	NEED TO REPAIR	6000
LH FENDER	4	NEED TO REPAIR	5000
LH FRONT DOOR	3	NEED TO REPAIR	5000

Ordered by: Gandharav | Inspected date: 2019-01-05

Order Id: 37298

Overall Score **7/10**



2,16,447

EXTERIOR (CONTINUED)

6/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH REAR DOOR	3	NEED TO REPAIR	5000
LH QUARTER PANEL	4	NEED TO REPAIR	5000
RH REAR DOOR	4	NEED TO REPAIR	5000
RH FRONT DOOR	4	NEED TO REPAIR	5000
RH FENDER	4	NEED TO REPAIR	4000

IMAGES




NEED ATTENTION ⚠️





 DOCUMENTS



DESCRIPTION

minor scratches and minor dent front bumper and Hood already painted Lh side fender painted rear bum

Ordered by: Gandharav | Inspected date: 2019-01-05

Order Id: 37298

Overall Score




7/10



2,16,447

IMAGES





Ordered by: Gandharav | Inspected date: 2019-01-05

Order Id: 37298

Overall Score



7/10



2,16,447

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.