

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 38647

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Jignesh	Inspection Date : 2019-01-17	Valid Till : 2019-04-18	Inspected By  <b>Verified Technician</b> 6+ vehicle inspected 1+ years experience  Awaiz Thakur
<div style="text-align: center;"> <h2>8/10</h2> <div style="width: 100%; height: 10px; background: linear-gradient(to right, green 80%, grey 20%);"></div> <p><b>Overall Score</b></p> </div> <ul style="list-style-type: none"> <li>✓ Evaluated across <b>6</b> segments</li> <li>✓ Covered <b>121+</b> checkpoints</li> <li>✓ <b>121</b> does not need attention</li> <li>✓ <b>1</b> Owner , <b>1</b> Year Vehicle Age</li> <li>✓ No Accidental History</li> </ul>			

## Honda Aviator 110CC-DRUM ALLOY, 2018



VEHICLE INFORMATION			
MAKE	HONDA	LOCATION	MUMBAI
MODEL	AVIATOR	REGISTRATION NO.	MH03CW7804
YEAR	2018	VIN/CHASIS NUMBER	ME4JF21CKH8013140
TRIM	110CC-DRUM ALLOY	KMS RUN	2675
COLOR	WHITE	INSURANCE EXPIRY	2020-1-19
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

KEY OBSERVATIONS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE (BUMPER TO BUMPER)	YES
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

## 54,890

Very Good Condition

## ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND 0	
Tyre	<div style="width: 80%; background: green;"></div> 8 / 10	0	0
Control	<div style="width: 80%; background: green;"></div> 8 / 10	0	0
Light	<div style="width: 80%; background: green;"></div> 8 / 10	0	0
Oil	<div style="width: 90%; background: green;"></div> 9 / 10	0	0
Chassis	<div style="width: 80%; background: green;"></div> 8 / 10	0	0
Stand	<div style="width: 80%; background: green;"></div> 8 / 10	0	0

[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: Jignesh | Inspected date: 2019-01-17

Order Id: 38647

Overall Score



8/10



54,890

**TYRE**



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	8		0
REAR TYRE CONDITION & AIR PRESSURE	8		0
WHEEL SPOKES FRONT	8		0
WHEEL SPOKES REAR	8		0
WHEEL RIM FRONT	8		0
WHEEL RIM REAR	8		0
WHEEL BEARINGS FRONT	8		0
WHEEL BEARINGS REAR	8		0
WHEEL SEALS FRONT	8		0
WHEEL SEALS REAR	8		0
BRAKE FUNCTION FRONT	8		0
BRAKE FUNCTION REAR	8		0
BRAKES CONDITION FRONT	8		0
BRAKES CONDITION REAR	8		0

**IMAGES**



Ordered by: Jignesh | Inspected date: 2019-01-17

Order Id: 38647

Overall Score  **8/10**



**54,890**

## STAND

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	8		0
CENTRE STAND RETENTION	8		0
SIDE STAND CONDITION	8		0
SIDE STAND RETENTION	8		0

## IMAGES



## CONTROL

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	9		0
LEVERS & PEDAL CONDITION	8		0
PIVOTS	8		0
CABLES CONDITION	8		0
CABLES ROUTING	8		0
HOSES CONDITION	8		0
HOSES ROUTING	8		0
THROTTLE OPERATION	9		0

Ordered by: Jignesh | Inspected date: 2019-01-17

Order Id: 38647

Overall Score



8/10



54,890



OIL



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	8		0
LEVELS - GEAR OIL/SHAFT DRIVE (NO)	10		0
LEVELS - HYDRAULIC FLUID (NO)	10		0
LEVELS - COOLANT (NO)	10		0
LEVELS - FUEL	8		0
LEAKS - ENGINE OIL	9		0
LEAKS - GEAR OIL	9		0
LEAKS - HYDRAULIC FLUID	9		0
LEAKS - COOLANT	9		0
LEAKS - FUEL	10		0



IMAGES



Ordered by: Jignesh | Inspected date: 2019-01-17

Order Id: 38647

Overall Score



8/10



54,890



 LIGHT



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	8		0
BATTERY VENT TUBE	8		0
HEADLAMP CONDITION	8		0
TAILLAMP/BRAKELAMP CONDITION	8		0
TAILLAMP/BRAKELAMP OPERATION	8		0
TURN SIGNALS OPERATION FRONT LEFT	8		0
TURN SIGNALS OPERATION FRONT RIGHT	8		0
TURN SIGNALS OPERATION REAR LEFT	8		0
TURN SIGNALS OPERATION REAR RIGHT	8		0
SWITCHES OPERATION	9		0
MIRRORS CONDITION	8		0
MIRRORS AIM	8		0
LENSES & REFLECTORS CONDITION	8		0
WIRING CONDITION	8		0
WIRING ROUTING	8		0

 IMAGES



Ordered by: Jignesh | Inspected date: 2019-01-17

Order Id: 38647

Overall Score



8/10



54,890



## CHASSIS





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	8		0
FRAME STEERING-HEAD BEARINGS	8		0
FRAME SWINGARM BUSHINGS	8		0
SUSPENSION FRONT FORKS LEFT	8		0
SUSPENSION FRONT FORKS RIGHT	8		0
SUSPENSION REAR SHOCKS LEFT	8		0
SUSPENSION REAR SHOCKS RIGHT	8		0
CHAIN/BELT TENSION	8		0
CHAIN/BELT LUBRICATION	8		0
CHAIN/BELT SPROCKETS	8		0
FASTENERS THREADED	8		0
FASTENERS CLIPS & COTTER PINS	8		0
ENGINE	8		0
TRANSMISSION	8		0



## IMAGES



Ordered by: Jignesh | Inspected date: 2019-01-17

Order Id: 38647

Overall Score



8/10



54,890

## DESCRIPTION

Showroom condition. Time to time serviced.



Ordered by: Jignesh | Inspected date: 2019-01-17

Order Id: 38647

Overall Score




8/10



54,890

IMAGES



Ordered by: Jignesh | Inspected date: 2019-01-17

Order Id: 38647

Overall Score



8/10



54,890

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.