

ECO INSPECTION CERTIFICATE

Premium

Order ID : 40739

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Rajnish	Inspection Date : 2019-02-08	Valid Till : 2019-05-09	Inspected By Pankaj Panwar
-------------------------	---------------------------------	----------------------------	-----------------------------------

8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 119 does not need attention
- ✓ 2 Owners , 11 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**
71+ vehicle inspected
1+ years experience

Bmw 5 Series 520D, 2008



VEHICLE INFORMATION

MAKE	BMW	TRANSMISSION TYPE	AUTOMATIC
MODEL	5 SERIES	REGISTRATION NO.	DL6CJ6734
YEAR	2008	VIN/CHASIS NUMBER	065057
TRIM	520D	KMS RUN	93443
COLOR	SILVER	INSURANCE EXPIRY	2019-7-23
BODY TYPE	SEDAN	LOCATION	PHASE 4
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (FULL)
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (3RD PARTY)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

9,12,964




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 4,000



Ordered by: Rajnish | Inspected date: 2019-02-08

Order Id: 40739

Overall Score



8/10



9,12,964



INTERIOR





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOODCONDITION AND WORKING PROPERLY	0
DOOR HINGES	8	GOODCONDITION AND WORKING PROPERLY	0
CARPET & FLOOR MAT	8	GOOD	0
SEAT & SEAT BELT	8	GOODCONDITION AND WORKING PROPERLY	0
DASHBOARD & INSTRUMENT PANEL	8	GOODCONDITION AND WORKING PROPERLY	0
HORN	8	GOODCONDITION AND WORKING PROPERLY	0
SPEAKERS & MUSIC SYSTEM	8	GOODCONDITION AND WORKING PROPERLY	0
HANDBRAKE	8	GOODCONDITION AND WORKING PROPERLY	0
STEERING-MOUNTED CONTROLS	8	GOODCONDITION AND WORKING PROPERLY	0
PEDALS	8	GOODCONDITION AND WORKING PROPERLY	0
CENTRAL LOCK	8	GOODCONDITION AND WORKING PROPERLY	0
A/C VENTS & HEATER	8	GOODCONDITION AND WORKING PROPERLY	0
CUP HOLDERS	8	GOOD	0
NAVIGATION (YES)	8	GOOD	0
ODOMETER	8	GOODCONDITION AND WORKING PROPERLY	0
POWER WINDOWS (YES)	8	GOODCONDITION AND WORKING PROPERLY	0
HAZARD LIGHT	8	GOODCONDITION AND WORKING PROPERLY	0



IMAGES



Ordered by: Rajnish | Inspected date: 2019-02-08

Order Id: 40739

Overall Score



8/10



9,12,964



NEED ATTENTION




TEST DRIVE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOODCONDITION AND WORKING PROPERLY	0
BRAKE PERFORMANCE	8	GOODCONDITION AND WORKING PROPERLY	0
CLUTCH PERFORMANCE	8	GOODCONDITION AND WORKING PROPERLY	0
ENGINE NOISE	8	GOOD SOUNDAND WORKING PROPERLY	0
IGNITION SYSTEM	8	GOODCONDITION AND WORKING PROPERLY	0
SUSPENSION PERFORMANCE	8	GOODCONDITION AND WORKING PROPERLY	0
SUSPENSION FRONT SHOCKS	8	GOODCONDITION AND WORKING PROPERLY	0
SUSPENSION REAR SHOCKS	8	GOODCONDITION AND WORKING PROPERLY	0
TRANSMISSION ENGAGE	8	GOODCONDITION AND WORKING PROPERLY	0
CRUISE CONTROL (YES)	8	GOODCONDITION AND WORKING PROPERLY	0
REAR PARKING SENSORS (YES)	8	GOODCONDITION AND WORKING PROPERLY	0
REAR VIEW CAMERA (YES)	8	GOODCONDITION AND WORKING PROPERLY	0



Ordered by: Rajnish | Inspected date: 2019-02-08

Order Id: 40739

Overall Score



8/10



9,12,964

WHEEL



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	NORMAL CONDITION	0
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY (ALLOY RIM)	8	GOODCONDITION AND WORKING PROPERLY	0

IMAGES



NEED ATTENTION ⚠



HOOD




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD	0
RH APRON	8	GOOD	0
RADIATOR	8	GOODCONDITION AND WORKING PROPERLY	0
WIRING	8	GOODCONDITION AND WORKING PROPERLY	0
		GOODCONDITION AND	

BATTERY	8	WORKING PROPERLY	0
BRAKE FLUID LEVEL	8	MAXIMUM LAVAL	0
ENGINE OIL	8	MAXIMUM LAVAL	0
COOLANT LEVEL	8	MAXIMUM LAVAL	0
BRAKE & COOLANT HOSE PIPES	8	GOODCONDITION AND WORKING PROPERLY	0
UNDERCARRIAGE	8	GOOD	0
EXHAUST SYSTEM	8	GOOD	0

IMAGES



NEED ATTENTION



Ordered by: Rajnish | Inspected date: 2019-02-08

Order Id: 40739

Overall Score  **8/10**



9,12,964

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD	0
HEAD LIGHTS	8	GOODCONDITION AND WORKING PROPERLY	0
GRILLE	8	GOOD	0
TURN SIGNAL	8	GOODCONDITION AND WORKING PROPERLY	0
FOG LAMPS	8	GOODCONDITION AND WORKING PROPERLY	0
HOOD	8	GOOD	0
PILLAR	8	GOOD	0
FRONT WINDSHIELD	8	GOODVISIBILITY	0
SIDE VIEW MIRRORS	8	GOOD	0
LH FENDER	8	GOOD	0
LH FRONT DOOR	8	GOODCONDITION AND WORKING PROPERLY	0
LH REAR DOOR	8		0
LH RUNNING BOARD	8	GOOD	0
LH QUARTER PANEL	8	GOOD	0
FUEL LID	8	GOODCONDITION AND WORKING PROPERLY	0
REAR WINDSHIELD	8	GOOD VISIBILITY	0
TAIL LIGHT	8	GOODCONDITION AND WORKING PROPERLY	0
TRUNK LID/TAIL GATE	8	GOODCONDITION AND WORKING PROPERLY	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD	0
RH QUARTER PANEL	8	GOOD	0
RH RUNNING BOARD	8	GOOD	0
RH REAR DOOR	8	GOODCONDITION AND	0

RH REAR DOOR	8	WORKING PROPERLY	0
RH FRONT DOOR	8	GOODCONDITION AND WORKING PROPERLY	0
RH FENDER	8	GOOD	0

Ordered by: Rajnish | Inspected date: 2019-02-08

Order Id: 40739

Overall Score



8/10



9,12,964



EXTERIOR (CONTINUED)




8/10











INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	8	NO	0
ROOF (SUN ROOF)	8	GOODCONDITION AND WORKING PROPERLY	0
PAINT CONDITION	8	GOOD	0
FRONT BUMPER	5	MINORS SCRATCHES	1000
REAR BUMPER	5	MINORS SCRATCHES	3000



IMAGES



NEED ATTENTION



Ordered by: Rajnish | Inspected date: 2019-02-08

Order Id: 40739

Overall Score





8/10




9,12,964

IMAGES







Ordered by: Rajnish | Inspected date: 2019-02-08

Order Id: 40739

Overall Score



8/10



9,12,964

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.