


ECO INSPECTION CERTIFICATE

Premium

Order ID : 37389

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Cinoy	Inspection Date : 2019-02-09	Valid Till : 2019-05-09	Inspected By  Praveen Singh
-----------------------	---------------------------------	----------------------------	--

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 116 does not need attention
- ✓ 1 Owner , 11 Years Vehicle Age
- ✓ No Accidental History

✓ Verified Technician

5+ vehicle inspected
1+ years experience

Hyundai Accent EXECUTIVE, 2008



VEHICLE INFORMATION

MAKE	HYUNDAI	TRANSMISSION TYPE	MANUAL
MODEL	ACCENT	REGISTRATION NO.	MH03AR0595
YEAR	2008	VIN/CHASIS NUMBER	MALCG41GR8M215637
TRIM	EXECUTIVE	KMS RUN	68778
COLOR	BLACK	INSURANCE EXPIRY	2019-10-15
BODY TYPE	SEDAN	LOCATION	KANDIVALI
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	YES (DUPLICATE)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,43,766




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 8,120



Ordered by: Cinoy | Inspected date: 2019-02-09

Order Id: 37389

Overall Score



6/10



1,43,766



INTERIOR




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD CONDITION	0
DOOR HINGES	6	PROPERLY HINGE	0
CARPET & FLOOR MAT	6	GOOD FLOOR MAT	0
SEAT & SEAT BELT	6	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	6	WORKING PROPERLY	0
HORN	6	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	6	WORKING	0
HANDBRAKE	6	PROPERLY WORKING	0
STEERING-MOUNTED CONTROLS	6	NO DAMAGE ON IT	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	WORKING	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	NO DAMAGE	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	PROPERLY WORKING	0
HAZARD LIGHT	6	WORKING	0



IMAGES



Ordered by: Cinoy | Inspected date: 2019-02-09

Order Id: 37389

Overall Score **6/10**



1,43,766

NEED ATTENTION ⚠️



TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD BRAKE	0
CLUTCH PERFORMANCE	6	OPERATING NORMAL	0
ENGINE NOISE	6	NORMAL ENGINE NOISE	0
IGNITION SYSTEM	6	WORKING PROPERLY	0
SUSPENSION FRONT SHOCKS	6	MINIMUM SHOCK	0
SUSPENSION REAR SHOCKS	6	MINIMUM SHOCK	0
TRANSMISSION ENGAGE	6	PROPER ENGAGE	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
SUSPENSION PERFORMANCE	5	GOOD	0

IMAGES



Ordered by: Cinoy | Inspected date: 2019-02-09

Order Id: 37389

Overall Score **6/10**



1,43,766

WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	NO WEAR TEAR GOOD TREAD	0
SPARE TYRE (YES)	6	ACCEPTABLE CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	6	NO BEND ON IT	0

IMAGES



NEED ATTENTION ⚠





HOOD

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	NO DAMAGE	0
RH APRON	6	NO DAMAGE	0
RADIATOR	6	NO DAMAGE	0
WIRING	6	ACCEPTABLE	0
BATTERY	6	FULLY CHARGED	0
BRAKE FLUID LEVEL	6	MORE THEN MINIMUM LEVEL	0

ENGINE OIL	6	GOOD OIL	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	NO DAMAGE FOUND	0
EXHAUST SYSTEM	6	NO SMOKE DETECT	0
COOLANT LEVEL	5	NEED TO REFILL	120

IMAGES



NEED ATTENTION



Ordered by: Cinoy | Inspected date: 2019-02-09

Order Id: 37389

Overall Score



6/10



1,43,766

 EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
HEAD LIGHTS	6	WORKING	0
GRILLE	6	NO DAMAGE	0
TURN SIGNAL	6	WORKING	0
FOG LAMPS	6	NOT AVAILABLE	0
HOOD	6	NO DENT ON IT	0
PILLAR	6	NO DAMAGE FOUND	0
FRONT WINDSHIELD	6	CLEAR VISIBILITY	0
SIDE VIEW MIRRORS	6	GOOD	0
LH FENDER	6	GOOD COMDITON	0
LH FRONT DOOR	6	ACCEPTABLE CONDITION	0
LH REAR DOOR	6	ACCEPTABLE CONDITION	0
LH QUARTER PANEL	6	GOOD CONDITION	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	NO DAMAGE	0
REAR BUMPER	6	MINOR SCARTCH ON IT	2000
TAIL LIGHT	6	WORKING	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD SPACE	0
RH RUNNING BOARD	6	NO DAMAGE	0
RH REAR DOOR	6	ACCEPTABLE CONDITION	0
RH FRONT DOOR	6	ACCEPTABLE CONDITION	0
RH FENDER	6	GOOD CONDITION	0
BODY RUST	6	NO RUSH ON BODY	0

Ordered by: Cinoy | Inspected date: 2019-02-09

Order Id: 37389

Overall Score **6/10**



1,43,766

EXTERIOR (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	6	GOOD CONDITION	0
PAINT CONDITION	6	GOOD	0
FRONT BUMPER	4	NEED TO REPAINT REPAIR	2000
LH RUNNING BOARD	5	DENT ON IT	2000
RH QUARTER PANEL	5	NEED TO REPAINT	2000

IMAGES




NEED ATTENTION ⚠️





DOCUMENTS



DESCRIPTION

good car some paint patch is on body which can be remove by polishing good tyre minor dent on it

Ordered by: Cinoy | Inspected date: 2019-02-09

Order Id: 37389

Overall Score















6/10



1,43,766

IMAGES





Ordered by: Cinoy | Inspected date: 2019-02-09

Order Id: 37389

Overall Score



6/10



1,43,766

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.