




ECO INSPECTION CERTIFICATE

Premium

Order ID : 41326

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Raja	Inspection Date : 2019-02-12	Valid Till : 2019-05-12	 Inspected By  Sagar Chavan ✔ Verified Technician 12+ vehicle inspected 1+ years experience
<div style="text-align: center;"> <h2>6/10</h2>  <p>Overall Score</p> </div> <ul style="list-style-type: none"> ✔ Evaluated across 6 segments ✔ Covered 121+ checkpoints ✔ 120 does not need attention ✔ 1 Owner , 2 Years Vehicle Age ✔ No Accidental History 			









Um Renegade Sports S 280CC, 2017



VEHICLE INFORMATION

MAKE	UM	LOCATION	DIVA
MODEL	RENEGADE SPORTS S	REGISTRATION NO.	MH04JD2697
YEAR	2017	VIN/CHASIS NUMBER	MDCM3RSG1KH301222
TRIM	280CC	KMS RUN	12587
COLOR	OTHER	INSURANCE EXPIRY	2019-7-15
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	20,000	 RC COPY AVAILABLE	YES (DUPLICATE)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	 BANK NOC	NO















Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,49,630




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Tyre		6 / 10
 Control		6 / 10
 Light		6 / 10
 Oil		6 / 10
 Chassis		6 / 10
 Stand		6 / 10

TOTAL ESTIMATE SPEND 0



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: raja | Inspected date: 2019-02-12

Order Id: 41326

Overall Score



6/10



1,49,630


TYRE



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	6	NORML WEAR AND TEAR	0
REAR TYRE CONDITION & AIR PRESSURE	6	NORMAL WEAR AND TEAR	0
WHEEL SPOKES FRONT	6	NO DAMAGE	0
WHEEL SPOKES REAR	6	ACCEPTABLE CONDITION	0
WHEEL RIM FRONT	6	NO CRACKS	0
WHEEL RIM REAR	6	NO DENT AND CRACKS	0
WHEEL BEARINGS FRONT	6	NO DAMAGE	0
WHEEL BEARINGS REAR	6	WORKING CONDITION	0
WHEEL SEALS FRONT	6	NO LEAK FOUND	0
WHEEL SEALS REAR	6	NO LEAK FOUND	0
BRAKE FUNCTION FRONT	6	WORKING CONDITION	0
BRAKE FUNCTION REAR	6	WORKING CONDITION	0
BRAKES CONDITION FRONT	6	ACCEPTABLE CONDITION	0
BRAKES CONDITION REAR	6	WORKING PROPERLY	0

IMAGES



Ordered by: raja | Inspected date: 2019-02-12

Order Id: 41326

Overall Score **6/10**



1,49,630

STAND

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	6	ACCEPTABLE CONDITION	0
CENTRE STAND RETENTION	6	WORKING	0
SIDE STAND CONDITION	6	ACCEPTABLE CONDITION	0
SIDE STAND RETENTION	6	WORKING	0

IMAGES



CONTROL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	6	NO DENTS AND CRACKS	0
LEVERS & PEDAL CONDITION	6	ACCEPTABLE CONDITION	0
PIVOTS	6	NOT AVAILABLE	0
CABLES CONDITION	6	WORKING CONDITION	0
HOSES CONDITION	6	NO DAMAGE	0
HOSES ROUTING	6	NO DAMAGE	0
THROTTLE OPERATION	6	WORKING	0
CABLES ROUTING	5	NO DAMAGE	0

Ordered by: raja | Inspected date: 2019-02-12

Order Id: 41326

Overall Score



6/10



1,49,630

IMAGES



NEED ATTENTION



OIL



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	6	MAXIMUM	0
LEVELS - GEAR OIL/SHAFT DRIVE (YES)	6	MAXIMUM	0
LEVELS - HYDRAULIC FLUID (YES)	6	MAXIMUMS	0
LEVELS - COOLANT (YES)	6	MAXIMUMS	0
LEVELS - FUEL	6	MAXIMUM	0
LEAKS - ENGINE OIL	6	NO LEAKS	0
LEAKS - GEAR OIL	6	NO LEAKS	0
LEAKS - HYDRAULIC FLUID	6	NO LEAKS	0
LEAKS - COOLANT	6	NO LEAKS	0
LEAKS - FUEL	6	NO LEAKS	0

IMAGES



Ordered by: raja | Inspected date: 2019-02-12

Order Id: 41326

Overall Score



6/10



1,49,630

LIGHT



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	6	ACCEPTABLE CONDITION	0
BATTERY VENT TUBE	6	NO DAMAGE	0
HEADLAMP CONDITION	6	ACCEPTABLE CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	6	GOOD	0
TAILLAMP/BRAKELAMP OPERATION	6	WORKING	0
TURN SIGNALS OPERATION FRONT LEFT	6	WORKING	0
TURN SIGNALS OPERATION FRONT RIGHT	6	WORKING PROPERLY	0
TURN SIGNALS OPERATION REAR LEFT	6	NO CRACK AND WORKING GOOD	0
TURN SIGNALS OPERATION REAR RIGHT	6	WORKING PROPERLY	0
SWITCHES OPERATION	6	WORKING PROPERLY	0
MIRRORS CONDITION	6	GOOD CONDITION	0
MIRRORS AIM	6	CORRECT	0
LENSES & REFLECTORS CONDITION	6	GOOD REFLECTOR	0
WIRING CONDITION	6	ACCEPTABLE CONDITION	0
WIRING ROUTING	6	NO DAMAGE	0

IMAGES



Ordered by: raja | Inspected date: 2019-02-12

Order Id: 41326

Overall Score  **6/10**



1,49,630

CHASSIS

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6	NO CRACKS	0
FRAME STEERING-HEAD BEARINGS	6	NO RUSTING	0
FRAME SWINGARM BUSHINGS	6	NO DAMAGE	0
SUSPENSION FRONT FORKS LEFT	6	ACCEPTABLE CONDITION	0
SUSPENSION FRONT FORKS RIGHT	6	ACCEPTABLE CONDITION	0
SUSPENSION REAR SHOCKS LEFT	6	ACCEPTABLE CONDITION	0
SUSPENSION REAR SHOCKS RIGHT	6	ACCEPTABLE CONDITION	0
CHAIN/BELT TENSION	6	WORKING	0
CHAIN/BELT LUBRICATION	6	BETTER LUBRICATED	0
CHAIN/BELT SPROCKETS	6	ACCEPTABLE CONDITION	0
FASTENERS THREADED	6	NO RUST AVAILBLE	0
FASTENERS CLIPS & COTTER PINS	6	NO RUST AVAILABLE	0
ENGINE	6	GOOD PERFORMANCE	0
TRANSMISSION	6	SMOOTH TRANSFER	0

IMAGES



Ordered by: raja | Inspected date: 2019-02-12

Order Id: 41326

Overall Score






6/10



1,49,630

DOCUMENTS



DESCRIPTION

good condition bike

Ordered by: raja | Inspected date: 2019-02-12

Order Id: 41326

Overall Score



6/10



1,49,630

IMAGES



General Insurance Company Limited
STATE CENTRAL MOTOR VEHICLE INSURANCE CO. LTD.
THE CENTRAL MOTOR VEHICLE RULES, 1989

Proposed No. & Date	191807261 05 Mar 2019
Period of Insurance	05 Mar 2019 12:00:00 AM to 05 Mar 2020 12:00:00 AM
Insurance Policy No.	MS/02/11749/000000
Vehicle Make	BSG
Model Type	PETROL
Service Tax Code No.	AAAU7280A
Vehicle No.	MH04JD2657
Non-Elec. Accessories	
Other Accessories	

Link Vehicle No

Norms : BHARAT STAGE IV

WHEELERS

Rear HSRP No : 05 2017

Month/Year of Manuf. : 05 2017

Chassis No : MDCMURSS1KH001222

Fuel : PETROL

Cubic Capacity : 234.66

Wheel base : 1545

Standing Cap : 177

Unladen Wt (kgs) : 127

RANGE : Laden/GV Wt (kgs) : NO

AC Fitted

As other than motor cabs (Gross Vehicle Weight)

As Regd. Weight(in kgs)

REGISTRATION CERTIFICATE

REGISTRATION NO. : MH04JD2657

REGISTRATION DATE : 05/03/2019

REGISTRATION TYPE : REGULAR

REGISTRATION CHARGE : 1000

REGISTRATION TAX : 1000

REGISTRATION FEE : 1000

REGISTRATION STAMP : 1000

REGISTRATION TOTAL : 4000

REGISTRATION STATUS : ACTIVE

REGISTRATION VALIDITY : 05/03/2020

REGISTRATION OFFICE : MUMBAI

REGISTRATION OFFICER : [Signature]

Ordered by: raja | Inspected date: 2019-02-12

Order Id: 41326

Overall Score



6/10



1,49,630

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.