

# ECO INSPECTION CERTIFICATE

Premium


Order ID : 41542

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Shekar	Inspection Date : 2019-02-12	Valid Till : 2019-05-13	Inspected By   <b>Vishwnath V</b> <span style="color: green;">✔</span> <b>Verified Technician</b> 10+ vehicle inspected 1+ years experience
<h2 style="color: blue;">9/10</h2> <div style="width: 100%; height: 10px; background: linear-gradient(to right, green 90%, gray 10%);"></div> <h3>Overall Score</h3>			
<ul style="list-style-type: none"> <li><span style="color: green;">✔</span> Evaluated across <b>5</b> segments</li> <li><span style="color: green;">✔</span> Covered <b>121+</b> checkpoints</li> <li><span style="color: green;">✔</span> <b>121</b> does not need attention</li> <li><span style="color: green;">✔</span> <b>1</b> Owner , <b>3</b> Years Vehicle Age</li> <li><span style="color: green;">✔</span> No Accidental History</li> </ul>			

## Mahindra Kuv100 K8 6 STR, 2016



VEHICLE INFORMATION			
MAKE	MAHINDRA	TRANSMISSION TYPE	MANUAL
MODEL	KUV100	REGISTRATION NO.	KA 41 MA 7872
YEAR	2016	VIN/CHASIS NUMBER	MA1VA2RBCG6F94060
TRIM	K8 6 STR	KMS RUN	24201
COLOR	BLUE	INSURANCE EXPIRY	2019-12-18
BODY TYPE	HATCHBACK	LOCATION	BANGALORE
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

KEY HIGHLIGHTS			
FLOOD DAMAGE	YES	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	60,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	YES	INSURANCE COPY AVAILABLE	YES (3RD PARTY)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	YES
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

## 4,61,979

Very Good Condition

## ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND 31,800	
Interior	<div style="width: 90%; height: 10px; background: linear-gradient(to right, green 90%, gray 10%);"></div> 9 / 10	Interior	0
Wheel	<div style="width: 90%; height: 10px; background: linear-gradient(to right, green 90%, gray 10%);"></div> 9 / 10	Wheel	0
Test Drive	<div style="width: 90%; height: 10px; background: linear-gradient(to right, green 90%, gray 10%);"></div> 9 / 10	Test Drive	0
Exterior	<div style="width: 90%; height: 10px; background: linear-gradient(to right, green 90%, gray 10%);"></div> 9 / 10	Exterior	31,800
Hood	<div style="width: 90%; height: 10px; background: linear-gradient(to right, green 90%, gray 10%);"></div> 9 / 10	Hood	0

Ordered by: Shekar | Inspected date: 2019-02-12

Order Id: 41542

Overall Score



9/10



4,61,979



## INTERIOR





9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	9	OK	0
DOOR HINGES	9	OK	0
CARPET & FLOOR MAT	9	OK	0
SEAT & SEAT BELT	9	OK	0
DASHBOARD & INSTRUMENT PANEL	9	OK	0
HORN	9	OK	0
SPEAKERS & MUSIC SYSTEM	10	OK	0
HANDBRAKE	9	OK	0
STEERING-MOUNTED CONTROLS	9	OK	0
PEDALS	9	OK	0
CENTRAL LOCK	9	OK	0
A/C VENTS & HEATER	9	OK	0
CUP HOLDERS	9	OK	0
NAVIGATION (NO)	10		0
ODOMETER	9	OK	0
POWER WINDOWS (YES)	9	OK	0
HAZARD LIGHT	9	OK	0



## IMAGES



Ordered by: Shekar | Inspected date: 2019-02-12

Order Id: 41542

Overall Score



9/10



4,61,979



NEED ATTENTION



TEST DRIVE



9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	9	OK	0
BRAKE PERFORMANCE	9	OK	0
CLUTCH PERFORMANCE	9	OK	0
ENGINE NOISE	9	OK	0
IGNITION SYSTEM	9	OK	0
SUSPENSION PERFORMANCE	9	OK	0
SUSPENSION FRONT SHOCKS	8	OK	0
SUSPENSION REAR SHOCKS	9	OK	0
TRANSMISSION ENGAGE	9	OK	0
CRUISE CONTROL (YES)	9	OK	0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



Ordered by: Shekar | Inspected date: 2019-02-12

Order Id: 41542

Overall Score



9/10



4,61,979


## WHEEL




9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	9	OK	0
SPARE TYRE (YES)	10	OK	0
WHEEL ASSEMBLY (ALLOY RIM)	9	OK	0

## IMAGES



## NEED ATTENTION ⚠



## HOOD



9/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	9	OK	0
RH APRON	9	OK	0
RADIATOR	8	OK	0
WIRING	9	OK	0
BATTERY	9	OK	0
BRAKE FLUID LEVEL	10	OK	0

ENGINE OIL	9	OK	0
COOLANT LEVEL	9	OK	0
BRAKE & COOLANT HOSE PIPES	9	OK	0
UNDERCARRIAGE	9	OK	0
EXHAUST SYSTEM	9	OK	0

## IMAGES



## NEED ATTENTION



Ordered by: Shekar | Inspected date: 2019-02-12

Order Id: 41542

Overall Score  **9/10**



**4,61,979**

 **EXTERIOR**

**9/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	9	OK	0
FRONT BUMPER	8	TINKARINH	4500
HEAD LIGHTS	9	OK	0
GRILLE	9	OK	0
TURN SIGNAL	9	OK	0
FOG LAMPS	9	OK	0
HOOD	9	PAITING	3500
PILLAR	9	OK	0
FRONT WINDSHIELD	9	OK	0
SIDE VIEW MIRRORS	9	OK	0
LH FENDER	9	TINKARING AND PAITING	4500
LH FRONT DOOR	8	PAITING AND TINKARING	5300
LH REAR DOOR	9	OK	0
LH RUNNING BOARD	9	OK	0
LH QUARTER PANEL	9	PAITING	2500
FUEL LID	8	OK	0
REAR WINDSHIELD	9	OK	0
REAR BUMPER	9	PAITING AND TINKARING	5500
TAIL LIGHT	8	OK	0
TRUNK LID/TAIL GATE	8	OK	0
LUGGAGE COMPARTMENT LIGHT	9	OK	0
RH QUARTER PANEL	8	OK	0
RH RUNNING BOARD	9	OK	0
RH REAR DOOR	9	PAINTING	3500

Ordered by: Shekar | Inspected date: 2019-02-12

Order Id: 41542

Overall Score  **9/10**



**4,61,979**

## EXTERIOR (CONTINUED)

**9/10**


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	9	OK	0
RH FENDER	8	PAINTING	2500
BODY RUST	9	OK	0
ROOF (REGULAR)	9	OK	0
PAINT CONDITION	9	OK	0

## IMAGES



## NEED ATTENTION ⚠️





## DOCUMENTS




[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by  [droom.in](http://droom.in)





## DESCRIPTION

good

Ordered by: Shekar | Inspected date: 2019-02-12

Order Id: 41542

Overall Score



9/10



4,61,979

IMAGES





Ordered by: Shekar | Inspected date: 2019-02-12

Order Id: 41542

Overall Score



9/10



4,61,979

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.