


# ECO INSPECTION CERTIFICATE

Premium


Order ID : 43865

121 Points Vehicle Inspection Certificate






ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Aman	Inspection Date : 2019-02-22	Valid Till : 2019-05-22	 Inspected By   <b>Verified Technician</b> 173+ vehicle inspected 1+ years experience  <b>Pawan Kumar Gupta</b>
----------------------	---------------------------------	----------------------------	---

## 6/10



**Overall Score**

-  Evaluated across **5** segments
-  Covered **121+** checkpoints
-  **121** does not need attention
-  **2** Owners , **6** Years Vehicle Age
-  No Accidental History






## Maruti Suzuki Dzire LDI, 2013



### VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	DZIRE	REGISTRATION NO.	PB13AG7999
YEAR	2013	VIN/CHASIS NUMBER	7134
TRIM	LDI	KMS RUN	110331
COLOR	WHITE	INSURANCE EXPIRY	2019-7-4
BODY TYPE	SEDAN	LOCATION	LUDHIANA
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	6,000	 RC COPY AVAILABLE	YES (DUPLICATE)	 BANK HYPOTHECATION	YES
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**3,12,530**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Interior	<div style="width: 70%;"></div>	<b>7 / 10</b>
 Wheel	<div style="width: 60%;"></div>	<b>6 / 10</b>
 Test Drive	<div style="width: 70%;"></div>	<b>7 / 10</b>
 Exterior	<div style="width: 70%;"></div>	<b>7 / 10</b>
 Hood	<div style="width: 60%;"></div>	<b>6 / 10</b>

#### TOTAL ESTIMATE SPEND 0



Ordered by: aman | Inspected date: 2019-02-22

Order Id: 43865

Overall Score  **6/10**




**3,12,530**

## INTERIOR

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	SAFE	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	WELL	0
DASHBOARD & INSTRUMENT PANEL	6	WORKING	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	WORKING	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	7	WELL	0
PEDALS	6	SAFE	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	6	WORKING	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	WORKING	0

## IMAGES



Ordered by: aman | Inspected date: 2019-02-22

Order Id: 43865

Overall Score 6/10



3,12,530

NEED ATTENTION



TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	6	LESS NOISE	0
IGNITION SYSTEM	6	SMOOTH	0
SUSPENSION PERFORMANCE	6	SAFE	0
SUSPENSION FRONT SHOCKS	7	SAFE	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	6	SMOOTH	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



Ordered by: aman | Inspected date: 2019-02-22

Order Id: 43865

Overall Score  **6/10**




**3,12,530**

## WHEEL


**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	6	GOOD	0

## IMAGES



## NEED ATTENTION ⚠




## HOOD

**6/10**


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	7	SAFE	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	ABOVE AVERAGE	0

ENGINE OIL	7	GOOD	0
COOLANT LEVEL	6	ABOVE AVERAGE	0
BRAKE & COOLANT HOSE PIPES	6	SAFE	0
UNDERCARRIAGE	6	BETTER	0
EXHAUST SYSTEM	6	BETTER	0

## IMAGES



## NEED ATTENTION



Ordered by: aman | Inspected date: 2019-02-22

Order Id: 43865

Overall Score



6/10



3,12,530

 EXTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	NO DAMAGE	0
FRONT BUMPER	7	NO DAMAGE	0
HEAD LIGHTS	7	WORKING	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	WORKING	0
FOG LAMPS	7	GOOD	0
HOOD	7	SAFE	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	NO SCRATCHES	0
SIDE VIEW MIRRORS	6	GOOD	0
LH FENDER	7	SAFE	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	7	GOOD	0
LH RUNNING BOARD	7	NO DAMAGE	0
LH QUARTER PANEL	7	SAFE	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	6	NO SCRATCHES	0
REAR BUMPER	7	NO DAMAGE	0
TAIL LIGHT	6	WORKING	0
TRUNK LID/TAIL GATE	7	SAFE	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	SAFE	0
RH RUNNING BOARD	7	NO DAMAGE	0
RH REAR DOOR	6	GOOD	0

Ordered by: aman | Inspected date: 2019-02-22

Order Id: 43865

Overall Score



6/10



3,12,530



## EXTERIOR (CONTINUED)



7/10




INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	GOOD	0
RH FENDER	7	SAFE	0
BODY RUST	7	NO BODY RUST	0
ROOF (REGULAR)	7	SMOOTH	0
PAINT CONDITION	6	GOOD	0




## IMAGES




## NEED ATTENTION ⚠





 **DOCUMENTS**



 **DESCRIPTION**

good



Ordered by: aman | Inspected date: 2019-02-22

Order Id: 43865

Overall Score















6/10



3,12,530

IMAGES





Ordered by: aman | Inspected date: 2019-02-22

Order Id: 43865

Overall Score



6/10



3,12,530

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.