


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 44362

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Ojas	Inspection Date : 2019-02-25	Valid Till : 2019-05-25	Inspected By  RAVI Jangra
----------------------	---------------------------------	----------------------------	--

## 5/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 105 does not need attention
- ✓ 1 Owner , 12 Years Vehicle Age
- ✓ No Accidental History

- ✓ Verified Technician
- 6+ vehicle inspected
- 1+ years experience

## Maruti Suzuki Swift LDI, 2007



### VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	SWIFT	REGISTRATION NO.	HR05T8323
YEAR	2007	VIN/CHASIS NUMBER	MA3FKEBISOO207233
TRIM	LDI	KMS RUN	73658
COLOR	WHITE	INSURANCE EXPIRY	2018-1-31
BODY TYPE	HATCHBACK	LOCATION	MODAL TOWN
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**33,252**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 40%;"></div>	4 / 10
Test Drive	<div style="width: 60%;"></div>	6 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 28,403



Ordered by: ojas | Inspected date: 2019-02-25

Order Id: 44362

Overall Score  **5/10**





**33,252**

## INTERIOR

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	IN GOOD CONDITION	0
DOOR HINGES	6	NO RUSTING	0
SEAT & SEAT BELT	6	IN GOOD CONDITION	0
HORN	6	SOUND IS GOOD	0
SPEAKERS & MUSIC SYSTEM	6	ALL SPEAKERS SOUND IS GOOD	0
STEERING-MOUNTED CONTROLS	6		0
PEDALS	6	IN GOOD CONDITION	0
CENTRAL LOCK	6		0
CUP HOLDERS	6	IN GOOD CONDITION	0
NAVIGATION (YES)	6		0
ODOMETER	6	IN GOOD CONDITION	0
POWER WINDOWS (YES - FRONT ONLY)	6		0
CARPET & FLOOR MAT	5	FINE CONDITION	1000
DASHBOARD & INSTRUMENT PANEL	5	HAZARD NOT WORKING	1000
HANDBRAKE	4	NOT WORKING WELL	2000
A/C VENTS & HEATER	5	LOW AIR FLOW	200
HAZARD LIGHT	0	NOT WORKING	2000

## IMAGES



Ordered by: ojas | Inspected date: 2019-02-25

Order Id: 44362

Overall Score **5/10**



**33,252**

**NEED ATTENTION**



**TEST DRIVE**

**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	WORK PROPERLY	0
BRAKE PERFORMANCE	6	PERFORMANCE IS GOOD	0
CLUTCH PERFORMANCE	6	IN GOOD CONDITION	0
ENGINE NOISE	6	GENUINE	0
IGNITION SYSTEM	6	ALL GOOD	0
SUSPENSION PERFORMANCE	6	SUSPENSION ALSO GOOD	0
SUSPENSION FRONT SHOCKS	6	LIKE NEW	0
SUSPENSION REAR SHOCKS	7	LIKE NEW	0
TRANSMISSION ENGAGE	6	WORK PROPERLY	0
CRUISE CONTROL (YES)	0	NOT AVAILABLE	1
REAR PARKING SENSORS (YES)	0	NOT AVAILABLE	1
REAR VIEW CAMERA (YES)	0	NOT AVAILABLE	1

**IMAGES**



Ordered by: ojas | Inspected date: 2019-02-25

Order Id: 44362

Overall Score **5/10**



**33,252**

## WHEEL


**4/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
WHEEL ASSEMBLY (STEEL RIM)	6	ALL RIMS ARE IN GOOD CONDITION	0
TYRES	4	IN FINE CONDITION	15000
SPARE TYRE (YES)	3	IN FINE CONDITION	1200

## IMAGES



## NEED ATTENTION



## HOOD

**6/10**


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	IN GOOD CONDITION	0
RH APRON	6	IN GOOD CONDITION	0
RADIATOR	6	NEAT AND CLEAN	0
WIRING	6	ALL ORIGINAL	0
BATTERY	6	IN FINE CONDITION	0
BRAKE FLUID LEVEL	6	TOP OF THE LEVEL	0

ENGINE OIL	6	TOP OF THE LEVEL	0
COOLANT LEVEL	6	TOP LEVEL	0
BRAKE & COOLANT HOSE PIPES	6	IN GOOD CONDITION	0
UNDERCARRIAGE	6	CONDITION IS GOOD	0
EXHAUST SYSTEM	7	NO WHITE AND GREY SMOKE	0

## IMAGES



## NEED ATTENTION



Ordered by: ojas | Inspected date: 2019-02-25

Order Id: 44362

Overall Score  **5/10**



**33,252**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	IN GOOD CONDITION	0
FRONT BUMPER	6	MINOR SCRATCHS ON IT	0
HEAD LIGHTS	6	GLOW PROPERLY	0
GRILLE	6	IN GOOD CONDITION	0
TURN SIGNAL	6	ALL WORK PROPERLY	0
FOG LAMPS	6	NOT AVAILABLE	0
HOOD	6	IN GOOD CONDITION	0
PILLAR	6	ALL ORIGINAL	0
FRONT WINDSHIELD	7	NO CRACK NO SCRATCHS	0
SIDE VIEW MIRRORS	6	IN GOOD CONDITION	0
LH FENDER	6	NEAT AND CLEAN	0
LH REAR DOOR	6	IN GOOD CONDITION	0
LH RUNNING BOARD	6	IN GOOD CONDITION	0
FUEL LID	7	WORK PROPERLY	0
REAR WINDSHIELD	7	IN GOOD CONDITION	0
TRUNK LID/TAIL GATE	6	ALL GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	NEAT AND CLEAN	0
RH RUNNING BOARD	6	IN GOOD CONDITION	0
RH FRONT DOOR	6	NEAT AND CLEAN	0
RH FENDER	6	NEAT AND CLEAN	0
BODY RUST	6	NO BODY RUSTING	0
ROOF (REGULAR)	6	NEAT AND CLEAN	0
PAINT CONDITION	6	FINE	0
LH FRONT DOOR	5	MINOR SCRATCHS	500

Ordered by: ojas | Inspected date: 2019-02-25

Order Id: 44362

Overall Score



5/10



33,252



## EXTERIOR (CONTINUED)



6/10




INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH QUARTER PANEL	4	DENTS ON IT	500
REAR BUMPER	4	CRACKING ON IT	2000
TAIL LIGHT	2	BOTH ARE CRACK	2000
RH QUARTER PANEL	5	MINOR DENT ON IT	500
RH REAR DOOR	5	ONE MAJOR SCRATCH	500




## IMAGES



## NEED ATTENTION





## DOCUMENTS



## DESCRIPTION

well maintained



Ordered by: ojas | Inspected date: 2019-02-25

Order Id: 44362

Overall Score






5/10



33,252

IMAGES





Ordered by: ojas | Inspected date: 2019-02-25

Order Id: 44362

Overall Score



5/10



33,252

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.