

ECO INSPECTION CERTIFICATE

Premium

Order ID : 45713

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Kuldeep	Inspection Date : 2019-03-01	Valid Till : 2019-06-01
-------------------------	---------------------------------	----------------------------

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **4** Years Vehicle Age
- ✔ No Accidental History

Inspected By



✔ Verified Technician

7+ vehicle inspected
1+ years experience

RAVI Jangra

Chevrolet Beat Ls Diesel, 2015



VEHICLE INFORMATION			
MAKE	CHEVROLET	TRANSMISSION TYPE	MANUAL
MODEL	BEAT	REGISTRATION NO.	HR05AP1034
YEAR	2015	VIN/CHASSIS NUMBER	MA6BFBCNFFT007298
TRIM	LS DIESEL	KMS RUN	30743
COLOR	WHITE	INSURANCE EXPIRY	2019-7-16
BODY TYPE	HATCHBACK	LOCATION	CLUB MARKET
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

2,94,143




Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
Wheel	<div style="width: 60%; background-color: yellow; height: 10px;"></div>	6 / 10
Test Drive	<div style="width: 80%; background-color: green; height: 10px;"></div>	8 / 10
Exterior	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
Hood	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10

TOTAL ESTIMATE SPEND 500



Ordered by: Kuldeep | Inspected date: 2019-03-01

Order Id: 45713

Overall Score **7/10**



2,94,143

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	IN GOOD CONDITION	0
DOOR HINGES	6	IN GOOD CONDITION	0
CARPET & FLOOR MAT	6	NEAT AND CLEAN	0
SEAT & SEAT BELT	6	CLEAN AND GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	ALL GOOD	0
HORN	6	WORK PROPERLY AND GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	6	SOUND ID GOOD SYSTEM WORK PROPERLY	0
HANDBRAKE	7	WORKING GOOD	0
STEERING-MOUNTED CONTROLS	6	ALL GOOD	0
PEDALS	6	NEAT AND CLEAN	0
CENTRAL LOCK	7	WORK PROPERLY	0
A/C VENTS & HEATER	7	ALL GOOD	0
CUP HOLDERS	6	IN GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	7	ALL GOOD	0
POWER WINDOWS (YES - FRONT ONLY)	7	WORKING GOOD	0
HAZARD LIGHT	7	WORK PROPERLY	0

IMAGES



Ordered by: Kuldeep | Inspected date: 2019-03-01

Order Id: 45713

Overall Score **7/10**



2,94,143

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	PERFORMANCE IS GOOD	0
BRAKE PERFORMANCE	7	PERFORMANCE GOOD	0
CLUTCH PERFORMANCE	6	VERY LIGHT CLUTCH	0
ENGINE NOISE	7	SILENT NOISE	0
IGNITION SYSTEM	6	ALL GOOD	0
SUSPENSION PERFORMANCE	7	ALL GOOD NOT ANY NOISE	0
SUSPENSION FRONT SHOCKS	7	IN GOOD CONDITION	0
SUSPENSION REAR SHOCKS	7	WELL CONDITION	0
TRANSMISSION ENGAGE	6	IN GOOD CONDITION	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	IN GOOD CONDITION	0
SPARE TYRE (YES)	7	UNUSED	0
WHEEL ASSEMBLY (ALLOY RIM)	6	ALL LIKE NEW	0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	ALL CLEAN	0
RH APRON	7	ALL CLEAN	0
RADIATOR	7	IN GOOD CONDITION	0
WIRING	7	ALL GENUINE	0
BATTERY	7	NEW	0
BRAKE FLUID LEVEL	7	TOP OF THE LEVEL	0
ENGINE OIL	6	TOP OF THE LEVEL	0
COOLANT LEVEL	6	TOP OF THE LEVEL	0
BRAKE & COOLANT HOSE PIPES	7	IN GOOD CONDITION	0
UNDERCARRIAGE	7	IN FINE CONDITION	0
EXHAUST SYSTEM	6	NO WHITE AND GREY SMOKE	0

 IMAGES



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Kuldeep | Inspected date: 2019-03-01

Order Id: 45713

Overall Score  **7/10**



2,94,143

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	IN FINE CONDITION	0
FRONT BUMPER	6	MINOR SCRATCHS ON IT	0
HEAD LIGHTS	7	ALL GOOD WORK PROPERLY	0
GRILLE	6	NEAT AND CLEAN	0
TURN SIGNAL	7	WORK PROPERLY	0
FOG LAMPS	6	IN GOOD CONDITION	0
HOOD	7	IN GOOD CONDITION	0
PILLAR	7	ALL GENUINE	0
FRONT WINDSHIELD	7	NEAT AND CLEAN	0
SIDE VIEW MIRRORS	7	IN GOOD CONDITION	0
LH FENDER	7	NOT EVEN ONE SCRATCH	0
LH FRONT DOOR	7	CLEAN	0
LH REAR DOOR	7	CLEAN	0
LH RUNNING BOARD	7	ALL GENUINE	0
LH QUARTER PANEL	7	ALL GENUINE	0
FUEL LID	7	WORK PROPERLY	0
REAR WINDSHIELD	7	NEAT AND CLEAN	0
REAR BUMPER	6	MINOR SCRATCHS	0
TAIL LIGHT	7	ALL GOOD	0
TRUNK LID/TAIL GATE	7	WORK PROPERLY	0
LUGGAGE COMPARTMENT LIGHT	7	CLEAN	0
RH QUARTER PANEL	7	NOT EVEN ONE SCRATCH	0
RH RUNNING BOARD	7	ALL CLEAN	0
RH REAR DOOR	7	NEAT AND CLEAN	0

Ordered by: Kuldeep | Inspected date: 2019-03-01

Order Id: 45713

Overall Score



7/10



2,94,143



EXTERIOR (CONTINUED)



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	ALL GENUINE	0
RH FENDER	7	ORIGINAL	0
ROOF (REGULAR)	7	ALL GENUINE	0
PAINT CONDITION	7	GOOD PAINT CONDITION	0
BODY RUST	5	MINOR RUSTING	500



IMAGES







NEED ATTENTION



DOCUMENTS



DESCRIPTION

all genuine car less runing

Ordered by: Kuldeep | Inspected date: 2019-03-01

Order Id: 45713

Overall Score








7/10



2,94,143

IMAGES





Ordered by: Kuldeep | Inspected date: 2019-03-01

Order Id: 45713

Overall Score



7/10



2,94,143

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.