



ECO INSPECTION CERTIFICATE

Premium

Order ID : 47108

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sunny	Inspection Date : 2019-03-06	Valid Till : 2019-06-06	 Inspected By  Shekhar Mundhe
-----------------------	---------------------------------	----------------------------	---

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **115** does not need attention
- ✔ **2** Owners , **9** Years Vehicle Age
- ✔ No Accidental History



Fiat Punto ACTIVE 1.2, 2010



VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	PUNTO	REGISTRATION NO.	MH06AW6009
YEAR	2010	VIN/CHASIS NUMBER	01ANZ
TRIM	ACTIVE 1.2	KMS RUN	64257
COLOR	WHITE	INSURANCE EXPIRY	2019-3-5
BODY TYPE	HATCHBACK	LOCATION	PUNE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	35,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	YES	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,39,990




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%; background: linear-gradient(to right, yellow 60%, grey 40%);"></div>	6 / 10
 Wheel	<div style="width: 70%; background: linear-gradient(to right, green 70%, grey 30%);"></div>	7 / 10
 Test Drive	<div style="width: 70%; background: linear-gradient(to right, green 70%, grey 30%);"></div>	7 / 10
 Exterior	<div style="width: 60%; background: linear-gradient(to right, yellow 60%, grey 40%);"></div>	6 / 10
 Hood	<div style="width: 70%; background: linear-gradient(to right, green 70%, grey 30%);"></div>	7 / 10

TOTAL ESTIMATE SPEND 10,500



Ordered by: sunny | Inspected date: 2019-03-06

Order Id: 47108

Overall Score



6/10



1,39,990



INTERIOR




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	OK	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	6	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES - FRONT ONLY)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0



IMAGES



Ordered by: sunny | Inspected date: 2019-03-06

Order Id: 47108

Overall Score



6/10



1,39,990



TEST DRIVE




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	OK	0
ENGINE NOISE	6	OK	0
IGNITION SYSTEM	6	OK	0
SUSPENSION PERFORMANCE	6	OK	0
SUSPENSION FRONT SHOCKS	6	OK	0
SUSPENSION REAR SHOCKS	6	OK	0
TRANSMISSION ENGAGE	6	OK	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES




WHEEL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0
SPARE TYRE (YES)	8	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	6	GOOD	0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES





Ordered by: sunny | Inspected date: 2019-03-06

Order Id: 47108

Overall Score  **6/10**



1,39,990

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HEAD LIGHTS	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
FOG LAMPS	6	NO	0
PILLAR	6	OK	0
FRONT WINDSHIELD	6	OK	0
SIDE VIEW MIRRORS	6	OK	0
LH FRONT DOOR	6	SCRATCH	500
LH REAR DOOR	6	SCRATCH	500
LH RUNNING BOARD	6	OK	0
LH QUARTER PANEL	6	OK	0
REAR WINDSHIELD	6	OK	0
REAR BUMPER	6	OK	0
TAIL LIGHT	6	OK	0
TRUNK LID/TAIL GATE	6	OK	0
LUGGAGE COMPARTMENT LIGHT	6	OK	0
RH QUARTER PANEL	6	OK	0
RH RUNNING BOARD	6	GOOD	0
RH REAR DOOR	6	GOOD	0
RH FRONT DOOR	6	GOOD	0
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0
LICENSE PLATE	3	NEED TO CHANGE	500

Ordered by: sunny | Inspected date: 2019-03-06

Order Id: 47108

Overall Score



6/10



1,39,990



EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT BUMPER	4	SMALL SCRATCHES	2000
HOOD	4	SMALL DENT	1000
LH FENDER	4	SMALL SCRATCHES	500
FUEL LID	4	NEED TO REPAIRE	500
RH FENDER	1	BIG DENT	5000








IMAGES







NEED ATTENTION



DOCUMENTS



DESCRIPTION

good

Ordered by: sunny | Inspected date: 2019-03-06

Order Id: 47108

Overall Score












6/10



1,39,990

IMAGES





Ordered by: sunny | Inspected date: 2019-03-06

Order Id: 47108

Overall Score



6/10



1,39,990

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.