

ECO INSPECTION CERTIFICATE

Premium

Order ID : 48282

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Abhishek	Inspection Date : 2019-03-09	Valid Till : 2019-06-09
--------------------------	---------------------------------	----------------------------

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 1 Owner , 15 Years Vehicle Age
- ✓ No Accidental History

Inspected By

✓ **Verified Technician**

14+ vehicle inspected

1+ years experience

Jagbir Singh

Toyota Corolla 1.8E, 2004



VEHICLE INFORMATION

MAKE	TOYOTA	TRANSMISSION TYPE	MANUAL
MODEL	COROLLA	REGISTRATION NO.	PB02AN2460
YEAR	2004	VIN/CHASIS NUMBER	6817213
TRIM	1.8E	KMS RUN	78892
COLOR	WHITE	INSURANCE EXPIRY	2019-7-4
BODY TYPE	SEDAN	LOCATION	AMRITSAR
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	6,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	YES
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,60,509




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 17,000



Ordered by: Abhishek | Inspected date: 2019-03-09

Order Id: 48282

Overall Score



7/10



1,60,509



INTERIOR






7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	SAFE	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	7	WELL	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	8	WORKING	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	8	WORKING	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	7	WELL	0
PEDALS	6	SAFE	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	WORKING	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	WORKING	0



IMAGES



Ordered by: Abhishek | Inspected date: 2019-03-09

Order Id: 48282

Overall Score **7/10**



1,60,509

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD	0
BRAKE PERFORMANCE	7	SAFE	0
CLUTCH PERFORMANCE	7	SAFE	0
ENGINE NOISE	7	LESS NOISE	0
IGNITION SYSTEM	8	SMOOTH	0
SUSPENSION PERFORMANCE	8	SAFE	0
SUSPENSION FRONT SHOCKS	7	SAFE	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	7	SMOOTH	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	SAFE	0
WIRING	8	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	ABOVE AVERAGE	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	ABOVE AVERAGE	0
BRAKE & COOLANT HOSE PIPES	8	SAFE	0
UNDERCARRIAGE	8	BETTER	0
EXHAUST SYSTEM	7	BETTER	0

 IMAGES





Ordered by: Abhishek | Inspected date: 2019-03-09

Order Id: 48282

Overall Score  **7/10**



1,60,509

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	NO DAMAGE	0
FRONT BUMPER	7	NO DAMAGE	0
HEAD LIGHTS	7	WORKING	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	WORKING	0
FOG LAMPS	8	WORKING	0
HOOD	7	SAFE	0
PILLAR	8	GOOD	0
FRONT WINDSHIELD	7	NO SCRATCHES	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	7	SAFE	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	7	GOOD	0
LH RUNNING BOARD	7	NO DAMAGE	0
LH QUARTER PANEL	7	SAFE	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	8	NO SCRATCHES	0
TAIL LIGHT	7	WORKING	0
TRUNK LID/TAIL GATE	7	SAFE	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	8	SAFE	0
RH RUNNING BOARD	7	NO DAMAGE	0
RH REAR DOOR	7	GOOD	0
RH FRONT DOOR	7	GOOD	0

Ordered by: Abhishek | Inspected date: 2019-03-09

Order Id: 48282

Overall Score **7/10**



1,60,509




EXTERIOR (CONTINUED)

7/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	7	SMOOTH	0
PAINT CONDITION	8	GOOD	0
REAR BUMPER	5	PAINT REMOVED	5000
RH FENDER	4	DAMAGE	6000
BODY RUST	5	RUST ON BUMPER	6000

IMAGES








NEED ATTENTION



DOCUMENTS



DESCRIPTION

good

Ordered by: Abhishek | Inspected date: 2019-03-09

Order Id: 48282

Overall Score














7/10



1,60,509

IMAGES





Ordered by: Abhishek | Inspected date: 2019-03-09

Order Id: 48282

Overall Score



7/10



1,60,509

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.