

ECO INSPECTION CERTIFICATE

Premium

Order ID : 42010

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : SHASHANK

Inspection Date : 2019-03-08

Valid Till : 2019-06-10

6/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 91 does not need attention
- ✓ 1 Owner , 11 Years Vehicle Age
- ✓ No Accidental History

Inspected By



ARVIND KUMAR

- ✓ Verified Technician
- 20+ vehicle inspected
- 1+ years experience

Maruti Suzuki 800 AC, 2008



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	800	REGISTRATION NO.	UP63J8116
YEAR	2008	VIN/CHASIS NUMBER	2721611
TRIM	AC	KMS RUN	79202
COLOR	WHITE	INSURANCE EXPIRY	2016-3-17
BODY TYPE	SEDAN	LOCATION	BHATINDA
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	8,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

54,233




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 50%;"></div>	5 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 700



Ordered by: SHASHANK | Inspected date: 2019-03-08

Order Id: 42010

Overall Score  **6/10**



54,233

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	OK	0
DOOR HINGES	6	OK	0
CARPET & FLOOR MAT	7	OK	0
SEAT & SEAT BELT	6	OK	0
DASHBOARD & INSTRUMENT PANEL	6	OK	0
HORN	7	OK	0
SPEAKERS & MUSIC SYSTEM	6	OK	0
HANDBRAKE	7	OK	0
STEERING-MOUNTED CONTROLS	6	OK	0
CENTRAL LOCK	6	OK	0
A/C VENTS & HEATER	6	OK	0
CUP HOLDERS	7	OK	0
NAVIGATION (NO)	10		0
POWER WINDOWS (NO)	10		0
HAZARD LIGHT	6	OK	0
PEDALS	5	OK	0
ODOMETER	5	OK	0

IMAGES



Ordered by: SHASHANK | Inspected date: 2019-03-08

Order Id: 42010

Overall Score



6/10



54,233



TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BRAKE PERFORMANCE	6	OK	0
ENGINE NOISE	6	OK	0
SUSPENSION PERFORMANCE	6	OK	0
SUSPENSION REAR SHOCKS	6	OK	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0
STEERING PERFORMANCE	5	SMOOTH	0
CLUTCH PERFORMANCE	5	OK	0
IGNITION SYSTEM	5	OK	0
SUSPENSION FRONT SHOCKS	5	OK	0
TRANSMISSION ENGAGE	5	OK	0



IMAGES



WHEEL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY (ALLOY RIM)	6	OK	0
TYRES	5	OK	0

 IMAGES



 NEED ATTENTION 



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH APRON	6	OK	0
WIRING	6	OK	0
BRAKE FLUID LEVEL	6	OK	0
COOLANT LEVEL	6	OK	0
BRAKE & COOLANT HOSE PIPES	6	OK	0
EXHAUST SYSTEM	6	OK	0
LH APRON	5	OK	0
RADIATOR	5	OK	0
BATTERY	5	OK	0
ENGINE OIL	5	OK	0
UNDERCARRIAGE	5	OK	0

 IMAGES



 **NEED ATTENTION** 



Ordered by: SHASHANK | Inspected date: 2019-03-08

Order Id: 42010

Overall Score



6/10



54,233

 EXTERIOR



5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	OK	0
HEAD LIGHTS	6	OK	0
TURN SIGNAL	6	OK	0
HOOD	6	OK	0
FRONT WINDSHIELD	6	OK	0
LH FENDER	6	OK	0
LH REAR DOOR	6	OK	0
LH RUNNING BOARD	6	OK	0
REAR BUMPER	6	OK	0
TRUNK LID/TAIL GATE	6	OK	0
RH REAR DOOR	6	OK	0
ROOF (REGULAR)	6	OK	0
FRONT BUMPER	5	OK	0
GRILLE	5	OK	0
FOG LAMPS	5	OK	0
PILLAR	5	OK	0
SIDE VIEW MIRRORS	5	OK	0
LH FRONT DOOR	5	OK	0
LH QUARTER PANEL	5	OK	0
FUEL LID	5	OK	0
REAR WINDSHIELD	5	OK	0
TAIL LIGHT	3	FAIR	700
LUGGAGE COMPARTMENT LIGHT	5	OK	0
RH QUARTER PANEL	5	OK	0

Ordered by: SHASHANK | Inspected date: 2019-03-08

Order Id: 42010

Overall Score



6/10



54,233



EXTERIOR (CONTINUED)




5/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH RUNNING BOARD	5	OK	0
RH FRONT DOOR	5	OK	0
RH FENDER	5	OK	0
BODY RUST	5	OK	0
PAINT CONDITION	5	OK	0




IMAGES



 NEED ATTENTION 



 DOCUMENTS



 DESCRIPTION

good

Ordered by: SHASHANK | Inspected date: 2019-03-08

Order Id: 42010

Overall Score









6/10



54,233

IMAGES





Ordered by: SHASHANK | Inspected date: 2019-03-08

Order Id: 42010

Overall Score



6/10



54,233

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.