

ECO INSPECTION CERTIFICATE

Premium

Order ID : 49004

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Mahiar Daver	Inspection Date : 2019-03-10	Valid Till : 2019-06-10
------------------------------	---------------------------------	----------------------------

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **2** Years Vehicle Age
- ✔ No Accidental History

Inspected By

✔ Verified Technician

18+ vehicle inspected
1+ years experience

Ajay Dalvi

Honda Wr-V VX PETROL, 2017



VEHICLE INFORMATION

MAKE	HONDA	TRANSMISSION TYPE	MANUAL
MODEL	WR-V	REGISTRATION NO.	MH01CP7563
YEAR	2017	VIN/CHASIS NUMBER	FH4005594
TRIM	VX PETROL	KMS RUN	3467
COLOR	RED	INSURANCE EXPIRY	2019-6-29
BODY TYPE	HATCHBACK	LOCATION	BANDRA
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	YES (DUPLICATE)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

8,60,075




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Wheel	<div style="width: 70%; background-color: green;"></div>	7 / 10
Test Drive	<div style="width: 80%; background-color: green;"></div>	8 / 10
Exterior	<div style="width: 70%; background-color: green;"></div>	7 / 10
Hood	<div style="width: 70%; background-color: green;"></div>	7 / 10

TOTAL ESTIMATE SPEND 1,500



Ordered by: Mahiar Daver | Inspected date: 2019-03-10

Order Id: 49004

Overall Score **7/10**




8,60,075

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	6	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (YES)	7	GOOD	0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0

IMAGES



Ordered by: Mahiar Daver | Inspected date: 2019-03-10

Order Id: 49004

Overall Score



7/10



8,60,075



TEST DRIVE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (YES)	7	GOOD	0



IMAGES




WHEEL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

 IMAGES




 HOOD




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES





Ordered by: Mahiar Daver | Inspected date: 2019-03-10

Order Id: 49004

Overall Score  **7/10**



8,60,075

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	7	GOOD	0
HOOD	6		0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	6	GOOD	0
LH REAR DOOR	7	GOOD	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	8	GOOD	0
RH REAR DOOR	7	GOOD	0
RH FRONT DOOR	8	GOOD	0

Ordered by: Mahiar Daver | Inspected date: 2019-03-10

Order Id: 49004

Overall Score **7/10**



8,60,075







EXTERIOR (CONTINUED)

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7	GOOD	0
BODY RUST	8	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	8	GOOD	0
REAR BUMPER	3	NOT OK	1500

IMAGES







NEED ATTENTION



DOCUMENTS



DESCRIPTION

car need washing. rear bumper not ok. overall car ok.

Ordered by: Mahiar Daver | Inspected date: 2019-03-10

Order Id: 49004

Overall Score





7/10



8,60,075

IMAGES





Ordered by: Mahiar Daver | Inspected date: 2019-03-10

Order Id: 49004

Overall Score



7/10



8,60,075

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.