


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 47250

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : MOHIT KUMAR	Inspection Date : 2019-03-09	Valid Till : 2019-06-11	Inspected By  Abu Zafar
-----------------------------	---------------------------------	----------------------------	--

## 7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **110** does not need attention
- ✔ **2** Owners , **14** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**  
288+ vehicle inspected  
1+ years experience

## Hyundai Santro Xing Xs, 2005



### VEHICLE INFORMATION

MAKE	HYUNDAI	TRANSMISSION TYPE	MANUAL
MODEL	SANTRO XING	REGISTRATION NO.	DL3CAQ1601
YEAR	2005	VIN/CHASIS NUMBER	641638
TRIM	XS	KMS RUN	110528
COLOR	SILVER	INSURANCE EXPIRY	2019-5-24
BODY TYPE	HATCHBACK	LOCATION	VASHUNDR GHAZI
FUEL TYPE	PETROL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	YES (DUPLICATE)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**99,721**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

#### TOTAL ESTIMATE SPEND 19,950



Ordered by: MOHIT KUMAR | Inspected date: 2019-03-09

Order Id: 47250

Overall Score



7/10



99,721



## INTERIOR










7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
HANDBRAKE	7		0
PEDALS	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0
CARPET & FLOOR MAT	5	NEED WASHING	300
SPEAKERS & MUSIC SYSTEM	5	NOT WORK NEED REPAIR	3000
STEERING-MOUNTED CONTROLS	0	NA	0
CENTRAL LOCK	0	NA	0



## IMAGES





## TEST DRIVE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7	NO ANY NOISE IN IDEAL CONDITION	0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



## IMAGES




## WHEEL



6/10







INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES

 NEED ATTENTION 

 HOOD

 7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0



Ordered by: MOHIT KUMAR | Inspected date: 2019-03-09

Order Id: 47250

Overall Score  **7/10**



**99,721**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	6	SOME SCRATCHES	500
PILLAR	6	MINOR SCRATCHES	500
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FRONT DOOR	6	MINOR SCRATCHES	500
LH REAR DOOR	6	MINOR SCRATCHES	500
LH RUNNING BOARD	6	SOME SCRATCHES	1000
LH QUARTER PANEL	6	MINOR SCRATCHES	500
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	6	SOME SCRATCHES	1000
TRUNK LID/TAIL GATE	6	SOME SCRATCHES	500
LUGGAGE COMPARTMENT LIGHT	7		0
RH RUNNING BOARD	6	SOME SCRATCHES	0
RH REAR DOOR	6	MINOR SCRATCHES	500
RH FRONT DOOR	6	MINOR SCRATCHES	500
RH FENDER	6	MINOR SCRATCHES	500
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
FRONT BUMPER	5	MANY SCRATCHES NEED TO BE PAINT	1500

Ordered by: MOHIT KUMAR | Inspected date: 2019-03-09

Order Id: 47250

Overall Score



7/10



99,721



## EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FOG LAMPS	5	RIGHT HAND SIDE NOT WORKING NEED CHANGE BULB	150
LH FENDER	5	DENT AND SOME SCRATCHES NEED REPAIR	1500
TAIL LIGHT	5	RIGHT HAND SIDE DAMAGE	1500
RH QUARTER PANEL	5	SOME SCRATCHES NEED REPAIR	1000
BODY RUST	0	NA	0




## IMAGES









 **NEED ATTENTION** 







## DOCUMENTS



## DESCRIPTION

some scratches on all body frame and dent tyre change after the 15000km

Ordered by: MOHIT KUMAR | Inspected date: 2019-03-09

Order Id: 47250

Overall Score



























7/10












99,721

**IMAGES**







Ordered by: MOHIT KUMAR | Inspected date: 2019-03-09

Order Id: 47250

Overall Score



7/10



99,721

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.