

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 49351

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Anuroop	Inspection Date : 2019-03-12	Valid Till : 2019-06-12	Inspected By  Prashant Singh
-------------------------	---------------------------------	----------------------------	------------------------------------

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **118** does not need attention
- ✔ **1** Owner , **7** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

2+ vehicle inspected  
1+ years experience

## Skoda Rapid 1.5 TDI CR ELEGANCE, 2012



### VEHICLE INFORMATION

MAKE	SKODA	TRANSMISSION TYPE	MANUAL
MODEL	RAPID	REGISTRATION NO.	UP78CP4678
YEAR	2012	VIN/CHASIS NUMBER	TMBBLANA3CG010024
TRIM	1.5 TDI CR ELEGANCE	KMS RUN	152638
COLOR	OTHER	INSURANCE EXPIRY	2020-1-15
BODY TYPE	SEDAN	LOCATION	KANPUR
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

3,34,589




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 70%;"></div>	7 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

#### TOTAL ESTIMATE SPEND 19,000



Ordered by: Anuroop | Inspected date: 2019-03-12

Order Id: 49351

Overall Score  **7/10**




**3,34,589**

## INTERIOR

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	DRYCLEAN REQUIRED	5000
DOOR HINGES	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	7		0
CARPET & FLOOR MAT	5	NEW MATS REQUIRED	1000

## IMAGES



Ordered by: Anuroop | Inspected date: 2019-03-12

Order Id: 49351

Overall Score  **7/10**



**3,34,589**

## TEST DRIVE

**8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES




## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (ALLOY RIM)	7		0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: Anuroop | Inspected date: 2019-03-12

Order Id: 49351

Overall Score  **7/10**



**3,34,589**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7	DENT PAINT	2000
LH REAR DOOR	7		0
LH RUNNING BOARD	7		1500
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		1500
RH FRONT DOOR	7		0
RH FENDER	7		0

Ordered by: Anuroop | Inspected date: 2019-03-12

Order Id: 49351

Overall Score  **7/10**



**3,34,589**

**EXTERIOR (CONTINUED)**

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
FRONT BUMPER	5	BUMPER CRACKED NEED TO CHANGE	6000
REAR BUMPER	5	PAINTING NEED	2000

**IMAGES**



**NEED ATTENTION** ⚠️



Ordered by: Anuroop | Inspected date: 2019-03-12

Order Id: 49351

Overall Score





7/10



3,34,589



## DOCUMENTS



## DESCRIPTION

good condition car

Ordered by: Anuroop | Inspected date: 2019-03-12

Order Id: 49351

Overall Score




7/10



3,34,589

IMAGES





Ordered by: Anuroop | Inspected date: 2019-03-12

Order Id: 49351

Overall Score



7/10



3,34,589

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.