




ECO INSPECTION CERTIFICATE

Premium

Order ID : 47170






121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Yatharth	Inspection Date : 2019-03-08	Valid Till : 2019-06-12	 Inspected By  Abu Zafar  Verified Technician 289+ vehicle inspected 1+ years experience
--------------------------	---------------------------------	----------------------------	---

7/10

Overall Score

-  Evaluated across **5** segments
-  Covered **121+** checkpoints
-  **118** does not need attention
-  **1** Owner , **6** Years Vehicle Age
-  No Accidental History




Volkswagen Vento TRENDLINE DIESEL, 2013



VEHICLE INFORMATION

MAKE	VOLKSWAGEN	TRANSMISSION TYPE	MANUAL
MODEL	VENTO	REGISTRATION NO.	UP14CA6300
YEAR	2013	VIN/CHASIS NUMBER	069306
TRIM	TRENDLINE DIESEL	KMS RUN	113372
COLOR	OTHER	INSURANCE EXPIRY	2019-8-10
BODY TYPE	SEDAN	LOCATION	GHAZIABAD
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	15,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

3,85,673




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 80%;"></div>	8 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 80%;"></div>	8 / 10
 Exterior	<div style="width: 70%;"></div>	7 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 8,500



Ordered by: yatharth | Inspected date: 2019-03-08

Order Id: 47170

Overall Score **7/10**





3,85,673





INTERIOR

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	7		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	7		0

IMAGES





TEST DRIVE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7	NO ANY NOISE IN IDEAL CONDITION	0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	7		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



WHEEL



7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0

 IMAGES

 HOOD

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES


Ordered by: yatharth | Inspected date: 2019-03-08

Order Id: 47170

Overall Score  **7/10**



3,85,673

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
HEAD LIGHTS	7		0
GRILLE	6	MINOR SCRATCHES	500
TURN SIGNAL	7		0
FOG LAMPS	7		0
PILLAR	6	MINOR SCRATCHES	500
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	6	MINOR SCRATCHES	500
LH REAR DOOR	6	MINOR DENT AND SCRATCHES	1000
LH RUNNING BOARD	6	MINOR DENT	500
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	6	SOME SCRATCHES	1000
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	6	MINOR SCRATCHES	500
RH RUNNING BOARD	7		0
RH REAR DOOR	6	SOME SCRATCHES	500
RH FRONT DOOR	6	MINOR SCRATCHES	500
RH FENDER	7		0

Ordered by: yatharth | Inspected date: 2019-03-08

Order Id: 47170

Overall Score **7/10**



3,85,673


EXTERIOR (CONTINUED)

7/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
FRONT BUMPER	5	NEED TO BE PAINT	1500
HOOD	4	PAINT FADE NEED TO BE PAINT	1500
BODY RUST	0	NA	0

IMAGES










 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

minor scratches and dent on all body dream, tyre change after the 15000km

Ordered by: yatharth | Inspected date: 2019-03-08

Order Id: 47170

Overall Score



7/10










3,85,673

IMAGES







Ordered by: yatharth | Inspected date: 2019-03-08

Order Id: 47170

Overall Score



7/10



3,85,673

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.