

ECO INSPECTION CERTIFICATE

Premium

Order ID : 47480

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Harneet Singh

Inspection Date :
2019-03-12

Valid Till :
2019-06-13

7/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ Covered 121+ checkpoints
- ✓ 117 does not need attention
- ✓ 1 Owner , 1 Year Vehicle Age
- ✓ No Accidental History

Inspected By



Anil Rana

- ✓ Verified Technician
- 95+ vehicle inspected
- 1+ years experience

Suzuki Intruder SP 150CC, 2018



VEHICLE INFORMATION

MAKE	SUZUKI	LOCATION	DELHI
MODEL	INTRUDER SP	REGISTRATION NO.	DL13SV5208
YEAR	2018	VIN/CHASIS NUMBER	11789
TRIM	150CC	KMS RUN	1399
COLOR	BLACK	INSURANCE EXPIRY	2019-3-12
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY OBSERVATIONS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,14,470




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Tyre	<div style="width: 70%;"></div>	7 / 10
Control	<div style="width: 70%;"></div>	7 / 10
Light	<div style="width: 70%;"></div>	7 / 10
Oil	<div style="width: 80%;"></div>	8 / 10
Chassis	<div style="width: 70%;"></div>	7 / 10
Stand	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 1,800



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: Harneet Singh | Inspected date: 2019-03-12

Order Id: 47480

Overall Score



7/10



1,14,470





TYRE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT TYRE CONDITION & AIR PRESSURE	7	GOOD CONDITION	0
REAR TYRE CONDITION & AIR PRESSURE	7	GOOD CONDITION	0
WHEEL SPOKES FRONT	7	GOOD CONDITION	0
WHEEL SPOKES REAR	7	GOOD CONDITION	0
WHEEL RIM FRONT	7	GOOD CONDITION	0
WHEEL RIM REAR	7	GOOD CONDITION	0
WHEEL BEARINGS FRONT	7	GOOD CONDITION	0
WHEEL BEARINGS REAR	7	GOOD CONDITION	0
WHEEL SEALS FRONT	7	GOOD CONDITION	0
WHEEL SEALS REAR	7	GOOD CONDITION	0
BRAKE FUNCTION FRONT	7	WORKING PROPERLY	0
BRAKE FUNCTION REAR	7	WORKING PROPERLY	0
BRAKES CONDITION FRONT	7	GOOD CONDITION	0
BRAKES CONDITION REAR	7	GOOD CONDITION	0

IMAGES





www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in

Ordered by: Harneet Singh | Inspected date: 2019-03-12

Order Id: 47480

Overall Score **7/10**



1,14,470

STAND

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
CENTRE STAND CONDITION	7	GOOD CONDITION	0
CENTRE STAND RETENTION	7	GOOD RETENTION	0
SIDE STAND CONDITION	7	GOOD CONDITION	0
SIDE STAND RETENTION	7	GOOD RETENTION	0

IMAGES




CONTROL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HANDLEBARS CONDITION	7	GOOD CONDITION	0
LEVERS & PEDAL CONDITION	7	GOOD CONDITION	0
PIVOTS	7	GOOD CONDITION	0
CABLES CONDITION	7	GOOD CONDITION	0
CABLES ROUTING	7	GOOD CONDITION	0
HOSES CONDITION	7	GOOD CONDITION	0
HOSES ROUTING	7	GOOD CONDITION	0
THROTTLE OPERATION	7	WORKING PROPERLY	0

IMAGES




OIL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LEVELS - ENGINE OIL	7	MAX LEVEL	0
LEVELS - GEAR OIL/SHAFT DRIVE (NO)	10		0
LEVELS - HYDRAULIC FLUID (YES)	7	MAX LEVEL	0
LEVELS - COOLANT (NO)	10		0
LEVELS - FUEL	7	MAX LEVEL	0
LEAKS - ENGINE OIL	7	NO ANY LEAKAGE	0
LEAKS - HYDRAULIC FLUID	7	NO ANY LEAKAGE	0
LEAKS - FUEL	7	NO ANY LEAKAGE	0
LEAKS - GEAR OIL	0	NA	0
LEAKS - COOLANT	0	NA	0

IMAGES



Ordered by: Harneet Singh | Inspected date: 2019-03-12

Order Id: 47480

Overall Score **7/10**




1,14,470

LIGHT

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BATTERY CONDITION	7	WORKING PROPERLY	0
BATTERY VENT TUBE	6	AVERAGE CONDITION	0
HEADLAMP CONDITION	7	GOOD CONDITION	0
TAILLAMP/BRAKELAMP CONDITION	7	GOOD CONDITION	0
TAILLAMP/BRAKELAMP OPERATION	7	WORKING PROPERLY	0
TURN SIGNALS OPERATION FRONT LEFT	7	WORKING PROPERLY	0
TURN SIGNALS OPERATION FRONT RIGHT	7	WORKING PROPERLY	0
TURN SIGNALS OPERATION REAR LEFT	7	WORKING PROPERLY	0
TURN SIGNALS OPERATION REAR RIGHT	7	WORKING PROPERLY	0
SWITCHES OPERATION	7	WORKING PROPERLY	0
LENSES & REFLECTORS CONDITION	6	AVERAGE CONDITION	0
WIRING CONDITION	7	GOOD CONDITION	0
WIRING ROUTING	7	GOOD CONDITION	0
MIRRORS CONDITION	4	NOT AVAILABLE NEW REQUIRED	1000
MIRRORS AIM	0	NA	0

IMAGES



Ordered by: Harneet Singh | Inspected date: 2019-03-12

Order Id: 47480

Overall Score **7/10**



1,14,470

 **NEED ATTENTION** 



 **CHASSIS**

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRAME CONDITION	6	REAR NUMBER PLATE CRACK	800
FRAME STEERING-HEAD BEARINGS	7	GOOD CONDITION	0
FRAME SWINGARM BUSHINGS	7	GOOD CONDITION	0
SUSPENSION FRONT FORKS LEFT	7	GOOD CONDITION	0
SUSPENSION FRONT FORKS RIGHT	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS LEFT	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS RIGHT	7	GOOD CONDITION	0
CHAIN/BELT TENSION	7	GOOD TENSION	0
CHAIN/BELT LUBRICATION	7	GOOD LUBRICATE	0
CHAIN/BELT SPROCKETS	7	GOOD CONDITION	0
FASTENERS THREADED	7	GOOD CONDITION	0
FASTENERS CLIPS & COTTER PINS	7	GOOD CONDITION	0
ENGINE	8	GOOD CONDITION	0
TRANSMISSION	8	WORKING SMOOTHLY	0

Ordered by: Harneet Singh | Inspected date: 2019-03-12

Order Id: 47480

Overall Score




7/10




1,14,470

IMAGES



DOCUMENTS



DESCRIPTION

Rear number plate crack, both mirrors not available

Ordered by: Harneet Singh | Inspected date: 2019-03-12

Order Id: 47480

Overall Score




7/10



1,14,470

IMAGES



Ordered by: Harneet Singh | Inspected date: 2019-03-12

Order Id: 47480

Overall Score



7/10



1,14,470

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.