

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 49668

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Mohd	Inspection Date : 2019-03-17	Valid Till : 2019-06-17	Inspected By  Shoab Khan
----------------------	---------------------------------	----------------------------	--------------------------------

## 6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 114 does not need attention
- ✓ 2 Owners , 9 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**  
11+ vehicle inspected  
1+ years experience

## Tata Indica Vista AQUA TDI BS-III, 2010



### VEHICLE INFORMATION

MAKE	TATA	TRANSMISSION TYPE	MANUAL
MODEL	INDICA VISTA	REGISTRATION NO.	MH33A1386
YEAR	2010	VIN/CHASIS NUMBER	MAT6085319PN91077
TRIM	AQUA TDI BS-III	KMS RUN	73972
COLOR	SILVER	INSURANCE EXPIRY	2019-12-11
BODY TYPE	SEDAN	LOCATION	NAGPUR
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	2,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (3RD PARTY)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**1,43,897**




### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

#### TOTAL ESTIMATE SPEND 30,000



Ordered by: Mohd | Inspected date: 2019-03-17

Order Id: 49668

Overall Score



6/10



1,43,897



## INTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	6		0
HORN	6		0
SPEAKERS & MUSIC SYSTEM	6		0
HANDBRAKE	6		0
PEDALS	6		0
CENTRAL LOCK	6	NOT AVAILABLE	5000
CUP HOLDERS	6		0
NAVIGATION (NO)	10		0
ODOMETER	6		0
POWER WINDOWS (NO)	10		0
HAZARD LIGHT	6		0
STEERING-MOUNTED CONTROLS	0	NOT AVAILABLE	10000
A/C VENTS & HEATER	5	NEED REFILL	2000



## IMAGES



Ordered by: Mohd | Inspected date: 2019-03-17

Order Id: 49668

Overall Score  **6/10**



**1,43,897**

## TEST DRIVE

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	6		0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	6		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

## IMAGES



## WHEEL

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6		0
SPARE TYRE (YES)	6		0
WHEEL ASSEMBLY (STEEL RIM)	6		0

 IMAGES




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	6		0
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0

 IMAGES



Ordered by: Mohd | Inspected date: 2019-03-17

Order Id: 49668

Overall Score  **6/10**



**1,43,897**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
FRONT BUMPER	6		0
HEAD LIGHTS	6		0
GRILLE	6		0
TURN SIGNAL	6		0
FOG LAMPS	6		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	6		0
SIDE VIEW MIRRORS	6		0
LH FENDER	6		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH RUNNING BOARD	6		0
LH QUARTER PANEL	6		0
FUEL LID	6		0
REAR WINDSHIELD	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH RUNNING BOARD	6		0
RH FRONT DOOR	6		0
RH FENDER	6		0
BODY RUST	6		0
ROOF (REGULAR)	6		0
PAINT CONDITION	6		0

Ordered by: Mohd | Inspected date: 2019-03-17

Order Id: 49668

Overall Score



6/10



1,43,897



## EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
REAR BUMPER	5	SCRATCHES	2500
TAIL LIGHT	4	DAMAGE	3000
TRUNK LID/TAIL GATE	4	SCRATCH	2500
RH QUARTER PANEL	4	SCRATCH	2500
RH REAR DOOR	4	SCRATCH	2500



## IMAGES



## NEED ATTENTION



Ordered by: Mohd | Inspected date: 2019-03-17

Order Id: 49668

Overall Score




6/10



1,43,897



## DOCUMENTS



## DESCRIPTION

good condition good maintain of vehicle

Ordered by: Mohd | Inspected date: 2019-03-17

Order Id: 49668

Overall Score




6/10



1,43,897

IMAGES





Ordered by: Mohd | Inspected date: 2019-03-17

Order Id: 49668

Overall Score



6/10



1,43,897

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.