

ECO INSPECTION CERTIFICATE

Premium

Order ID : 46521

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Vishwajeet

Inspection Date :
2019-03-08

Valid Till :
2019-06-18

9/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 7 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Saurabh Tyagi

- ✓ Verified Technician
- 2+ vehicle inspected
- 1+ years experience

Maruti Suzuki Swift VDI, 2012



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	SWIFT	REGISTRATION NO.	UP80CC6352
YEAR	2012	VIN/CHASIS NUMBER	MA3FHEB1S00242203
TRIM	VDI	KMS RUN	123095
COLOR	BLUE	INSURANCE EXPIRY	2019-5-2
BODY TYPE	HATCHBACK	LOCATION	KRISHNA PARADIS
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	YES	INSURANCE COPY AVAILABLE	YES (3RD PARTY)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,66,448




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 90%;"></div>	9 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 100%;"></div>	10 / 10
Exterior	<div style="width: 100%;"></div>	10 / 10
Hood	<div style="width: 100%;"></div>	10 / 10

TOTAL ESTIMATE SPEND 8,000



Ordered by: Vishwajeet | Inspected date: 2019-03-08

Order Id: 46521

Overall Score **9/10**




2,66,448

INTERIOR

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	SCRATCHES ON DASHBOARD	0
DOOR HINGES	9		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	8		0
SPEAKERS & MUSIC SYSTEM	9		0
HANDBRAKE	9		0
STEERING-MOUNTED CONTROLS	9		0
PEDALS	9		0
CENTRAL LOCK	9		0
A/C VENTS & HEATER	9		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	9		0
POWER WINDOWS (YES)	9	REAR RIGHT POWER WINDOW NOT WORKING PROPERLY	1000
HAZARD LIGHT	9		0

IMAGES



Ordered by: Vishwajeet | Inspected date: 2019-03-08

Order Id: 46521

Overall Score




9/10



2,66,448

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	10		0
BRAKE PERFORMANCE	10		0
CLUTCH PERFORMANCE	10		0
ENGINE NOISE	9		0
IGNITION SYSTEM	10		0
SUSPENSION PERFORMANCE	10		0
SUSPENSION FRONT SHOCKS	10		0
SUSPENSION REAR SHOCKS	10		0
TRANSMISSION ENGAGE	7	GEAR TRANSMISSION HARD FROM 3RD TO 2ND	7000
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

 IMAGES

 WHEEL

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	ONE TYRE HAVING ONE SIDED WEAR AND SPARE WHEEL DAMAGED	0
SPARE TYRE (NO)	10		0
WHEEL ASSEMBLY (STEEL RIM)	8		0

 IMAGES



 HOOD

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	10		0
RH APRON	10		0
RADIATOR	10		0
WIRING	10		0
BATTERY	10		0
BRAKE FLUID LEVEL	10		0
ENGINE OIL	10		0
COOLANT LEVEL	10		0
BRAKE & COOLANT HOSE PIPES	10		0
UNDERCARRIAGE	10		0
EXHAUST SYSTEM	10		0

 IMAGES



Ordered by: Vishwajeet | Inspected date: 2019-03-08

Order Id: 46521

Overall Score **9/10**



2,66,448

 **EXTERIOR**

10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	10		0
FRONT BUMPER	10		0
HEAD LIGHTS	10		0
GRILLE	10		0
TURN SIGNAL	10		0
FOG LAMPS	10		0
HOOD	10		0
PILLAR	10		0
FRONT WINDSHIELD	10		0
SIDE VIEW MIRRORS	10		0
LH FENDER	10		0
LH FRONT DOOR	9	MINOR DENT	0
LH REAR DOOR	9		0
LH RUNNING BOARD	10		0
LH QUARTER PANEL	10		0
FUEL LID	10		0
REAR WINDSHIELD	10		0
REAR BUMPER	9		0
TAIL LIGHT	10		0
TRUNK LID/TAIL GATE	10		0
LUGGAGE COMPARTMENT LIGHT	10		0
RH QUARTER PANEL	10		0
RH RUNNING BOARD	10		0
RH REAR DOOR	9	MINOR DENT	0

Ordered by: Vishwajeet | Inspected date: 2019-03-08

Order Id: 46521

Overall Score **9/10**






2,66,448

EXTERIOR (CONTINUED)


10/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	10		0
RH FENDER	10		0
BODY RUST	10		0
ROOF (REGULAR)	10		0
PAINT CONDITION	10		0

IMAGES



DOCUMENTS



DESCRIPTION

vehicle is in good condition some minor dents and scratches in vehicle customer has replaced new fro

Ordered by: Vishwajeet | Inspected date: 2019-03-08

Order Id: 46521

Overall Score








9/10



2,66,448

IMAGES



Ordered by: Vishwajeet | Inspected date: 2019-03-08

Order Id: 46521

Overall Score



9/10



2,66,448

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.