


ECO INSPECTION CERTIFICATE

Premium

Order ID : 51682

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Tinku Barman	Inspection Date : 2019-03-22	Valid Till : 2019-06-22	Inspected By  Kamran Ansari
------------------------------	---------------------------------	----------------------------	--

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **2** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

57+ vehicle inspected
1+ years experience








Maruti Suzuki S-Cross ZETA 1.3, 2017



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	S-CROSS	REGISTRATION NO.	MH46BA5520
YEAR	2017	VIN/CHASIS NUMBER	MA3FNEB1S00159128
TRIM	ZETA 1.3	KMS RUN	26945
COLOR	WHITE	INSURANCE EXPIRY	2019-6-29
BODY TYPE	OTHER	LOCATION	KAMOTHE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	13,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (ZERO DEPRECIATION)	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

8,53,860




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 80%;"></div>	8 / 10
 Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Tinku Barman | Inspected date: 2019-03-22

Order Id: 51682

Overall Score  **7/10**







8,53,860

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	VERY GOOD CONDITION AND WORKING	0
DOOR HINGES	8	VERY GOOD CONDITION AND WORKING	0
CARPET & FLOOR MAT	7	AVAILABLE	0
SEAT & SEAT BELT	7	GOOD CONDITION AND WORKING	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION AND WORKING	0
HORN	7	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	7	GOOD CONDITION AND WORKING	0
HANDBRAKE	7	GOOD VEHICLE HOLD	0
STEERING-MOUNTED CONTROLS	7	GOOD STEERING MOUNT	0
PEDALS	7	GOOD CONDITION AND PLAY	0
CENTRAL LOCK	7	GOOD CONDITION AND WORKING	0
A/C VENTS & HEATER	8	VERY GOOD CONDITION AND WORKING	0
CUP HOLDERS	7	GOOD CONDITION	0
NAVIGATION (YES)	7	GOOD CONDITION AND WORKING	0
ODOMETER	7	SMOOTHLY WORKING	0
POWER WINDOWS (YES)	8	VERY GOOD CONDITION AND WORKING	0
HAZARD LIGHT	7	GOOD CONDITION AND WORKING	0

IMAGES



TEST DRIVE



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD CONDITION AND SMOOTH WORKING	0
BRAKE PERFORMANCE	7	GOOD BRAKING	0
CLUTCH PERFORMANCE	7	GOOD CONDITION AND WORKING	0
ENGINE NOISE	8	ALMOST NO NOISE	0
IGNITION SYSTEM	7	GOOD CONDITION AND WORKING	0
SUSPENSION PERFORMANCE	8	ABSORBING EVERY ROAD SHOCKS	0
SUSPENSION FRONT SHOCKS	8	ABSORBING EVERY ROAD SHOCKS	0
SUSPENSION REAR SHOCKS	8	ABSORBING EVERY ROAD SHOCKS	0
TRANSMISSION ENGAGE	8	VERY SMOOTH ENGAGEMENT	0
CRUISE CONTROL (YES)	7	GOOD CONDITION AND WORKING	0
REAR PARKING SENSORS (YES)	7	GOOD CONDITION AND WORKING	0
REAR VIEW CAMERA (YES)	7	GOOD CONDITION AND WORKING	0



IMAGES








WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD CONDITION	0
SPARE TYRE (YES)	7	GOOD CONDITION	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD CONDITION	0

IMAGES





HOOD

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	VERY GOOD CONDITION	0
RH APRON	8	VERY GOOD CONDITION	0
RADIATOR	8	VERY GOOD CONDITION NO LEAK FOUND	0
WIRING	7	GOOD CONDITION NO LEAK FOUND	0
BATTERY	7	GOOD CONDITION AND FULLY CHARGED	0
BRAKE FLUID LEVEL	7	MAXIMUM	0

ENGINE OIL	7	GOOD CONDITION	0
COOLANT LEVEL	7	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION NO LEAK FOUND	0
UNDERCARRIAGE	7	GOOD CONDITION	0
EXHAUST SYSTEM	7	GOOD CONDITION AND WORKING	0

 IMAGES



Ordered by: Tinku Barman | Inspected date: 2019-03-22

Order Id: 51682

Overall Score  **7/10**



8,53,860

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	8	VERY GOOD CONDITION	0
HEAD LIGHTS	8	VERY GOOD CONDITION	0
GRILLE	7	GOOD CONDITION	0
TURN SIGNAL	7	GOOD CONDITION AND WORKING	0
FOG LAMPS	7	GOOD CONDITION AND WORKING	0
HOOD	8	VERY GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	8	VERY GOOD VISIBILITY	0
SIDE VIEW MIRRORS	7	GOOD CONDITION AND WORKING	0
LH FENDER	8	VERY GOOD CONDITION	0
LH FRONT DOOR	8	VERY GOOD CONDITION	0
LH REAR DOOR	8	VERY GOOD CONDITION	0
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	8	VERY GOOD CONDITION	0
FUEL LID	7	GOOD CONDITION AND WORKING	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
REAR BUMPER	6	AVERAGE CONDITION	0
TAIL LIGHT	8	VERY GOOD CONDITION AND WORKING	0
TRUNK LID/TAIL GATE	8	VERY GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD SPACING	0
RH QUARTER PANEL	8	VERY GOOD CONDITION	0
RH RUNNING BOARD	7	GOOD CONDITION	0

RH REAR DOOR	8	VERY GOOD CONDITION	0
--------------	---	---------------------	---

Ordered by: Tinku Barman | Inspected date: 2019-03-22

Order Id: 51682

Overall Score **7/10**



8,53,860

EXTERIOR (CONTINUED)

8/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	VERY GOOD CONDITION	0
RH FENDER	8	VERY GOOD CONDITION	0
BODY RUST	8	NO RUST FOUND	0
ROOF (REGULAR)	8	VERY GOOD CONDITION	0
PAINT CONDITION	9	EXCELLENT CONDITION	0

IMAGES





 DOCUMENTS



 DESCRIPTION

Excellent Condition Car

Ordered by: Tinku Barman | Inspected date: 2019-03-22

Order Id: 51682

Overall Score




















7/10



8,53,860

IMAGES





Ordered by: Tinku Barman | Inspected date: 2019-03-22

Order Id: 51682

Overall Score



7/10



8,53,860

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.