

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 51105

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Manoj Sharma	Inspection Date : 2019-03-22	Valid Till : 2019-06-22
------------------------------	---------------------------------	----------------------------

## 7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 1 Owner , 4 Years Vehicle Age
- ✓ No Accidental History

**Inspected By**

✓ **Verified Technician**

146+ vehicle inspected

1+ years experience

**Pankaj Panwar**

## Maruti Suzuki Swift VDI ABS BS IV, 2015



VEHICLE INFORMATION			
MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	SWIFT	REGISTRATION NO.	DL5CJ9858
YEAR	2015	VIN/CHASIS NUMBER	806462
TRIM	VDI ABS BS IV	KMS RUN	74967
COLOR	SILVER	INSURANCE EXPIRY	2019-3-22
BODY TYPE	HATCHBACK	LOCATION	45 SEC
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	35,000	RC COPY AVAILABLE	YES (DUPLICATE)
DENT	NO	INSURANCE COPY AVAILABLE	NO
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.  
With this evaluation, the Fair Market Price for this vehicle comes to be:

## 4,51,415

## ECO SCORE & REPAIR COST ESTIMATE

**ECO SCORE**

Interior	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
Wheel	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
Test Drive	<div style="width: 80%; background-color: green; height: 10px;"></div>	8 / 10
Exterior	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10
Hood	<div style="width: 70%; background-color: green; height: 10px;"></div>	7 / 10

**TOTAL ESTIMATE SPEND 1,800**

Ordered by: Manoj Sharma | Inspected date: 2019-03-22

Order Id: 51105

Overall Score




7/10



4,51,415

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION AND WORKING PROPERLY	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD CONDITION AND WORKING PROPERLY	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION AND WORKING PROPERLY	0
HORN	7	GOOD CONDITION AND WORKING PROPERLY	0
SPEAKERS & MUSIC SYSTEM	7	GOOD CONDITION AND WORKING PROPERLY	0
HANDBRAKE	7	GOOD CONDITION AND WORKING PROPERLY	0
PEDALS	7	GOOD CONDITION AND WORKING PROPERLY	0
CENTRAL LOCK	7	GOOD CONDITION AND WORKING PROPERLY	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD CONDITION AND WORKING PROPERLY	0
POWER WINDOWS (YES - FRONT ONLY)	7	GOOD CONDITION AND WORKING PROPERLY	0
HAZARD LIGHT	7	GOOD CONDITION AND WORKING PROPERLY	0
STEERING-MOUNTED CONTROLS	0	NOT AVAILABLE	0

 IMAGES


Ordered by: Manoj Sharma | Inspected date: 2019-03-22

Order Id: 51105

Overall Score




7/10



4,51,415

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD CONDITION AND WORKING PROPERLY	0
BRAKE PERFORMANCE	7	GOOD CONDITION AND WORKING PROPERLY	0
CLUTCH PERFORMANCE	7	GOOD CONDITION AND WORKING PROPERLY	0
ENGINE NOISE	7	GOOD SOUND AND WORKING PROPERLY	0
IGNITION SYSTEM	7	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION PERFORMANCE	7	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION FRONT SHOCKS	7	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD CONDITION AND WORKING PROPERLY	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

 IMAGES

 WHEEL

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD CONDITION AND WORKING PROPERLY	0
SPARE TYRE (YES)	7	GOOD CONDITION AND WORKING PROPERLY	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	MAXIMUM	0
ENGINE OIL	7	MAXIMUM	0
COOLANT LEVEL	7	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: Manoj Sharma | Inspected date: 2019-03-22

Order Id: 51105

Overall Score  **7/10**



**4,51,415**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD CONDITION AND WORKING PROPERLY	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	7	GOOD	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	6	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
REAR BUMPER	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	7	GOOD	0
RH FRONT DOOR	7	GOOD	0
RH FENDER	7	GOOD	0

Ordered by: Manoj Sharma | Inspected date: 2019-03-22

Order Id: 51105

Overall Score  **7/10**



**4,51,415**

## EXTERIOR (CONTINUED)



**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0
FOG LAMPS	0	NOT AVAILABLE	0
TAIL LIGHT	5	RIGHT SIDE TAIL LIGHT NEED TO BE CHANG	1800

## IMAGES








 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

minor scratches fully dent paint

Ordered by: Manoj Sharma | Inspected date: 2019-03-22

Order Id: 51105

Overall Score













7/10



4,51,415

IMAGES





Ordered by: Manoj Sharma | Inspected date: 2019-03-22

Order Id: 51105

Overall Score



7/10



4,51,415

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.