


ECO INSPECTION CERTIFICATE

Premium

Order ID : 51973

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Togi Umashankar	Inspection Date : 2019-03-23	Valid Till : 2019-06-27	Inspected By  Siddharth Ningurkar
---------------------------------	---------------------------------	----------------------------	--

8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 118 does not need attention
- ✓ 1 Owner , 3 Years Vehicle Age
- ✓ No Accidental History

- ✓ **Verified Technician**
- 48+ vehicle inspected
- 1+ years experience

Fiat Punto Evo DYNAMIC MULTIJET 1.3, 2016



VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	PUNTO EVO	REGISTRATION NO.	MH12MR6085
YEAR	2016	VIN/CHASIS NUMBER	66668
TRIM	DYNAMIC MULTIJET 1.3	KMS RUN	33860
COLOR	WHITE	INSURANCE EXPIRY	2019-9-22
BODY TYPE	HATCHBACK	LOCATION	OUNE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	YES (FULL)
TYRE LIFE REMAINING (KM)	40,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

4,71,304




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 90%;"></div>	9 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 5,500



Ordered by: togi umashankar | Inspected date: 2019-03-23

Order Id: 51973

Overall Score



8/10



4,71,304



INTERIOR





8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR HINGES	8	GOOD	0
CARPET & FLOOR MAT	8	GOOD	0
SEAT & SEAT BELT	8	GOOD	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD	0
HORN	8	GOOD	0
SPEAKERS & MUSIC SYSTEM	8	GOOD	0
HANDBRAKE	8	GOOD	0
STEERING-MOUNTED CONTROLS	8	GOOD	0
PEDALS	8	GOOD	0
CENTRAL LOCK	8	GOOD	0
A/C VENTS & HEATER	8	GOOD	0
CUP HOLDERS	8	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	8	GOOD	0
POWER WINDOWS (YES)	8	GOOD	0
HAZARD LIGHT	8	GOOD	0
DOOR PANEL	3	NEED POLISH	500



IMAGES



Ordered by: togi umashankar | Inspected date: 2019-03-23

Order Id: 51973

Overall Score **8/10**



4,71,304

NEED ATTENTION




TEST DRIVE

9/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	GOOD	0
BRAKE PERFORMANCE	8	GOOD	0
CLUTCH PERFORMANCE	8	GOOD	0
ENGINE NOISE	8	GOOD	0
IGNITION SYSTEM	8	GOOD	0
SUSPENSION PERFORMANCE	8	GOOD	0
SUSPENSION FRONT SHOCKS	8	GOOD	0
SUSPENSION REAR SHOCKS	8	GOOD	0
TRANSMISSION ENGAGE	8	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



Ordered by: togi umashankar | Inspected date: 2019-03-23

Order Id: 51973

Overall Score **8/10**




4,71,304

WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	GOOD	0
SPARE TYRE (YES)	8	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	8	GOOD	0

IMAGES






HOOD

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	GOOD	0
RH APRON	8	GOOD	0
RADIATOR	8	GOOD	0
WIRING	8	GOOD	0
BATTERY	8	GOOD	0
BRAKE FLUID LEVEL	8	GOOD	0
ENGINE OIL	8	GOOD	0
COOLANT LEVEL	8	GOOD	0

BRAKE & COOLANT HOSE PIPES	8	GOOD	0
UNDERCARRIAGE	8	GOOD	0
EXHAUST SYSTEM	8	GOOD	0

 IMAGES



Ordered by: togi umashankar | Inspected date: 2019-03-23

Order Id: 51973

Overall Score  **8/10**



4,71,304

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	8	GOOD	0
GRILLE	8	GOOD	0
TURN SIGNAL	8	GOOD	0
HOOD	8	GOOD	0
PILLAR	8	GOOD	0
FRONT WINDSHIELD	8	GOOD	0
SIDE VIEW MIRRORS	8	GOOD	0
LH FENDER	8	GOOD	0
LH FRONT DOOR	8	GOOD	0
LH REAR DOOR	8	GOOD	0
LH RUNNING BOARD	8	GOOD	0
LH QUARTER PANEL	8	GOOD	0
FUEL LID	8	GOOD	0
REAR WINDSHIELD	8	GOOD	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	8	GOOD	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD	0
RH QUARTER PANEL	8	GOOD	0
RH RUNNING BOARD	8	GOOD	0
RH REAR DOOR	8	GOOD	0
RH FRONT DOOR	8	GOOD	0
RH FENDER	8	GOOD	0

Ordered by: togi umashankar | Inspected date: 2019-03-23

Order Id: 51973

Overall Score **8/10**



4,71,304




EXTERIOR (CONTINUED)

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
BODY RUST	8	GOOD	0
ROOF (REGULAR)	8	GOOD	0
PAINT CONDITION	8	GOOD	0
FOG LAMPS	3	NO	2000
REAR BUMPER	3	SCRATCHES	3000

IMAGES





 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

good, new tyres new battery

Ordered by: togi umashankar | Inspected date: 2019-03-23

Order Id: 51973

Overall Score
















8/10



4,71,304

IMAGES





Ordered by: togi umashankar | Inspected date: 2019-03-23

Order Id: 51973

Overall Score



8/10



4,71,304

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.