

ECO INSPECTION CERTIFICATE

Premium

Order ID : 53123

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Shantanu	Inspection Date : 2019-03-27	Valid Till : 2019-06-28
--------------------------	---------------------------------	----------------------------

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 116 does not need attention
- ✓ 3 Owners , 7 Years Vehicle Age
- ✓ No Accidental History

Inspected By

✓ **Verified Technician**

65+ vehicle inspected

1+ years experience

VICKY KUMAR

Mahindra Thar CRDE 4X4 AC, 2012



VEHICLE INFORMATION			
MAKE	MAHINDRA	TRANSMISSION TYPE	MANUAL
MODEL	THAR	REGISTRATION NO.	RJ14UC5247
YEAR	2012	VIN/CHASIS NUMBER	82420
TRIM	CRDE 4X4 AC	KMS RUN	90290
COLOR	SILVER	INSURANCE EXPIRY	2018-3-14
BODY TYPE	OTHER	LOCATION	JAIPUR
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS			
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO
TYRE LIFE REMAINING (KM)	9,000	RC COPY AVAILABLE	YES (ORIGINAL)
DENT	NO	INSURANCE COPY AVAILABLE	NO
		SERVICE LOGS AVAILABLE	NO
		BANK HYPOTHECATION	NO
		BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.

With this evaluation, the Fair Market Price for this vehicle comes to be:

3,24,384


Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%; background-color: #27ae60; height: 10px;"></div>	8 / 10
Wheel	<div style="width: 70%; background-color: #27ae60; height: 10px;"></div>	7 / 10
Test Drive	<div style="width: 80%; background-color: #27ae60; height: 10px;"></div>	8 / 10
Exterior	<div style="width: 80%; background-color: #27ae60; height: 10px;"></div>	8 / 10
Hood	<div style="width: 70%; background-color: #27ae60; height: 10px;"></div>	7 / 10

TOTAL ESTIMATE SPEND 3,000



Ordered by: shantanu | Inspected date: 2019-03-27

Order Id: 53123

Overall Score **7/10**



3,24,384

INTERIOR

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	OK	0
DOOR HINGES	7	OK	0
CARPET & FLOOR MAT	8	OK	0
SEAT & SEAT BELT	7	OK	0
DASHBOARD & INSTRUMENT PANEL	8	OK	0
HORN	9	OK	0
SPEAKERS & MUSIC SYSTEM	7	OK	0
HANDBRAKE	8	OK	0
STEERING-MOUNTED CONTROLS	7	OK	0
PEDALS	8	OK	0
CENTRAL LOCK	7	OK	0
A/C VENTS & HEATER	7	OK	0
CUP HOLDERS	7	OK	0
NAVIGATION (NO)	10		0
ODOMETER	8	OK	0
POWER WINDOWS (YES - FRONT ONLY)	6	OK	0
HAZARD LIGHT	8	OK	0

IMAGES



Ordered by: shantanu | Inspected date: 2019-03-27

Order Id: 53123

Overall Score **7/10**




3,24,384

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	SMOOTH	0
BRAKE PERFORMANCE	7	OK	0
CLUTCH PERFORMANCE	8	OK	0
ENGINE NOISE	7	OK	0
IGNITION SYSTEM	8	OK	0
SUSPENSION PERFORMANCE	7	OK	0
SUSPENSION FRONT SHOCKS	8	OK	0
SUSPENSION REAR SHOCKS	7	OK	0
TRANSMISSION ENGAGE	8	OK	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	OK	0
SPARE TYRE (YES)	8	OK	0
WHEEL ASSEMBLY (ALLOY RIM)	7	OK	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	OK	0
RH APRON	8	OK	0
RADIATOR	6	OK	0
WIRING	8	OK	0
BATTERY	7	OK	0
BRAKE FLUID LEVEL	8	OK	0
ENGINE OIL	7	OK	0
COOLANT LEVEL	8	OK	0
BRAKE & COOLANT HOSE PIPES	7	OK	0
UNDERCARRIAGE	6	OK	0
EXHAUST SYSTEM	8	OK	0

 IMAGES





Ordered by: shantanu | Inspected date: 2019-03-27

Order Id: 53123

Overall Score  **7/10**



3,24,384

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	OK	0
FRONT BUMPER	8	OK	0
HEAD LIGHTS	7	OK	0
GRILLE	8	OK	0
TURN SIGNAL	8	OK	0
FOG LAMPS	7	OK	0
HOOD	8	OK	0
PILLAR	7	OK	0
FRONT WINDSHIELD	8	OK	0
SIDE VIEW MIRRORS	7	OK	0
LH FENDER	8	OK	0
LH FRONT DOOR	7	OK	0
LH RUNNING BOARD	8	OK	0
LH QUARTER PANEL	7	OK	0
FUEL LID	8	OK	0
TAIL LIGHT	8	OK	0
TRUNK LID/TAIL GATE	8	OK	0
LUGGAGE COMPARTMENT LIGHT	7	OK	0
RH QUARTER PANEL	8	OK	0
RH RUNNING BOARD	9	OK	0
RH FRONT DOOR	7	OK	0
RH FENDER	8	OK	0
ROOF (NO ROOF)	10		0
PAINT CONDITION	7	OK	0

Ordered by: shantanu | Inspected date: 2019-03-27

Order Id: 53123

Overall Score **7/10**



3,24,384

EXTERIOR (CONTINUED)

8/10


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH REAR DOOR	0	NOT IN MODEL	0
REAR WINDSHIELD	0	NOT IN MODEL	0
REAR BUMPER	5	FAIR	1000
RH REAR DOOR	0	NOT IN MODEL	0
BODY RUST	5	OK	2000

IMAGES





NEED ATTENTION ⚠️



DOCUMENTS



DESCRIPTION

good

Ordered by: shantanu | Inspected date: 2019-03-27

Order Id: 53123

Overall Score














7/10



3,24,384

IMAGES





Ordered by: shantanu | Inspected date: 2019-03-27

Order Id: 53123

Overall Score



7/10



3,24,384

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.