

ECO INSPECTION CERTIFICATE

Premium

Order ID : 44678

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Tushar	Inspection Date : 2019-03-28	Valid Till : 2019-06-28
------------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **3** Owners , **8** Years Vehicle Age
- ✔ No Accidental History

Inspected By

✔ **Verified Technician**

14+ vehicle inspected
1+ years experience

Piyush Malakiya

Nissan X-Trail SLX AT, 2011



VEHICLE INFORMATION			
MAKE	NISSAN	TRANSMISSION TYPE	AUTOMATIC
MODEL	X-TRAIL	REGISTRATION NO.	GJ12BF9597
YEAR	2011	VIN/CHASIS NUMBER	000333
TRIM	SLX AT	KMS RUN	186198
COLOR	GREY	INSURANCE EXPIRY	2019-3-28
BODY TYPE	SEDAN	LOCATION	RAJKOT
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS					
FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

5,38,264

Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 70%; background-color: yellow; height: 10px;"></div>	6 / 10
Wheel	<div style="width: 70%; background-color: yellow; height: 10px;"></div>	6 / 10
Test Drive	<div style="width: 70%; background-color: yellow; height: 10px;"></div>	6 / 10
Exterior	<div style="width: 70%; background-color: yellow; height: 10px;"></div>	6 / 10
Hood	<div style="width: 70%; background-color: yellow; height: 10px;"></div>	6 / 10

TOTAL ESTIMATE SPEND 0

0

Interior

0

Wheel

0

Test Drive

0

Exterior

0

Hood

Ordered by: Tushar | Inspected date: 2019-03-28

Order Id: 44678

Overall Score **6/10**





5,38,264

INTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	6		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	6		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	6		0
SPEAKERS & MUSIC SYSTEM	6		0
HANDBRAKE	6		0
STEERING-MOUNTED CONTROLS	6		0
PEDALS	6		0
CENTRAL LOCK	6		0
A/C VENTS & HEATER	6		0
CUP HOLDERS	6		0
NAVIGATION (NO)	10		0
ODOMETER	6		0
POWER WINDOWS (YES)	6		0
HAZARD LIGHT	6		0

IMAGES



Ordered by: Tushar | Inspected date: 2019-03-28

Order Id: 44678

Overall Score **6/10**



5,38,264

TEST DRIVE

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	6		0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	6		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (YES)	6		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (YES)	6		0

IMAGES




WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6		0
SPARE TYRE (YES)	6		0
WHEEL ASSEMBLY (STEEL RIM)	6		0

 IMAGES




 HOOD

 6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	6		0
BRAKE FLUID LEVEL	6		0
ENGINE OIL	6		0
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	6		0
EXHAUST SYSTEM	6		0

 IMAGES





Ordered by: Tushar | Inspected date: 2019-03-28

Order Id: 44678

Overall Score



6/10



5,38,264



EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
FRONT BUMPER	6		0
HEAD LIGHTS	6		0
GRILLE	6		0
TURN SIGNAL	6		0
FOG LAMPS	6		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	6		0
SIDE VIEW MIRRORS	6		0
LH FENDER	6		0
LH FRONT DOOR	6		0
LH REAR DOOR	6		0
LH RUNNING BOARD	6		0
LH QUARTER PANEL	6		0
FUEL LID	6		0
REAR WINDSHIELD	6		0
REAR BUMPER	6		0
TAIL LIGHT	6		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	6		0
RH RUNNING BOARD	6		0
RH REAR DOOR	6		0

Ordered by: Tushar | Inspected date: 2019-03-28

Order Id: 44678

Overall Score



6/10



5,38,264



EXTERIOR (CONTINUED)





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6		0
RH FENDER	6		0
BODY RUST	6		0
ROOF (SUN ROOF)	6		0
PAINT CONDITION	6		0



IMAGES





DOCUMENTS



DESCRIPTION

average

Ordered by: Tushar | Inspected date: 2019-03-28

Order Id: 44678

Overall Score







6/10



5,38,264

IMAGES





Ordered by: Tushar | Inspected date: 2019-03-28

Order Id: 44678

Overall Score



6/10



5,38,264

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.