


ECO INSPECTION CERTIFICATE

Premium

Order ID : 53382

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Dharmendra Yadav	Inspection Date : 2019-03-29	Valid Till : 2019-06-30	Inspected By  Rathod Abhijit
----------------------------------	---------------------------------	----------------------------	---

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 7 Years Vehicle Age
- ✓ No Accidental History

✓ **Verified Technician**
661+ vehicle inspected
3+ years experience

Maruti Suzuki Swift LDI, 2012



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	TRANSMISSION TYPE	MANUAL
MODEL	SWIFT	REGISTRATION NO.	GJ01KP5716
YEAR	2012	VIN/CHASIS NUMBER	MA3FHEB1S0019644
TRIM	LDI	KMS RUN	82390
COLOR	RED	INSURANCE EXPIRY	2019-3-30
BODY TYPE	HATCHBACK	LOCATION	AHMEDABAD
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	10,000	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,68,127




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: dharmendra yadav | Inspected date: 2019-03-29

Order Id: 53382

Overall Score  **7/10**




2,68,127


INTERIOR

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	GOOD CONDITION	0
DOOR HINGES	8	GOOD CONDITION	0
CARPET & FLOOR MAT	8	GOOD CONDITION	0
SEAT & SEAT BELT	8	GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	8	GOOD CONDITION	0
HORN	8	GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	8	GOOD CONDITION	0
HANDBRAKE	8	GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	8	GOOD CONDITION	0
PEDALS	8	GOOD CONDITION	0
CENTRAL LOCK	8	GOOD CONDITION	0
A/C VENTS & HEATER	8	GOOD CONDITION	0
CUP HOLDERS	8	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	8	GOOD CONDITION	0
POWER WINDOWS (NO)	10		0
HAZARD LIGHT	8	GOOD CONDITION	0

IMAGES






TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD CONDITION	0
BRAKE PERFORMANCE	7	GOOD CONDITION	0
CLUTCH PERFORMANCE	7	GOOD CONDITION	0
ENGINE NOISE	7	GOOD CONDITION	0
IGNITION SYSTEM	7	GOOD CONDITION	0
SUSPENSION PERFORMANCE	7	GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	7	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	7	GOOD CONDITION	0
TRANSMISSION ENGAGE	7	GOOD CONDITION	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	NEUTRAL CONDITION	0
SPARE TYRE (YES)	7	GOOD CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	8	GOOD CONDITION	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD CONDITION	0
RH APRON	7	GOOD CONDITION	0
RADIATOR	7	GOOD CONDITION	0
WIRING	7	GOOD CONDITION	0
BATTERY	7	GOOD CONDITION	0
BRAKE FLUID LEVEL	7	GOOD CONDITION	0
ENGINE OIL	7	GOOD CONDITION	0
COOLANT LEVEL	7	GOOD CONDITION	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION	0
UNDERCARRIAGE	7	GOOD CONDITION	0
EXHAUST SYSTEM	7	GOOD CONDITION	0

 IMAGES



Ordered by: dharmendra yadav | Inspected date: 2019-03-29

Order Id: 53382

Overall Score  **7/10**



2,68,127

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	GOOD CONDITION	0
FRONT BUMPER	8	GOOD CONDITION	0
HEAD LIGHTS	8	GOOD CONDITION	0
GRILLE	8	GOOD CONDITION	0
TURN SIGNAL	8	GOOD CONDITION	0
FOG LAMPS	8	NOT AVAILABLE	0
HOOD	8	GOOD CONDITION	0
PILLAR	8	GOOD CONDITION	0
FRONT WINDSHIELD	8	GOOD CONDITION	0
SIDE VIEW MIRRORS	8	GOOD CONDITION	0
LH FENDER	8	GOOD CONDITION	0
LH FRONT DOOR	8	GOOD CONDITION	0
LH REAR DOOR	8	GOOD CONDITION	0
LH RUNNING BOARD	8	GOOD CONDITION	0
LH QUARTER PANEL	8	GOOD CONDITION	0
FUEL LID	8	GOOD CONDITION	0
REAR WINDSHIELD	8	GOOD CONDITION	0
REAR BUMPER	8	GOOD CONDITION	0
TAIL LIGHT	8	GOOD CONDITION	0
TRUNK LID/TAIL GATE	8	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	8	GOOD CONDITION	0
RH QUARTER PANEL	8	GOOD CONDITION	0
RH RUNNING BOARD	8	GOOD CONDITION	0
RH REAR DOOR	8	GOOD CONDITION	0

Ordered by: dharmendra yadav | Inspected date: 2019-03-29

Order Id: 53382

Overall Score **7/10**





2,68,127

EXTERIOR (CONTINUED)

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	GOOD CONDITION	0
RH FENDER	8	GOOD CONDITION	0
BODY RUST	8	GOOD CONDITION	0
ROOF (REGULAR)	8	GOOD CONDITION	0
PAINT CONDITION	8	GOOD CONDITION	0

IMAGES



DESCRIPTION

Good condition

Ordered by: dharmendra yadav | Inspected date: 2019-03-29

Order Id: 53382

Overall Score
















7/10



2,68,127

IMAGES



Ordered by: dharmendra yadav | Inspected date: 2019-03-29

Order Id: 53382

Overall Score



7/10



2,68,127

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.